

ASS. REC. BY: Steve

CS/UP/122008523/EV43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 6BL4078M Yr Regn: 9/7/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Duna 150 c.c. 1982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: N/A T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTJAT35Y70K216676

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jaimmed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 30/8/22

Survey held at Borneo

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - \$5K \$86k 1/9/22 steve
	PV - 36,925
	NV - 48,075

Date/Time, File Pass to? : Preli. Report : Final Report

1) Date/Time, File Return to?

2) _____

Report Format: _____
Lump Sum / I.E.S. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + R.S. \$ _____
Photos _____
Others _____
TOTAL _____

Inchcape
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO1	M/S Lim Bs Enterprise Plasterceil	
		Document No. 0	8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252	
		Document Date 01/09/2022	Mobile: 81801016	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DHOM120061172100 ACC DATE:30.08.2022 TOW IN:30.08.2022 EXCESS: DATE-IN:30.08.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT 4 x 100				400 600.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP				122.40
4	S	BP-SUBLET R/I DASHBOARD ASSY TO FAC REPAIR				1440.00
5	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				720.00
6	S	BP-SUBLET REPLACE ROOF LINING				770 1440.00
7	S	BP-SUBLET R/I AC BLOWER SYSTEM TO FAC REPAIR				720.00
8	S	BP-SUBLET R/I WIRE HARNESS ASSY TO FAC REPAIR				720.00
9	S	BP-SUBLET REPLACE FRONT WINDSCREEN GLASS				462.00
10	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR				360.00
11	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST				122.40
12	S	BP-SUBLET R/I CABIN ASSY TO FAC REPAIR 216				2880.00
13	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
14	S	BP-SUBLET REPLACE BRAKE BOOSTER & BRAKE SYSTEM				720.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 ANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016
	Document No. 0	
	Document Date 01/09/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	S	BP-SUBLET REPLACE ACC DAMAGED PARTS <i>10 x 710</i>				8640.00
16	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS <i>5 x 590</i>				5900.00
17	S	BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER -1PC				50.00
18	Z	BP-BKT SUPPLY IU BRACKET				26.00
19	1	T54801-25130 TUBE SUB-ASSY, TILT	1.00	761.40		761.40
20	2	T51701-25110 BRACKET SUB-ASSY	1.00	545.50		545.50
21	3	T52211-37010 SPACER, CAB FR	2.00	63.10		126.20
22	4	T51702-25060 BRACKET SUB-ASSY	1.00	545.50		545.50
23	5	T54915-37230 SPRING, TILT CAB	1.00	404.40		404.40
24	6	T54911-37160 ARM, TILT CAB SPRING	1.00	214.90		214.90
25	7	T75315-37080 ORNAMENT, RADIATOR	1.00	76.20		76.20
26	8	T75311-25100 PLATE, FR NAME, NO.1	1.00	68.70		68.70
27	9	T75362-35090 PLATE, FR FENDER	1.00	54.70		54.70
28	0	T53111-37A01 B1 GRILLE, RADIATOR	1.00	644.30		644.30
29	1	T67771-37040 RETAINER, DOOR TRIM	10.00	6.60		66.00
30	2	T90467-10188 CLIP	4.00	3.00		12.00
31	3	T53115-37080 BRACKET, RADIATOR	1.00	26.90		26.90
32	4	T63111-37120 PANEL, ROOF	1.00	667.80		667.80
33	5	T63132-37074 PANEL, WINDSHIELD	1.00	196.00		196.00
34	6	T63141-37061 REINFORCEMENT, ROOF	1.00	184.20		184.20

7200
2950

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 ANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil	
		Document No.	8 Marsiling Ind Estate Road 3	
		0	#01-12 Marsiling Industrial Estate Singapore 739252	
		Document Date	Mobile: 81801016	
		01/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	7	T61131-37083 PILLAR, FR BODY, (RH) <i>DD</i>	1.00	442.50		442.50
36	8	T61108-37031 REINFORCEMENT <i>DD</i>	1.00	315.80		315.80
37	9	T61023-37041 PILLAR SUB-ASSY, FR <i>DD</i>	1.00	378.90		378.90
38	0	T61455-37010 RETAINER, FR STEP, <i>PPC</i>	1.00	28.20		28.20
39	1	T61245-37010 REINFORCEMENT, ROOF <i>PPC</i>	1.00	39.60		39.60
40	2	T61035-37070 BRACKET SUB-ASSY, <i>PPC</i>	1.00	129.20		129.20
41	3	T61231-37050 RAIL, ROOF SIDE, (RH) <i>DD</i>	1.00	197.90		197.90
42	4	T61611-37142 PANEL, QUARTER, <i>DD</i>	1.00	689.80		689.80
43	5	T61451-37010 PLATE, STEP, LWR RH <i>PPC</i>	1.00	48.00		48.00
44	6	T53827-37010 PROTECTOR, FR FENDER <i>PPC</i>	2.00	48.80		97.60
45	7	T56111-37120 GLASS, WINDSHIELD <i>BR</i>	1.00	1697.40		1697.40
46	8	T56121-25040 WEATHERSTRIP, <i>PPC</i>	1.00	399.40		399.40
47	9	T55078-37110 COVER SUB-ASSY, FR <i>DD (Wip Pcs)</i>	1.00	337.00		337.00
48	0	T55738-37080 PROTECTOR, FR PANEL <i>PPC</i>	1.00	98.70		98.70
49	1	T55735-37021 REINFORCEMENT, COWL <i>DD</i>	1.00	43.10		43.10
50	2	T55736-37021 REINFORCEMENT, COWL X	1.00	43.10		43.10
51	3	T55700-37350 COWL ASSY <i>DD (Part for)</i>	1.00	1291.80		1291.80
52	4	T53821-37100 BRACKET, FR FENDER, <i>DD</i>	1.00	67.50		67.50
53	5	T53813-37170 B0 PANEL, FR SIDE, RH <i>DD</i>	1.00	353.40		353.40
54	6	T55785-37070 PAD, FR PANEL COVER <i>PPC</i>	1.00	0.00		

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 ANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016
	Document No. 0	
	Document Date 01/09/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
55	7	T55301-37090 C0 PANEL SUB-ASSY, <i>CR4</i>	1.00	1090.40		1090.40
56	8	T55429-37020 STAY, INSTRUMENT	1.00	68.20		68.20
57	9	T55429-37010 STAY, INSTRUMENT	1.00	104.10		104.10
58	0	T55330-37210 REINFORCEMENT ASSY,	1.00	678.20		678.20
59	1	T55306-37073 BRACE SUB-ASSY,	1.00	138.00		138.00
60	2	T55472-37010 C0 PANEL, INSTRUMENT	1.00	56.10		56.10
61	3	T55650-37060 B0 REGISTER ASSY,	2.00	125.80		251.60
62	4	T55448-37040 C0 COVER, OIL RESERVOIR TANK, RH	1.00	29.40		29.40
63	5	T55411-37060 C0 PANEL, INSTRUMENT	1.00	375.20		375.20
64	6	T45288-37022 PLATE, STEERING	1.00	56.20		56.20
65	7	T55045-37010 B0 PANEL SUB-ASSY,	1.00	145.20		145.20
66	8	T55539-48030 C0 COVER, SPARE SWITCH	1.00	9.50		9.50
67	9	T55547-20020 B2 COVER, REMOTE	1.00	22.50		22.50
68	0	T55046-37020 B0 PANEL SUB-ASSY,	1.00	231.10		231.10
69	1	T55548-37020 B0 COVER, INSTRUMENT	1.00	65.00		65.00
70	2	T55537-95010 B2 COVER, THROTTLE KNOB	1.00	4.80		4.80
71	3	T90467-07041 P5 CLIP	2.00	3.30		6.60
72	4	T55405-37200 C0 PANEL SUB-ASSY,	1.00	460.90		460.90
73	5	T55650-37060 B0 REGISTER ASSY,	2.00	125.80		251.60
74	6	T55521-37030 COVER, STEREO	2.00	63.10		126.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 ANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil	
		Document No.	8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252	
		Document Date	Mobile: 81801016	
		0		
		01/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
75	7	T55521-37020 C0 COVER, STEREO ?	1.00	84.40		84.40
76	8	T55452-37010 B0 BOX, INSTRUMENT ?	1.00	213.10		213.10
77	9	T55320-37060 B0 PANEL ASSY ?	1.00	288.20		288.20
78	0	T90467-07191 C1 CLIP ?	1.00	2.90		2.90
79	1	T55473-37010 C0 PANEL, INSTRUMENT ?	1.00	56.10		56.10
80	2	T55451-37011 B0 BOX, INSTRUMENT ?	1.00	273.70		273.70
81	3	T58839-37030 B0 COVER, CONSOLE BOX ?	2.00	12.30		24.60
82	4	T74348-37010 B0 HOLDER, VISOR ?	2.00	16.20		32.40
83	5	T55549-37010 B0 COVER, INSTRUMENT ?	1.00	47.20		47.20
84	6	T61184-37090 BRACKET, INSTRUMENT ?	1.00	5.00		5.00
85	7	T55312-37011 B0 PANEL, INSTRUMENT, ?	1.00	302.70		302.70
86	8	T55458-37030 B0 COVER, INSTRUMENT, ?	1.00	73.70		73.70
87	9	T90467-07041 P5 CLIP ?	1.00	3.30		3.30
88	0	T87114-37010 COVER, HEATER ?	1.00	161.10		161.10
89	1	T57408-25470 MEMBER SUB-ASSY, FR ?	1.00	686.50		686.50
90	2	T58251-37032 BRACE, FLOOR PANEL, ?	1.00	197.90		197.90
91	3	T58252-37031 BRACE, FLOOR PANEL, ?	1.00	118.70		118.70
92	4	T58111-37534 PANEL, FR FLOOR ?	1.00	886.20		886.20
93	5	T58295-37060 BRACKET, FLOOR SHIFT ?	1.00	76.90		76.90
94	6	T58236-95J01 BRACKET, CLUTCH TUBE ?	1.00	14.80		14.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 1967000862
 No. : MR-8500000-9
 ANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil	
		Document No.	8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252	
		Document Date	Mobile: 81801016	
		0		
		01/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
95	7	T58335-37080 PLATE, FLOOR SIDE, <i>1</i>	1.00	129.20		129.20
96	8	T58840-37010 COVER ASSY, SHIFTING <i>1</i>	1.00	64.40		64.40
97	9	T51771-25021 PLATE, STEP, RH <i>1</i>	1.00	327.70		327.70
98	0	T53701-37090 APRON SUB-ASSY, FR <i>1</i>	1.00	129.30		129.30
99	1	T57157-37030 REINFORCEMENT, FR <i>1</i>	1.00	56.90		56.90
100	2	T67913-37010 B1 PLATE, FR DOOR <i>1</i>	1.00	234.10		234.10
101	3	T58515-37080 C0 MAT, FR FLOOR, RR <i>1</i>	1.00	17.60		17.60
102	4	T82712-37070 SUPPORT, WIRING <i>1</i>	4.00	64.00		256.00
103	5	T58510-37M02 B1 MAT ASSY, FLOOR, FR <i>1</i>	1.00	1256.50		1256.50
104	6	T58255-37021 B1 COVER, SHIFT LEVER <i>1</i>	1.00	141.10		141.10
105	7	T58839-37010 B1 COVER, CONSOLE BOX <i>1</i>	1.00	100.50		100.50
106	8	T58834-25021 B1 COVER, CONSOLE, LWR <i>1</i>	1.00	304.10		304.10
107	9	T62210-37010 B0 GARNISH ASSY, FR <i>1</i>	1.00	92.40		92.40
108	0	T62530-37020 B0 PANEL ASSY, QUARTER <i>1</i>	1.00	111.30		111.30
109	1	T62313-37080 B0 TRIM, FR DOOR <i>1</i>	1.00	117.80		117.80
110	2	T90467-10162 CLIP <i>10</i>	10.00	3.10		31.00
111	3	T90467-10188 CLIP <i>10</i>	10.00	3.00		30.00
112	4	T63310-37611 B0 HEADLINING ASSY, <i>CR4</i>	1.00	1935.30		1935.30
113	5	T90467-06048 B9 CLIP <i>10</i>	10.00	3.00		30.00
114	6	T67610-37090 B6 PANEL ASSY, FR DOOR <i>DD (Trim)</i>	1.00	531.70		531.70

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

No. : 196700086Z
 9 No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No. 0		
		Document Date 01/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
115	7	T74141-25010 B1 GARNISH, FR ASH	1.00	46.90		46.90
116	8	T90467-07071 P4 CLIP	2.00	2.60		5.20
117	9	T74630-37020 C0 GRIP ASSY, DOOR	1.00	158.20		158.20
118	0	T74811-95J04 B3 HANDLE, DOOR PULL	2.00	19.30		38.60
119	1	T74610-37040 B0 GRIP ASSY, ASSIST	1.00	71.30		71.30
120	2	T74611-48010 B0 GRIP, ASSIST	1.00	46.90		46.90
121	3	T74348-22020 B9 HOLDER, VISOR	2.00	19.90		39.80
122	4	T74231-37012 B1 PANEL, FR DOOR	1.00	35.00		35.00
123	5	T74231-37020 B1 PANEL, FR DOOR	1.00	33.00		33.00
124	6	T67001-25051 PANEL SUB-ASSY, FR	1.00	1941.80		1941.80
125	7	T67861-37021 WEATHERSTRIP, FR	1.00	221.40		221.40
126	8	T67863-37011 WEATHERSTRIP, FR	1.00	110.40		110.40
127	9	T67831-37020 COVER, FR DOOR	1.00	44.90		44.90
128	0	T53866-37042 SEAL, FR FENDER TO	1.00	50.50		50.50
129	1	T68610-37030 CHECK ASSY, FR DOOR	2.00	198.60		397.20
130	2	T68161-37011 WEATHERSTRIP, FR	1.00	123.20		123.20
131	3	T67495-37010 COVER, FR DOOR FR	1.00	60.00		60.00
132	4	T68141-37030 RUN, FR DOOR GLASS,	1.00	263.40		263.40
133	5	T68101-37100 GLASS SUB-ASSY, FR	1.00	805.10		805.10
134	6	T67403-37021 FRAME SUB-ASSY, FR	1.00	0.00		

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 HAN DAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc		S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016	
		Document No. 0		
		Document Date 01/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
135	7	T90541-09031 CUSHION	4.00	10.80		43.20
136	8	T68618-37020 BRACKET, FR DOOR	2.00	16.50		33.00
137	9	T69210-37020 HANDLE ASSY, FR	1.00	221.00		221.00
138	0	T69205-37010 B1 HANDLE SUB-ASSY, FR	1.00	53.20		53.20
139	1	T69310-37080 LOCK ASSY, FR DOOR	1.00	341.40		341.40
140	2	T69711-37010 LINK, FR DOOR LOCK	1.00	21.70		21.70
141	3	T69749-12070 CLAMP, DOOR LOCK	2.00	3.20		6.40
142	4	T69410-20110 PLATE ASSY, DOOR	2.00	42.60		85.20
143	5	T68710-37020 HINGE ASSY, FR DOOR	1.00	119.20		119.20
144	6	T68730-37010 HINGE ASSY, FR DOOR	1.00	119.20		119.20
145	7	T69801-37052 REGULATOR SUB-ASSY	1.00	384.50		384.50
146	8	T69801-37063 REGULATOR SUB-ASSY	1.00	385.10		385.10
147	9	T85710-37090 MOTOR ASSY, POWER	1.00	765.50		765.50
148	0	T71811-37022 B1 COVER, RECLINING	1.00	72.40		72.40
149	1	T72110-37020 TRACK ASSY, FR SEAT	1.00	359.00		359.00
150	2	T72130-37020 TRACK ASSY, FR SEAT	1.00	536.50		536.50
151	3	T81110-37660 HEADLAMP ASSY, RH	1.00	1272.30		1272.30
152	4	T81150-37660 HEADLAMP ASSY, LH	1.00	1272.30		1272.30
153	5	T85212-37081 BLADE, FR WIPER, RH	1.00	91.90		91.90
154	6	T85222-37141 BLADE, FR WIPER, LH	1.00	91.90		91.90

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 G No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016
	Document No. 0	
	Document Date 01/09/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
155	7	T87810-37091 C0 MIRROR ASSY, INNER <i>supp ?</i>	1.00	136.10		136.10
156	8	T87819-25010 LENS, INNER RR VIEW <i>supp ?</i>	1.00	15.40		15.40
157	9	T87910-25040 MIRROR ASSY, OUTER <i>supp ?</i>	1.00	352.70		352.70
158	0	T87965-37030 GROMMET, OUTER <i>supp ?</i>	1.00	37.20		37.20
159	1	T87010-37230 UNIT ASSY, AIR <i>supp ?</i>	1.00	2895.60		2895.60
160	2	T87210-37100 CASE ASSY, AIR <i>supp ?</i>	1.00	365.40		365.40
161	3	T55900-37560 CONTROL & ACCESSORY <i>supp ?</i>	1.00	954.80		954.80
162	4	T55843-37140 DUCT, HEATER TO <i>supp ?</i>	1.00	100.50		100.50
163	5	T55845-37060 DUCT, HEATER TO <i>supp ?</i>	1.00	148.80		148.80
164	6	T55844-37060 DUCT, HEATER TO <i>supp ?</i>	1.00	100.50		100.50
165	7	T55950-37100 NOZZLE ASSY, <i>supp ?</i>	1.00	165.50		165.50
166	8	T55972-37070 DUCT, SIDE DEFROSTER <i>supp ?</i>	1.00	45.00		45.00
167	9	T55967-37080 NOZZLE, DEFROSTER, <i>supp ?</i>	1.00	92.50		92.50
168	0	T55870-37010 DUCT ASSY, HEATER TO <i>supp ?</i>	1.00	77.40		77.40
169	1	T17700-30241 CLEANER ASSY, AIR <i>supp ?</i>	1.00	844.90		844.90
170	2	T17940-30110 INTERCOOLER ASSY <i>supp ?</i>	1.00	2599.50		2599.50
171	3	T55150-37320 BRACKET ASSY, PEDAL <i>supp ?</i>	1.00	312.70		312.70
172	4	T47101-37131 PEDAL SUB-ASSY, <i>supp ?</i>	1.00	135.10		135.10
173	5	T44610-25350 BOOSTER ASSY, BRAKE <i>supp ?</i>	1.00	1704.20		1704.20
174	6	T44704-25160 RESERVOIR SUB-ASSY, <i>supp ?</i>	1.00	252.80		252.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUO11	M/S Lim Bs Enterprise Plasterceil 8 Marsiling Ind Estate Road 3 #01-12 Marsiling Industrial Estate Singapore 739252 Mobile: 81801016
	Document No. 0	
	Document Date 01/09/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	KDY231R	TLMKY S5	09/07/2021	GBL4078M	0	17266	GBL4078M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFAT35Y70K216676	1KDB090552	60	Thomas Pang W T	--/------	0.00	--/------	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
175	7	T47220-37120 RESERVOIR ASSY, ?	1.00	227.20		227.20
176	8	T44778-25050 HOSE, CONNECTOR TO ?	1.00	70.40		70.40
177	9	T08889-01203 COOLANT, SLLC (BLUE) ?	2.00	138.00		276.00

*Stere (LKK)
1/9/22, 11.00am*

*00-M ML
EXCESS-?
PIP
My Bal by
20 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts must be subject to confirmation
- Third party survey is on a "Bill of Materials" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer
Signature: _____

Customer's Signature
Please acknowledge receipt of vehicle
Signature: _____

Charge Summary		Total	72,791.40
Parts	47,588.60	GST 7.00%	5,095.40
Labour	126.00	Less	0.00
Sublet	25,076.80	Amount Due	77,886.80
Lubrication/Fluid	0.00		
Others	0.00		

Customer Copy