

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no: 6631 1188

## ESTIMATE

| Account Details   |         |   | Account No.                           |                 | Customer Details   |         |                      |
|---|---------|---|---------------------------------------|-----------------|--|---------|----------------------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |   | S1000019 / ICUO11                     |                 | M/S Lim Bs Enterprise Plasterceil<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |         |                      |
|   |         |   | Document No.<br>0                     |                 |  |         |                      |
|   |         |   | Document Date<br>01/09/2022           |                 |  |         |                      |
| Year  | Model   | Variant   | Reg. Date                             | Reg. No.        | Kilometers   | Wip No. | Order No. / Remarks  |
| 2021  | KDY231R | TLMKY S5  | 09/07/2021                            | GBL4078M        | 0  | 17266   | GBL4078M             |
| Chassis No.   |         | Engine No.  | Terms                                 | SA / Counter    | Vehicle In   |         | Collected On         |
| JTFAT35Y70K216676   |         | 1KDB090552  | 60                                    | Thomas Pang W T | --/--/----   |         | 0.00 --/--/---- 0.00 |
| L   | Cd      | Job/Parts Description   | Qty                                   | Unit Price      | Disc %   | Amount  |                      |
| 1   | Z       | BP-SUNDRY SUNDRIES<br>POLICY NO.:DHOM120061172100 ACC DATE:30.08.2022<br>TOW IN:30.08.2022 EXCESS:<br>DATE-IN:30.08.2022 DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORIZED ON: |                                       |                 |  | 50      | 100.00               |
| 2   | S       | BP-SUBLET SUPPLY JOINT PANEL SEALANT 4 x 100 nec  |                                       |                 |  | 400     | 600.00<br>122.40     |
| 3   | S       | BP-SUBLET REPLACE AND REFOCUS HEADLAMP  |                                       |                 |  |         | 1440.00              |
| 4   | S       | BP-SUBLET R/I DASHBOARD ASSY TO FAC REPAIR  |                                       |                 |  |         | 720.00               |
| 5   | S       | BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR  |                                       |                 |  | 770     | 1440.00              |
| 6   | S       | BP-SUBLET REPLACE ROOF LINING   |                                       |                 |  |         | 720.00               |
| 7   | S       | BP-SUBLET R/I AC BLOWER SYSTEM TO FAC REPAIR  |                                       |                 |  |         | 720.00               |
| 8   | S       | BP-SUBLET R/I WIRE HARNESS ASSY TO FAC REPAIR   |                                       |                 |  |         | 462.00               |
| 9   | S       | BP-SUBLET REPLACE FRONT WINDSCREEN GLASS  |                                       |                 |  |         | 360.00               |
| 10  | S       | BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENTS<br>ONTO NEW DOOR  |                                       |                 |  |         | 122.40               |
| 11  | S       | BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST   |                                       |                 |  | 2160    | 2880.00              |
| 12  | S       | BP-SUBLET R/I CABIN ASSY TO FAC REPAIR  |                                       |                 |  |         | 180.00               |
| 13  | S       | BP-SUBLET TO RESET ECU AND REPROGRAMME  |                                       |                 |  |         | 720.00               |
| 14  | S       | BP-SUBLET REPLACE BRAKE BOOSTER & BRAKE SYSTEM  |                                       |                 |  |         |                      |
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd                                   |         |   | Customer's Signature                  |                 | Charge Summary   |         | Total                |
|   |         |   | Please acknowledge receipt of vehicle |                 | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others   |         | Less                 |
|   |         |   |                                       |                 |  |         | Amount Due           |

Customer Copy

chcape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details   |         |   | Account No.                           |                 | Customer Details   |         |                      |
|---|---------|---|---------------------------------------|-----------------|--|---------|----------------------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |   | S1000019 / ICUO11                     |                 | M/S Lim Bs Enterprise Plasterceil<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |         |                      |
|   |         |   | Document No.                          |                 |  |         |                      |
|   |         |   | 0                                     |                 |  |         |                      |
|   |         |   | Document Date                         |                 |  |         |                      |
|   |         |   | 01/09/2022                            |                 |  |         |                      |
| Year  | Model   | Variant   | Reg. Date                             | Reg. No.        | Kilometers   | Wip No. | Order No. / Remarks  |
| 2021  | KDY231R | TLMKY S5  | 09/07/2021                            | GBL4078M        | 0  | 17266   | GBL4078M             |
| Chassis No.   |         | Engine No.  | Terms                                 | SA / Counter    | Vehicle In   |         | Collected On         |
| JTFAT35Y70K216676   |         | 1KDB090552  | 60                                    | Thomas Pang W T | --/--/----   |         | 0.00 --/--/---- 0.00 |
| L   | Cd      | Job/Parts Description                                   | Qty                                   | Unit Price      | Disc %   | Amount  |                      |
| 15  | S       | BP-SUBLET REPLACE ACC DAMAGED PARTS <sup>10 x 710</sup> |                                       |                 |  | 7700    | 8640.00              |
| 16  | S       | BP-SUBLET RESPRAY ACC AFFECTED AREAS <sup>5 x 590</sup> |                                       |                 |  | 2950    | 5900.00              |
| 17  | S       | BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER -1PC        |                                       |                 |  |         | 50.00                |
| 18  | Z       | BP-BKT SUPPLY IU BRACKET                                |                                       |                 |  |         | 26.00                |
| 19  | 1       | T54801-25130 TUBE SUB-ASSY, TILT <sup>1 x 710</sup>     | 1.00                                  | 761.40          |  |         | 761.40               |
| 20  | 2       | T51701-25110 BRACKET SUB-ASSY <sup>1 x 710</sup>        | 1.00                                  | 545.50          |  |         | 545.50               |
| 21  | 3       | T52211-37010 SPACER, CAB FR <sup>2 x 710</sup>          | 2.00                                  | 63.10           |  |         | 126.20               |
| 22  | 4       | T51702-25060 BRACKET SUB-ASSY <sup>1 x 710</sup>        | 1.00                                  | 545.50          |  |         | 545.50               |
| 23  | 5       | T54915-37230 SPRING, TILT CAB <sup>1 x 710</sup>        | 1.00                                  | 404.40          |  |         | 404.40               |
| 24  | 6       | T54911-37160 ARM, TILT CAB SPRING <sup>1 x 710</sup>    | 1.00                                  | 214.90          |  |         | 214.90               |
| 25  | 7       | T75315-37080 ORNAMENT, RADIATOR <sup>1 x 710</sup>      | 1.00                                  | 76.20           |  |         | 76.20                |
| 26  | 8       | T75311-25100 PLATE, FR NAME, NO.1 <sup>1 x 710</sup>    | 1.00                                  | 68.70           |  |         | 68.70                |
| 27  | 9       | T75362-35090 PLATE, FR FENDER <sup>1 x 710</sup>        | 1.00                                  | 54.70           |  |         | 54.70                |
| 28  | 0       | T53111-37A01 B1 GRILLE, RADIATOR <sup>1 x 710</sup>     | 1.00                                  | 644.30          |  |         | 644.30               |
| 29  | 1       | T67771-37040 RETAINER, DOOR TRIM <sup>1 x 710</sup>     | 10.00                                 | 6.60            |  |         | 66.00                |
| 30  | 2       | T90467-10188 CLIP <sup>1 x 710</sup>                    | 2.00                                  | 3.00            |  | 6.00    | 12.00                |
| 31  | 3       | T53115-37080 BRACKET, RADIATOR <sup>1 x 710</sup>       | 1.00                                  | 26.90           |  |         | 26.90                |
| 32  | 4       | T63111-37120 PANEL, ROOF <sup>1 x 710</sup>             | 1.00                                  | 667.80          |  |         | 667.80               |
| 33  | 5       | T63132-37074 PANEL, WINDSHIELD <sup>1 x 710</sup>       | 1.00                                  | 196.00          |  |         | 196.00               |
| 34  | 6       | T63141-37061 REINFORCEMENT, ROOF <sup>1 x 710</sup>     | 1.00                                  | 184.20          |  |         | 184.20               |
| For & on behalf of  |         |   | Customer's Signature                  |                 | Charge Summary   |         | Total                |
| Borneo Motors (Singapore) Pte Ltd   |         |   |                                       |                 |  |         |                      |
|   |         |   | Please acknowledge receipt of vehicle |                 | Parts  |         | Less                 |
|   |         |   |                                       |                 | Labour   |         |                      |
|   |         |   |                                       |                 | Sublet   |         |                      |
|   |         |   |                                       |                 | Lubrication/Fluid  |         |                      |
|   |         |   |                                       |                 | Others   |         |                      |
|   |         |   |                                       |                 | Amount Due   |         |                      |

Customer Copy

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no: 6631 1188

## ESTIMATE

| Account Details   |         |  | Account No.                           |                 | Customer Details   |         |                      |        |         |
|---|---------|--|---------------------------------------|-----------------|--|---------|----------------------|--------|---------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |  | S1000019 / ICUO11                     |                 | M/S Lim Bs Enterprise Plasterceil<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252 |         |                      |        |         |
|   |         |  | Document No.<br>0                     |                 | Mobile: 81801016   |         |                      |        |         |
|   |         |  | Document Date<br>01/09/2022           |                 |  |         |                      |        |         |
| Year  | Model   | Variant                                      | Reg. Date                             | Reg. No.        | Kilometers   | Wip No. | Order No. / Remarks  |        |         |
| 2021  | KDY231R | TLMKY S5                                     | 09/07/2021                            | GBL4078M        | 0  | 17266   | GBL4078M             |        |         |
| Chassis No.   |         | Engine No.                                   | Terms                                 | SA / Counter    | Vehicle In   |         | Collected On         |        |         |
| JTFAT35Y70K216676   |         | 1KDB090552                                   | 60                                    | Thomas Pang W T | --/--/----   |         | 0.00 --/--/---- 0.00 |        |         |
| L   | Cd      | Job/Parts Description                        |                                       |                 |  | Qty     | Unit Price           | Disc % | Amount  |
| 35  | 7       | T61131-37083 PILLAR, FR BODY, (RH) <i>DD</i> |                                       |                 |  | 1.00    | 442.50               |        | 442.50  |
| 36  | 8       | T61108-37031 REINFORCEMENT <i>DD</i>         |                                       |                 |  | 1.00    | 315.80               |        | 315.80  |
| 37  | 9       | T61023-37041 PILLAR SUB-ASSY, FR <i>DD</i>   |                                       |                 |  | 1.00    | 378.90               |        | 378.90  |
| 38  | 0       | T61455-37010 RETAINER, FR STEP, <i>DD</i>    |                                       |                 |  | 1.00    | 28.20                |        | 28.20   |
| 39  | 1       | T61245-37010 REINFORCEMENT, ROOF <i>DD</i>   |                                       |                 |  | 1.00    | 39.60                |        | 39.60   |
| 40  | 2       | T61035-37070 BRACKET SUB-ASSY, <i>DD</i>     |                                       |                 |  | 1.00    | 129.20               |        | 129.20  |
| 41  | 3       | T61231-37050 RAIL, ROOF SIDE, (RH) <i>DD</i> |                                       |                 |  | 1.00    | 197.90               |        | 197.90  |
| 42  | 4       | T61611-37142 PANEL, QUARTER, <i>DD</i>       |                                       |                 |  | 1.00    | 689.80               |        | 689.80  |
| 43  | 5       | T61451-37010 PLATE, STEP, LWR RH <i>DD</i>   |                                       |                 |  | 1.00    | 48.00                |        | 48.00   |
| 44  | 6       | T53827-37010 PROTECTOR, FR FENDER <i>DD</i>  |                                       |                 |  | 2.00    | 48.80                |        | 97.60   |
| 45  | 7       | T53827-37010 GLASS, WINDSHIELD <i>DD</i>     |                                       |                 |  | 1.00    | 1697.40              |        | 1697.40 |
| 46  | 8       | T56121-25040 WEATHERSTRIP, <i>DD</i>         |                                       |                 |  | 1.00    | 399.40               |        | 399.40  |
| 47  | 9       | T55078-37110 COVER SUB-ASSY, FR <i>DD</i>    |                                       |                 |  | 1.00    | 337.00               |        | 337.00  |
| 48  | 0       | T55738-37080 PROTECTOR, FR PANEL <i>DD</i>   |                                       |                 |  | 1.00    | 98.70                |        | 98.70   |
| 49  | 1       | T55735-37021 REINFORCEMENT, COWL <i>DD</i>   |                                       |                 |  | 1.00    | 43.10                |        | 43.10   |
| 50  | 2       | T55736-37021 REINFORCEMENT, COWL <i>DD</i>   |                                       |                 |  | 1.00    | 43.10                |        | 43.10   |
| 51  | 3       | T55700-37350 COWL ASSY <i>DD</i>             |                                       |                 |  | 1.00    | 1291.80              |        | 1291.80 |
| 52  | 4       | T53821-37100 BRACKET, FR FENDER, <i>DD</i>   |                                       |                 |  | 1.00    | 67.50                |        | 67.50   |
| 53  | 5       | T53813-37170 BO PANEL, FR SIDE, RH <i>DD</i> |                                       |                 |  | 1.00    | 353.40               |        | 353.40  |
| 54  | 6       | T55785-37070 PAD, FR PANEL COVER <i>DD</i>   |                                       |                 |  | 1.00    | 3.00                 |        | 3.00    |
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd                                   |         |  | Customer's Signature                  |                 | Charge Summary   |         | Total                |        |         |
|   |         |  | Please acknowledge receipt of vehicle |                 | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others   |         | Less                 |        |         |
|   |         |  |                                       |                 |  |         | Amount Due           |        |         |

Customer Copy

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no. : 6631 1188

**ESTIMATE**

| Account Details   |  | Account No.                 | Customer Details   |  |
|---|--|-----------------------------|--|--|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |  | S1000019 / ICUO11           | M/S Lim Bs Enterprise Plastercell<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |  |
|   |  | Document No.<br>0           |  |  |
|   |  | Document Date<br>01/09/2022 |  |  |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2021              | KDY231R    | TLMKY S5 | 09/07/2021      | GBL4078M   | 0            | 17266      | GBL4078M            |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JTFAT35Y70K216676 | 1KDB090552 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L  | Cd | Job/Parts Description                                     | Qty  | Unit Price | Disc % | Amount  |
|----|----|---|------|------------|--------|---------|
| 55 | 7  | T55301-37090 C0 PANEL SUB-ASSY, <i>CR4</i>                | 1.00 | 1090.40    |        | 1090.40 |
| 56 | 8  | T55429-37020 STAY, INSTRUMENT <i>x no</i>                 | 1.00 | 68.20      |        | 68.20   |
| 57 | 9  | T55429-37010 STAY, INSTRUMENT <i>x no</i>                 | 1.00 | 104.10     |        | 104.10  |
| 58 | 0  | T55330-37210 REINFORCEMENT ASSY, <i>BT</i>                | 1.00 | 678.20     |        | 678.20  |
| 59 | 1  | T55306-37073 BRACE SUB-ASSY, <i>x no</i>                  | 1.00 | 138.00     |        | 138.00  |
| 60 | 2  | T55472-37010 C0 PANEL, INSTRUMENT <i>x no</i>             | 1.00 | 56.10      |        | 56.10   |
| 61 | 3  | T55650-37060 B0 REGISTER ASSY, <i>x no</i>                | 2.00 | 125.80     |        | 251.60  |
| 62 | 4  | T55448-37040 C0 COVER, OIL RESERVOIR TANK, RH <i>x no</i> | 1.00 | 29.40      |        | 29.40   |
| 63 | 5  | T55411-37060 C0 PANEL, INSTRUMENT <i>x no</i>             | 1.00 | 375.20     |        | 375.20  |
| 64 | 6  | T45288-37022 PLATE, STEERING <i>x no</i>                  | 1.00 | 56.20      |        | 56.20   |
| 65 | 7  | T55045-37010 B0 PANEL SUB-ASSY, <i>x no</i>               | 1.00 | 145.20     |        | 145.20  |
| 66 | 8  | T55539-48030 C0 COVER, SPARE SWITCH <i>x no</i>           | 1.00 | 9.50       |        | 9.50    |
| 67 | 9  | T55547-20020 B2 COVER, REMOTE <i>x no</i>                 | 1.00 | 22.50      |        | 22.50   |
| 68 | 0  | T55046-37020 B0 PANEL SUB-ASSY, <i>x no</i>               | 1.00 | 231.10     |        | 231.10  |
| 69 | 1  | T55548-37020 B0 COVER, INSTRUMENT <i>x no</i>             | 1.00 | 65.00      |        | 65.00   |
| 70 | 2  | T55537-95010 B2 COVER, THROTTLE KNOB <i>x no</i>          | 1.00 | 4.80       |        | 4.80    |
| 71 | 3  | T90467-07041 P5 CLIP <i>no</i>                            | 2.00 | 3.30       |        | 6.60    |
| 72 | 4  | T55405-37200 C0 PANEL SUB-ASSY, <i>x no</i>               | 1.00 | 460.90     |        | 460.90  |
| 73 | 5  | T55650-37060 B0 REGISTER ASSY, <i>x no</i>                | 2.00 | 125.80     |        | 251.60  |
| 74 | 6  | T55521-37030 COVER, STEREO <i>x no</i>                    | 2.00 | 63.10      |        | 126.20  |

|   |                                       |  |            |
|---|---------------------------------------|--|------------|
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary   | Total      |
|   | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|   |                                       |  | Amount Due |

Customer Copy



Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no : 6631 1188

**ESTIMATE**

| Account Details   |         |  | Account No.                           |                 | Customer Details   |            |                      |        |
|---|---------|--|---------------------------------------|-----------------|--|------------|----------------------|--------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |  | S1000019 / ICUO11                     |                 | M/S Lim Bs Enterprise Plasterceil<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |            |                      |        |
|   |         |  | Document No.                          |                 |  |            |                      |        |
|   |         |  | 0                                     |                 |  |            |                      |        |
|   |         |  | Document Date                         |                 |  |            |                      |        |
|   |         |  | 01/09/2022                            |                 |  |            |                      |        |
| Year  | Model   | Variant  | Reg. Date                             | Reg. No.        | Kilometers   | Wip No.    | Order No. / Remarks  |        |
| 2021  | KDY231R | TLMKY S5   | 09/07/2021                            | GBL4078M        | 0  | 17266      | GBL4078M             |        |
| Chassis No.   |         | Engine No.                                       | Terms                                 | SA / Counter    | Vehicle In   |            | Collected On         |        |
| JTFAT35Y70K216676   |         | 1KDB090552                                       | 60                                    | Thomas Pang W T | --/--/----   |            | 0.00 --/--/---- 0.00 |        |
| L   | Cd      | Job/Parts Description                            |                                       |                 | Qty  | Unit Price | Disc %               | Amount |
| 75  | 7       | T55521-37020 C0 COVER, STEREO <i>1 x nn</i>      |                                       |                 | 1.00   | 84.40      |                      | 84.40  |
| 76  | 8       | T55452-37010 B0 BOX, INSTRUMENT <i>1 x nn</i>    |                                       |                 | 1.00   | 213.10     |                      | 213.10 |
| 77  | 9       | T55320-37060 B0 PANEL ASSY <i>1 x nn</i>         |                                       |                 | 1.00   | 288.20     |                      | 288.20 |
| 78  | 0       | T90467-07191 C1 CLIP <i>1 x nn</i>               |                                       |                 | 1.00   | 2.90       |                      | 2.90   |
| 79  | 1       | T55473-37010 C0 PANEL, INSTRUMENT <i>1 x nn</i>  |                                       |                 | 1.00   | 56.10      |                      | 56.10  |
| 80  | 2       | T55451-37011 B0 BOX, INSTRUMENT <i>1 x nn</i>    |                                       |                 | 1.00   | 273.70     |                      | 273.70 |
| 81  | 3       | T58839-37030 B0 COVER, CONSOLE BOX <i>1 x nn</i> |                                       |                 | 2.00   | 12.30      |                      | 24.60  |
| 82  | 4       | T74348-37010 B0 HOLDER, VISOR <i>1 x nn</i>      |                                       |                 | 2.00   | 16.20      |                      | 32.40  |
| 83  | 5       | T55549-37010 B0 COVER, INSTRUMENT <i>1 x nn</i>  |                                       |                 | 1.00   | 47.20      |                      | 47.20  |
| 84  | 6       | T61184-37090 BRACKET, INSTRUMENT <i>1 x nn</i>   |                                       |                 | 1.00   | 5.00       |                      | 5.00   |
| 85  | 7       | T55312-37011 B0 PANEL, INSTRUMENT <i>1 x nn</i>  |                                       |                 | 1.00   | 302.70     |                      | 302.70 |
| 86  | 8       | T55458-37030 B0 COVER, INSTRUMENT <i>1 x nn</i>  |                                       |                 | 1.00   | 73.70      |                      | 73.70  |
| 87  | 9       | T90467-07041 P5 CLIP <i>1 x nn</i>               |                                       |                 | 1.00   | 3.30       |                      | 3.30   |
| 88  | 0       | T87114-37010 COVER, HEATER <i>1 x nn</i>         |                                       |                 | 1.00   | 161.10     |                      | 161.10 |
| 89  | 1       | T57408-25470 MEMBER SUB-ASSY, FR <i>1 x nn</i>   |                                       |                 | 1.00   | 686.50     |                      | 686.50 |
| 90  | 2       | T58251-37032 BRACE, FLOOR PANEL, <i>1 x nn</i>   |                                       |                 | 1.00   | 197.90     |                      | 197.90 |
| 91  | 3       | T58252-37031 BRACE, FLOOR PANEL, <i>1 x nn</i>   |                                       |                 | 1.00   | 118.70     |                      | 118.70 |
| 92  | 4       | T58111-37534 PANEL, FR FLOOR <i>1 x nn</i>       |                                       |                 | 1.00   | 886.20     |                      | 886.20 |
| 93  | 5       | T58295-37060 BRACKET, FLOOR SHIFT <i>1 x nn</i>  |                                       |                 | 1.00   | 76.90      |                      | 76.90  |
| 94  | 6       | T58236-95J01 BRACKET, CLUTCH TUBE <i>1 x nn</i>  |                                       |                 | 1.00   | 14.80      |                      | 14.80  |
| For & on behalf of  |         |  | Customer's Signature                  |                 | Charge Summary   |            | Total                |        |
| Borneo Motors (Singapore) Pte Ltd   |         |  |                                       |                 |  |            |                      |        |
|   |         |  | Please acknowledge receipt of vehicle |                 | Parts  |            | Less                 |        |
|   |         |  |                                       |                 | Labour   |            |                      |        |
|   |         |  |                                       |                 | Sublet   |            |                      |        |
|   |         |  |                                       |                 | Lubrication/Fluid  |            |                      |        |
|   |         |  |                                       |                 | Others   |            | Amount Due           |        |

Customer Copy



Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no. : 6631 1188

## ESTIMATE

| Account Details   |         |                                       | Account No.          |                   | Customer Details                                       |            |                      |        |        |
|---|---------|---------------------------------------|----------------------|-------------------|--|------------|----------------------|--------|--------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |                                       | S1000019 / ICUO11    |                   | M/S Lim Bs Enterprise Plastercell                      |            |                      |        |        |
|   |         |                                       | Document No.         |                   | 8 Marsiling Ind Estate Road 3                          |            |                      |        |        |
|   |         |                                       | 0                    |                   | #01-12 Marsiling Industrial Estate<br>Singapore 739252 |            |                      |        |        |
|   |         |                                       | Document Date        |                   | Mobile: 81801016                                       |            |                      |        |        |
|   |         | 01/09/2022                            |                      |                   |  |            |                      |        |        |
| Year  | Model   | Variant                               | Reg. Date            | Reg. No.          | Kilometers   | Wip No.    | Order No. / Remarks  |        |        |
| 2021  | KDY231R | TLMKY S5                              | 09/07/2021           | GBL4078M          | 0  | 17266      | GBL4078M             |        |        |
| Chassis No.   |         | Engine No.                            | Terms                | SA / Counter      | Vehicle In   |            | Collected On         |        |        |
| JTFAT35Y70K216676   |         | 1KDB090552                            | 60                   | Thomas Pang W T   | --/--/----   |            | 0.00 --/--/---- 0.00 |        |        |
| L   | Cd      | Job/Parts Description                 |                      |                   |  | Qty        | Unit Price           | Disc % | Amount |
| 95  | 7       | T58335-37080                          | PLATE, FLOOR SIDE,   | 1.00              | 129.20   |            | 129.20               |        |        |
| 96  | 8       | T58840-37010                          | COVER ASSY, SHIFTING | 1.00              | 64.40  |            | 64.40                |        |        |
| 97  | 9       | T51771-25021                          | PLATE, STEP, RH      | 1.00              | 327.70   |            | 327.70               |        |        |
| 98  | 0       | T53701-37090                          | APRON SUB-ASSY, FR   | 1.00              | 129.30   |            | 129.30               |        |        |
| 99  | 1       | T57157-37030                          | REINFORCEMENT, FR    | 1.00              | 56.90  |            | 56.90                |        |        |
| 100   | 2       | T67913-37010 B1                       | PLATE, FR DOOR       | 1.00              | 234.10   |            | 234.10               |        |        |
| 101   | 3       | T58515-37080 C0                       | MAT, FR FLOOR, RR    | 1.00              | 17.60  |            | 17.60                |        |        |
| 102   | 4       | T82712-37070                          | SUPPORT, WIRING      | 4.00              | 64.00  |            | 256.00               |        |        |
| 103   | 5       | T58510-37M02 B1                       | MAT ASSY, FLOOR, FR  | 1.00              | 1256.50  |            | 1256.50              |        |        |
| 104   | 6       | T58255-37021 B1                       | COVER, SHIFT LEVER   | 1.00              | 141.10   |            | 141.10               |        |        |
| 105   | 7       | T58839-37010 B1                       | COVER, CONSOLE BOX   | 1.00              | 100.50   |            | 100.50               |        |        |
| 106   | 8       | T58834-25021 B1                       | COVER, CONSOLE, LWR  | 1.00              | 304.10   |            | 304.10               |        |        |
| 107   | 9       | T62210-37010 B0                       | GARNISH ASSY, FR     | 1.00              | 92.40  |            | 92.40                |        |        |
| 108   | 0       | T62530-37020 B0                       | PANEL ASSY, QUARTER  | 1.00              | 111.30   |            | 111.30               |        |        |
| 109   | 1       | T62313-37080 B0                       | TRIM, FR DOOR        | 1.00              | 117.80   |            | 117.80               |        |        |
| 110   | 2       | T90467-10162                          | CLIP                 | 10.00             | 3.10   |            | 31.00                |        |        |
| 111   | 3       | T90467-10188                          | CLIP                 | 10.00             | 3.00   |            | 30.00                |        |        |
| 112   | 4       | T63310-37611 B0                       | HEADLINING ASSY,     | 1.00              | 1935.30  |            | 1935.30              |        |        |
| 113   | 5       | T90467-06048 B9                       | CLIP                 | 10.00             | 3.00   |            | 30.00                |        |        |
| 114   | 6       | T67610-37090 B6                       | PANEL ASSY, FR DOOR  | 1.00              | 531.70   |            | 531.70               |        |        |
| For & on behalf of  |         | Customer's Signature                  |                      | Charge Summary    |  | Total      |                      |        |        |
| Borneo Motors (Singapore) Pte Ltd   |         |                                       |                      |                   |  |            |                      |        |        |
|   |         | Please acknowledge receipt of vehicle |                      | Parts             |  | Less       |                      |        |        |
|   |         |                                       |                      | Labour            |  |            |                      |        |        |
|   |         |                                       |                      | Sublet            |  |            |                      |        |        |
|   |         |                                       |                      | Lubrication/Fluid |  |            |                      |        |        |
|   |         |                                       |                      | Others            |  | Amount Due |                      |        |        |

Customer Copy

inchcape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

**ESTIMATE**

| Account Details   |         |  | Account No.       |                 | Customer Details   |            |                     |         |
|---|---------|--|-------------------|-----------------|--|------------|---------------------|---------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |         |  | S1000019 / ICUO11 |                 | M/S Lim Bs Enterprise Plasterceil<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |            |                     |         |
|   |         |  | Document No.      |                 |  |            |                     |         |
|   |         |  | 0                 |                 |  |            |                     |         |
|   |         |  | Document Date     |                 |  |            |                     |         |
|   |         |  | 01/09/2022        |                 |  |            |                     |         |
| Year  | Model   | Variant  | Reg. Date         | Reg. No.        | Kilometers   | Wip No.    | Order No. / Remarks |         |
| 2021  | KDY231R | TLMKY S5   | 09/07/2021        | GBL4078M        | 0  | 17266      | GBL4078M            |         |
| Chassis No.   |         | Engine No.   | Terms             | SA / Counter    | Vehicle In   |            | Collected On        |         |
| JTFAT35Y70K216676   |         | 1KDB090552   | 60                | Thomas Pang W T | ---/---/--- 0.00   |            | ---/---/--- 0.00    |         |
| L   | Cd      | Job/Parts Description                                |                   |                 | Qty  | Unit Price | Disc %              | Amount  |
| 115   | 7       | T74141-25010 B1 GARNISH, FR ASH <i>CRU x nn</i>      |                   |                 | 1.00   | 46.90      |                     | 46.90   |
| 116   | 8       | T90467-07071 P4 CLIP <i>CRU x nn</i>                 |                   |                 | 2.00   | 2.60       |                     | 5.20    |
| 117   | 9       | T74630-37020 C0 GRIP ASSY, DOOR <i>CRU x nn</i>      |                   |                 | 1.00   | 158.20     |                     | 158.20  |
| 118   | 0       | T74811-95J04 B3 HANDLE, DOOR PULL <i>CRU x nn</i>    |                   |                 | 2.00   | 19.30      |                     | 38.60   |
| 119   | 1       | T74610-37040 B0 GRIP ASSY, ASSIST <i>CRU x nn</i>    |                   |                 | 1.00   | 71.30      |                     | 71.30   |
| 120   | 2       | T74611-48010 B0 GRIP, ASSIST <i>CRU x nn</i>         |                   |                 | 1.00   | 46.90      |                     | 46.90   |
| 121   | 3       | T74348-22020 B9 HOLDER, VISOR <i>CRU x nn</i>        |                   |                 | 1.00   | 19.90      |                     | 39.80   |
| 122   | 4       | T74231-37012 B1 PANEL, FR DOOR <i>CRU x nn</i>       |                   |                 | 2.00   | 35.00      |                     | 35.00   |
| 123   | 5       | T74231-37020 B1 PANEL, FR DOOR <i>CRU x nn</i>       |                   |                 | 1.00   | 33.00      |                     | 33.00   |
| 124   | 6       | T67001-25051 PANEL SUB-ASSY, FR <i>CRU (over)</i>    |                   |                 | 1.00   | 1941.80    |                     | 1941.80 |
| 125   | 7       | T67861-37021 WEATHERSTRIP, FR <i>CRU</i>             |                   |                 | 1.00   | 221.40     |                     | 221.40  |
| 126   | 8       | T67863-37011 WEATHERSTRIP, FR <i>CRU x nn</i>        |                   |                 | 1.00   | 110.40     |                     | 110.40  |
| 127   | 9       | T67831-37020 COVER, FR DOOR <i>CRU x nn</i>          |                   |                 | 1.00   | 44.90      |                     | 44.90   |
| 128   | 0       | T53866-37042 SEAL, FR FENDER TO <i>CRU x nn</i>      |                   |                 | 1.00   | 50.50      |                     | 50.50   |
| 129   | 1       | T68610-37030 CHECK ASSY, FR DOOR <i>CRU x nn</i>     |                   |                 | 1.00   | 50.50      |                     | 50.50   |
| 130   | 2       | T68161-37011 WEATHERSTRIP, FR <i>CRU (with mull)</i> |                   |                 | 1.00   | 198.60     |                     | 198.60  |
| 131   | 3       | T67495-37010 COVER, FR DOOR FR <i>CRU</i>            |                   |                 | 1.00   | 123.20     |                     | 123.20  |
| 132   | 4       | T68141-37030 RUN, FR DOOR GLASS, <i>CRU</i>          |                   |                 | 1.00   | 60.00      |                     | 60.00   |
| 133   | 5       | T68101-37100 GLASS SUB-ASSY, FR <i>CRU</i>           |                   |                 | 1.00   | 263.40     |                     | 263.40  |
| 134   | 6       | T67403-37021 FRAME SUB-ASSY, FR <i>CRU</i>           |                   |                 | 1.00   | 805.10     |                     | 805.10  |
| For & on behalf of  |         | Customer's Signature                                 |                   |                 | Charge Summary   |            | Total               |         |
| Borneo Motors (Singapore) Pte Ltd   |         | Please acknowledge receipt of vehicle                |                   |                 | Parts  |            | Less                |         |
|   |         |  |                   |                 | Labour   |            |                     |         |
|   |         |  |                   |                 | Sublet   |            |                     |         |
|   |         |  |                   |                 | Lubrication/Fluid  |            |                     |         |
|   |         |  |                   |                 | Others   |            | Amount Due          |         |

Customer Copy

hchcape

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no. : 6631 1188

## ESTIMATE

| Account Details   |  | Account No.                 | Customer Details  |  |
|---|--|-----------------------------|---|--|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |  | S1000019 / ICUOI1           | M/S Lim Bs Enterprise Plasterceil   |  |
|   |  | Document No.<br>0           | 8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252 |  |
|   |  | Document Date<br>01/09/2022 | Mobile: 81801016  |  |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2021              | KDY231R    | TLMKY S5 | 09/07/2021      | GBL4078M   | 0            | 17266      | GBL4078M            |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JTFAT35Y70K216676 | 1KDB090552 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L   | Cd | Job/Parts Description               | Qty  | Unit Price | Disc % | Amount  |
|-----|----|-------------------------------------|------|------------|--------|---------|
| 135 | 7  | T90541-09031 CUSHION                | 4.00 | 10.80      |        | 43.20   |
| 136 | 8  | T68618-37020 BRACKET, FR DOOR       | 2.00 | 16.50      |        | 33.00   |
| 137 | 9  | T69210-37020 HANDLE ASSY, FR        | 1.00 | 221.00     |        | 221.00  |
| 138 | 0  | T69205-37010 B1 HANDLE SUB-ASSY, FR | 1.00 | 53.20      |        | 53.20   |
| 139 | 1  | T69310-37080 LOCK ASSY, FR DOOR.    | 1.00 | 341.40     |        | 341.40  |
| 140 | 2  | T69711-37010 LINK, FR DOOR LOCK     | 1.00 | 21.70      |        | 21.70   |
| 141 | 3  | T69749-12070 CLAMP, DOOR LOCK       | 2.00 | 3.20       |        | 6.40    |
| 142 | 4  | T69410-20110 PLATE ASSY, DOOR       | 2.00 | 42.60      |        | 85.20   |
| 143 | 5  | T68710-37020 HINGE ASSY, FR DOOR.   | 1.00 | 119.20     |        | 119.20  |
| 144 | 6  | T68730-37010 HINGE ASSY, FR DOOR.   | 1.00 | 119.20     |        | 119.20  |
| 145 | 7  | T69801-37052 REGULATOR SUB-ASSY.    | 1.00 | 384.50     |        | 384.50  |
| 146 | 8  | T69801-37063 REGULATOR SUB-ASSY.    | 1.00 | 385.10     |        | 385.10  |
| 147 | 9  | T85710-37090 MOTOR ASSY, POWER      | 1.00 | 765.50     |        | 765.50  |
| 148 | 0  | T71811-37022 B1 COVER, RECLINING    | 1.00 | 72.40      |        | 72.40   |
| 149 | 1  | T72110-37020 TRACK ASSY, FR SEAT,   | 1.00 | 359.00     |        | 359.00  |
| 150 | 2  | T72130-37020 TRACK ASSY, FR SEAT,   | 1.00 | 536.50     |        | 536.50  |
| 151 | 3  | T81110-37660 HEADLAMP ASSY, RH      | 1.00 | 1272.30    |        | 1272.30 |
| 152 | 4  | T81150-37660 HEADLAMP ASSY, LH      | 1.00 | 1272.30    |        | 1272.30 |
| 153 | 5  | T85212-37081 BLADE, FR WIPER, RH    | 1.00 | 91.90      |        | 91.90   |
| 154 | 6  | T85222-37141 BLADE, FR WIPER, LH    | 1.00 | 91.90      |        | 91.90   |

|   |                                       |  |            |
|---|---------------------------------------|--|------------|
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary   | Total      |
|   | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|   |                                       |  | Amount Due |

Customer Copy



# Borneo Motors



# TOYOTA

inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no. : 6631 1188

## ESTIMATE

| Account Details   |  | Account No.                 | Customer Details  |  |  |
|---|--|-----------------------------|---|--|--|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc |  | S1000019 / ICUO11           | M/S Lim Bs Enterprise Plastercell   |  |  |
|   |  | Document No.<br>0           | 8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252 |  |  |
|   |  | Document Date<br>01/09/2022 | Mobile: 81801016  |  |  |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2021              | KDY231R    | TLMKY S5 | 09/07/2021      | GBL4078M   | 0            | 17266      | GBL4078M            |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JTFAT35Y70K216676 | 1KDB090552 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L   | Cd | Job/Parts Description                                | Qty  | Unit Price | Disc % | Amount  |
|-----|----|--|------|------------|--------|---------|
| 155 | 7  | T87810-37091 C0 MIRROR ASSY, INNER <i>2xpr ? 1BR</i> | 1.00 | 136.10     |        | 136.10  |
| 156 | 8  | T87819-25010 LENS, INNER RR VIEW <i>mis</i>          | 1.00 | 15.40      |        | 15.40   |
| 157 | 9  | T87910-25040 MIRROR ASSY, OUTER <i>BR</i>            | 1.00 | 352.70     |        | 352.70  |
| 158 | 0  | T87965-37030 GROMMET, OUTER <i>x nn</i>              | 1.00 | 37.20      |        | 37.20   |
| 159 | 1  | T87010-37230 UNIT ASSY, AIR <i>BR</i>                | 1.00 | 2895.60    |        | 2895.60 |
| 160 | 2  | T87210-37100 CASE ASSY, AIR <i>BR</i>                | 1.00 | 365.40     |        | 365.40  |
| 161 | 3  | T55900-37560 CONTROL & ACCESSORY <i>x nn</i>         | 1.00 | 954.80     |        | 954.80  |
| 162 | 4  | T55843-37140 DUCT, HEATER TO <i>x nn</i>             | 1.00 | 100.50     |        | 100.50  |
| 163 | 5  | T55845-37060 DUCT, HEATER TO <i>x nn</i>             | 1.00 | 148.80     |        | 148.80  |
| 164 | 6  | T55844-37060 DUCT, HEATER TO <i>x nn</i>             | 1.00 | 100.50     |        | 100.50  |
| 165 | 7  | T55950-37100 NOZZLE ASSY, <i>x nn</i>                | 1.00 | 165.50     |        | 165.50  |
| 166 | 8  | T55972-37070 DUCT, SIDE DEFROSTER <i>x nn</i>        | 1.00 | 45.00      |        | 45.00   |
| 167 | 9  | T55967-37080 NOZZLE, DEFROSTER, <i>x nn</i>          | 1.00 | 92.50      |        | 92.50   |
| 168 | 0  | T55870-37010 DUCT ASSY, HEATER TO <i>x nn</i>        | 1.00 | 77.40      |        | 77.40   |
| 169 | 1  | T17700-30241 CLEANER ASSY, AIR <i>x nn</i>           | 1.00 | 844.90     |        | 844.90  |
| 170 | 2  | T17940-30110 INTERCOOLER ASSY <i>x nn</i>            | 1.00 | 2599.50    |        | 2599.50 |
| 171 | 3  | T55150-37320 BRACKET ASSY, PEDAL <i>x nn</i>         | 1.00 | 312.70     |        | 312.70  |
| 172 | 4  | T47101-37131 PEDAL SUB-ASSY, <i>x nn</i>             | 1.00 | 135.10     |        | 135.10  |
| 173 | 5  | T44610-25350 BOOSTER ASSY, BRAKE <i>x nn</i>         | 1.00 | 1704.20    |        | 1704.20 |
| 174 | 6  | T44704-25160 RESERVOIR SUB-ASSY, <i>x nn</i>         | 1.00 | 252.80     |        | 252.80  |

|   |                                       |  |            |
|---|---------------------------------------|--|------------|
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary   | Total      |
|   | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|   |                                       |  | Amount Due |

Customer Copy



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no. 6631 1188

## ESTIMATE

| Account Details  |         |                       | Account No.                |                 | Customer Details   |         |                      |           |            |           |
|--|---------|-----------------------|----------------------------|-----------------|--|---------|----------------------|-----------|------------|-----------|
| United Overseas Insurance Ltd<br>146 Robinson Road<br>#02-01 UOI Building<br>Singapore cc  |         |                       | S1000019 / ICU011          |                 | M/S Lim Bs Enterprise Plastercell<br>8 Marsiling Ind Estate Road 3<br>#01-12 Marsiling Industrial Estate<br>Singapore 739252<br><br>Mobile: 81801016 |         |                      |           |            |           |
|  |         |                       | Document No.               |                 |  |         |                      |           |            |           |
|  |         |                       | 0                          |                 |  |         |                      |           |            |           |
|  |         |                       | Document Date              |                 |  |         |                      |           |            |           |
|  |         |                       | 01/09/2022                 |                 |  |         |                      |           |            |           |
| Year   | Model   | Variant               | Reg. Date                  | Reg. No.        | Kilometers   | Wip No. | Order No. / Remarks  |           |            |           |
| 2021   | KDY231R | TLMKY S5              | 09/07/2021                 | GBL4078M        | 0  | 17266   | GBL4078M             |           |            |           |
| Chassis No.  |         | Engine No.            | Terms                      | SA / Counter    | Vehicle In   |         | Collected On         |           |            |           |
| JTFAT35Y70K216676  |         | 1KDB090552            | 60                         | Thomas Pang W T | --/--/----   |         | 0.00 --/--/---- 0.00 |           |            |           |
| L  | Cd      | Job/Parts Description |                            |                 |  | Qty     | Unit Price           | Disc %    | Amount     |           |
| 175  | 7       | T47220-37120          | RESERVOIR ASSY. ? x m      |                 |  |         | 1.00                 | 227.20    |            | 227.20    |
| 176  | 8       | T44778-25050          | HOSE, CONNECTOR TO ? x m   |                 |  |         | 1.00                 | 70.40     |            | 70.40     |
| 177  | 9       | T08889-01203          | COOLANT, SLLC (BLUE) ? x m |                 |  |         | 2.00                 | 138.00    |            | 276.00    |
| <p>SKK (LKK)<br/>11/9/22, 11.30am</p> <p>OO-M ML<br/>EXCESS-?<br/>PIP<br/>My Bel by<br/>20 days</p>  |         |                       |                            |                 |  |         |                      |           | 72,908.60  |           |
| <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>For Borneo Motors subject to confirmation</li> <li>Third party survey is not allowed</li> <li>Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> |         |                       |                            |                 | Customer's Signature   |         | Charge Summary       |           | Total      | 72,791.40 |
| Borneo Motors (Singapore) Pte Ltd  |         |                       |                            |                 | Please acknowledge receipt of vehicle  |         | Parts                | 47,588.60 | GST 7.00%  | 5,095.40  |
|  |         |                       |                            |                 |  |         | Labour               | 126.00    | Less       | 0.00      |
|  |         |                       |                            |                 |  |         | Sublet               | 25,076.80 |            |           |
|  |         |                       |                            |                 |  |         | Lubrication/Fluid    | 0.00      |            |           |
|  |         |                       |                            |                 |  |         | Others               | 0.00      | Amount Due | 77,886.80 |

Customer Copy