



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22008523/Evy3e2 Date: 07/12/2022 Code: UOI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBL 4078M
Policy No.	DH0M120061172100	Coverage (\$)	0.00
Claim No.	M12D19412209	Excess (\$)	500.00
Assign From	JOSEPHINE WONG	Assign Date	01/09/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTFAT35Y70K216676	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175 R15	DUNLOP	4 mm
L/H Front Tyre	175 R15	DUNLOP	4 mm
R/H Rear Tyre	175 R15	DUNLOP	4 mm
L/H Rear Tyre	175 R15	DUNLOP	4 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	30/08/2022	Inspection Date	01/09/2022
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
	A)THE MARKET VALUE IS S\$86,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days