

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008524/KQY3Q2**Date:** 13/09/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00048812200		
Claimant Vehicle No :	SJK946U	Insured Vehicle No :	GBA2827P		
Date of Loss:	27/08/2022	Nature of Claim:	TP	Claim No:	SNM22D206130/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK946U		Engine No:	4A910100100
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A)		Chassis No:	JMYSRCY2A8U007840
Reg. Date:	03/10/2008 (Man. Year: 2008)		Odometer:	141927 km
Colour:	White			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,115.90	1,805.81	310.09	14.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,150.00	1,050.00	47.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,315.90	2,955.81	1,360.09	31.51
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	4,315.90	2,350.00	1,965.90	45.55
+ GST 7.00/7.00% (S\$)	302.11	164.50	137.61	45.55
Nett Amount (S\$)	4,618.01	2,514.50	2,103.51	45.55

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	01/09/2022 Inspected At:	Riverview Auto Services Pte Ltd (HQ) 10, Ang Mo Kio Industrial Park 2A, #04-07 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK946U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RHS	Bent	588.00 F	*588.00 FL
2	1		*FRONT FENDER INNER SHIELD RHS	Cracked	175.90 F	*175.90 FL
3	1		*FRONT FENDER SIGNAL LAMP RHS	Cracked	87.50 F	*87.50 FL
4	1		*FRONT DOOR RHS	Bent	921.50 F	*921.50 FL
5	1		*FRONT DOOR HANDLE RHS	Dented	128.00 F	*128.00 FL
6	1		*FRONT FENDER INNER SHIELD CLIPS RHS	Necessary	35.00 FS	*35.00 FS
7	1		*FRONT DOOR STICKER WRAP RHS	Necessary	180.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,115.90	1,995.90
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	190.09
Total Parts (\$)	2,115.90	1,805.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & REPAIR ACCIDENT AREA	New	1,000.00	450.00
2	TO SPRAY PAINT FRONT FENDER RHS FRONT DOOR RHS AND REAR DOOR RHS	New	1,200.00	700.00
Gross Labour Cost (S\$)			2,200.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >