

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 05 Sep 2022

Preliminary Advice

Insured Vehicle No	: GBA2827P		
TP Vehicle No	: SJK946U	Accident Date	: 27/08/2022
Make	: MITSUBISHI LANCER	Assignment Date	: 01/09/2022
Date of Inspection	: 01/09/2022	Est. Duration of Repair	: 4
Inspection At	: RIVERVIEW AUTO SERVICES PTE LTD (HQ) 10, ANG MO KIO INDUSTRIAL PARK 2A, #04-07 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,315.90
Revised Amount	:S\$	2,955.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,955.54
 Lump Sum Repair	 :S\$	 2,350.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.