

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008530/TVY3Q2
Date: 01/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00047422207
Claimant Vehicle No :	SMH5698H	Insured Vehicle No :	YN2108R
Date of Loss:	31/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D206167/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH5698H	Engine No:	40605442B38A15A
Make & Model:	BMW X2, 2.0 SDrive20i (A)	Chassis No:	WBAYH12060EM92757
Reg. Date:	28/01/2019 (Man. Year: 2018)	Odometer:	48064 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,517.00	7,802.41	1,714.59	18.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,570.00	810.00	34.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,897.00	9,372.41	2,524.59	21.22
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	11,897.00	7,500.00	4,397.00	36.96
+ GST 7.00/7.00% (S\$)	832.79	525.00	307.79	36.96
Nett Amount (S\$)	12,729.79	8,025.00	4,704.79	36.96

INSPECTION

Date of Assignment:	01/09/2022	
Date Inspected:	01/09/2022	Inspected At: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts: M1-SUV	BMW X2 2.0 SDrive20i (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH5698H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,420.00 FL	*1,342.30 FL
2	1		*FRONT BUMPER SIDE RETAINERS	N/S Not Necessary/O/SNecessary	40.00 FL	*20.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	1		*FRONT BUMPER SENSOR (ORIGINAL) RH	Not Necessary	195.00 FL	*- FL
5	1		*FRONT BUMPER SENSOR HOLDER RH	Not Necessary	46.00 FL	*- FL
6	1		*HEADLAMP LED RH	Cut	3,360.00 FL	*3,138.30 FL
7	1		*HEADLAMP BOTTOM RETAINERS	Deformed	72.00 FL	*72.00 FL
8	1		*FRONT FENDER RH (ALUMINIUM)	Bent	724.00 FL	*677.35 FL
9	1		*FRONT FENDER EMBLEM /M RH	Necessary	80.00 FL	*80.00 FL
10	1		*FRONT FENDER INNER SHIELD RH	Deformed	156.00 FL	*156.00 FL
11	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*FRONT FENDER ARCH PROTECTOR RH	Cut	314.00 FL	*314.00 FL
13	1		*SET FRONT FENDER ARCH PROTECTOR CLIPS	Necessary	30.00 FL	*30.00 FL
14	1		*FRONT SPORT RIM RH	Dented	1,858.00 FL	*1,736.50 FL
15	1		*FRONT WHEEL BEARING RH	Bent	555.00 FL	*519.00 FL
16	1		*FRONT KNUCKLE ARM RH	Bent	550.00 FL	*513.90 FL
17	1		*FRONT SHOCK ABSORBER RH	Not Necessary	660.00 FL	*- FL
18	1		*FRONT TYRE RH	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,530.00	8,669.35
- List Item Discount on L Items 10.00/10.00% (\$)	1,013.00	866.94
Total Parts (\$)	9,517.00	7,802.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	600.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	60.00	30.00
5	REMOVE AND INSTALL FRONT SENSOR	New	90.00	30.00
6	REMOVE AND INSTALL FRONT UNDERCARRIAGE RH	New	280.00	150.00
7	TO CHECK FOUR WHEELS ALIGNMENT	New	90.00	80.00
8	TO RESET FAULT CODE SYSTEM	New	220.00	150.00
			Gross Labour Cost (\$)	2,380.00
				1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >