

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SMH 6698H  
 Vehicle Model : BMW X2  
 Accident Date : 31.07.2022  
 Original Reg Date : 28.01.2019

Date : 31.08.2022  
 Chassis : WDAYM1264DEM32757  
 TP Ins. **CHINA TAIPING**

## ESTIMATE

1	1 pc	Front Bumper	de/		1420.00	1342.30
2	2 pcs	Front Bumper Side Retainers	L4X m/h nu/	20.-	40.00	20
3	1 set	Front Bumper Clips	nu/		40.00	40
4	1 pc	Front Bumper Sensor (Original) RH	X nu/		195.00	
5	1 pc	Front Bumper Sensor Holder RH	X nu/		46.00	
6	1 pc	Headlamps 'LED' RH	nu/		3360.00	3138.30
7	1 pc	Headlamps Bottom Retainers	?	de/	72.00	
8	1 pc	Front Fender RH (Aluminium)	bt/		724.00	677.35
9	1 pc	Front Fender Emblem /// M RH	nu/		80.00	
10	1 pc	Front Fender Inner Shield RH	?	de/	156.00	
11	1 set	Front Fender Inner Shield Clips	?	nu/	30.00	
12	1 pc	Front Fender Arch Protector RH	nu/		314.00	✓
13	1 set	Front Fender Arch Protector Clips	nu/		30.00	✓
14	1 pc	Front Sport Rim RH	de/		1858.00	1736.50
15	1 pc	Front Wheel Bearing RH	?	✓ bt/	555.00	519
16	1 pc	Front Knuckle Arm RH	?	✓ bt/	550.00	513.90
17	1 pc	Front Shock Absorber RH	X nu/		660.00	
					10,130.00	8669.35
					1,013.00	7802.41
					9,117.00	

Tanpa 92467749  
 up 1/9/2022 less 10%  
 2/3 heavy of the up -

### Special Nett

1	1 pc	Front Tyre RH	4 days		400.00	X nu/
---	------	---------------	--------	--	--------	-------

### Labour charge

Panel Beating	500	800.00
Spray painting	600	800.00
Check Wiring	20	40.00
Anti rust	30	60.00
Remove and install front sensor.	90	90.00
Remove and install front undercarriage RH	✓ 150!	280.00
To check four wheels alignment	80.	90.00
To reset fault code system.	150	220.00

11,897.00  
 less 20% 2,379.40  
 Lump Sum 9,517.60  
 7802.41  
 1570  
 9372.41  
 1/5\$ 7500  
 = 4 days \*