



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

NO. : 41509

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
ATTN: MOTOR CLAIMS DEPT

DATE : 26/08/2022  
CLAIM NO. : 11994  
POLICY NO. : MC/00914057/01

FROM : RAYMOND

VEHICLE NO. : FBK1698Z  
MAKE/MODEL : YAM / YBR125

*not Authorized  
Lee  
1/9/22  
4/5 \$3200  
6 days.*

*limited*

(Page 1 of 4)

| S/N | Description                                                        | Action  | Qty  | Unit Price | Amount       |
|-----|--------------------------------------------------------------------|---------|------|------------|--------------|
| 1   | ALIGNMENT BODY<br>P/N: 29561<br>- (REPORTED BY MECHANIC)           | Repair  | 1.00 | \$380.00   | 11 380.00 X  |
| 2   | AXLE WHEEL FRONT<br>P/N: 25363<br>- (REPORTED BY MECHANIC)         | REPLACE | 1.00 | \$23.00    | sent 23.00   |
| 3   | BAR HANDLE<br>P/N: 42062<br>- (REPORTED BY MECHANIC)               | REPLACE | 1.00 | \$49.00    | sent 49.00   |
| 4   | BEARING 6202-DDUCM (NSK)<br>P/N: 40216<br>- (REPORTED BY MECHANIC) | REPLACE | 2.00 | \$14.00    | sent 28.00   |
| 5   | BRACKET FOOTREST LH<br>P/N: 25346<br>- (REPORTED BY MECHANIC)      | REPLACE | 1.00 | \$38.00    | sent 38.00 X |
| 6   | BRACKET MUDGUARD FRONT<br>P/N: 46221<br>- (REPORTED BY MECHANIC)   | REPLACE | 1.00 | \$24.00    | sent 24.00   |
| 7   | BRACKET UNDER FORK<br>P/N: 27458<br>- (REPORTED BY MECHANIC)       | REPLACE | 1.00 | \$180.00   | sent 180.00  |
| 8   | CABLE CLUTCH<br>P/N: 44111<br>- (REPORTED BY MECHANIC)             | REPLACE | 1.00 | \$19.00    | 2 days 19.00 |
| 9   | CABLE SPEEDOMETER<br>P/N: 50366<br>- (REPORTED BY MECHANIC)        | REPLACE | 1.00 | \$14.00    | 2 days 14.00 |

*102*

\*41509 \*

*bizSAFE<sub>3</sub>*



Quotation Nos. : 41509

| S/N | Description                                                                | Action  | Qty  | Unit Price | Amount              |
|-----|----------------------------------------------------------------------------|---------|------|------------|---------------------|
| 10  | CABLE THROTTLE 1<br>P/N: 43817<br>- (REPORTED BY MECHANIC)                 | REPLACE | 1.00 | \$22.00    | 22.00 <i>Dye</i> ✓  |
| 11  | CABLE THROTTLE 2<br>P/N: 43812<br>- (REPORTED BY MECHANIC)                 | REPLACE | 1.00 | \$24.00    | 24.00 <i>Dye</i> ✓  |
| 12  | CALIPER BRAKE FRONT ASSY<br>P/N: 45878<br>- (REPORTED BY MECHANIC)         | REPLACE | 1.00 | \$390.00   | 390.00 <i>11</i> X  |
| 13  | CAMERA (V_SYS) M6 (WIFI VERSION)<br>P/N: 56377<br>- (REPORTED BY MECHANIC) | REPLACE | 1.00 | \$350.00   | 350.00 <i>Dye</i> ✓ |
| 14  | COVER SIDE LH (BLACK)<br>P/N: 50007<br>- (REPORTED BY MECHANIC)            | REPLACE | 1.00 | \$96.00    | 96.00 <i>cm</i> ✓   |
| 15  | COVER SIDE RH (BLACK)<br>P/N: 53724<br>- (REPORTED BY MECHANIC)            | REPLACE | 1.00 | \$96.00    | 96.00 <i>cm</i> ✓   |
| 16  | COVER TAIL LH (RED)<br>P/N: 45536<br>- (REPORTED BY MECHANIC)              | REPLACE | 1.00 | \$77.00    | 77.00 <i>12</i> X   |
| 17  | COVER TANK SIDE LH (BLACK)<br>P/N: 54458<br>- (REPORTED BY MECHANIC)       | REPLACE | 1.00 | \$96.00    | 96.00 <i>cm</i> ✓   |
| 18  | COVER TANK SIDE RH (BLACK)<br>P/N: 54477<br>- (REPORTED BY MECHANIC)       | REPLACE | 1.00 | \$96.00    | 96.00 <i>cm</i> ✓   |
| 19  | COWLING FRONT (RED)<br>P/N: 52897<br>- (REPORTED BY MECHANIC)              | REPLACE | 1.00 | \$133.00   | 133.00 <i>Dis</i> ✓ |
| 20  | CRASH BAR<br>P/N: 35878<br>- (REPORTED BY MECHANIC)                        | REPLACE | 1.00 | \$203.00   | 203.00 <i>But</i> ✓ |
| 21  | CROWN HANDLE<br>P/N: 28100<br>- (REPORTED BY MECHANIC)                     | REPLACE | 1.00 | \$75.00    | 75.00 <i>1w1</i> ✓  |
| 22  | FOOTREST REAR ASSY LH<br>P/N: 25348<br>- (REPORTED BY MECHANIC)            | REPLACE | 1.00 | \$15.00    | 15.00 <i>11</i> X   |
| 23  | FORK FRONT ASSY LH<br>P/N: 45155<br>- (REPORTED BY MECHANIC)               | REPLACE | 1.00 | \$624.00   | 624.00 <i>But</i> ✓ |
| 24  | FORK FRONT ASSY RH<br>P/N: 45154<br>- (REPORTED BY MECHANIC)               | REPLACE | 1.00 | \$624.00   | 624.00 <i>But</i> ✓ |

\*41509 \*

bizSAFE<sub>3</sub>

Quotation Nos. : 41509

| S/N | Description                                                                           | Action         | Qty   | Unit Price | Amount     |
|-----|---------------------------------------------------------------------------------------|----------------|-------|------------|------------|
| 25  | GASKET EXHAUST PIPE<br>P/N: 21453<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00  | \$5.00     | 5.00 ✓     |
| 26  | HEADLAMP ASSY<br>P/N: 43129<br>- (REPORTED BY MECHANIC)                               | REPLACE        | 1.00  | \$105.00   | 105.00 ✓   |
| 27  | LABOUR<br>P/N: 06766<br>- LABOUR QUOTED FOR DISMANTLING AND<br>INSTALLATION OF PARTS. | Supply/Install | 16.00 | \$63.00    | 1,008.00 ✓ |
| 28  | LAMP SIGNAL FRONT LH<br>P/N: 43433<br>- (REPORTED BY MECHANIC)                        | REPLACE        | 1.00  | \$21.00    | 21.00 ✓    |
| 29  | LAMP SIGNAL FRONT RH<br>P/N: 43432<br>- (REPORTED BY MECHANIC)                        | REPLACE        | 1.00  | \$21.00    | 21.00 ✓    |
| 30  | LAMP SIGNAL REAR LH<br>P/N: 44190<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00  | \$21.00    | 21.00 ✓    |
| 31  | LEVER CLUTCH<br>P/N: 52644<br>- (REPORTED BY MECHANIC)                                | REPLACE        | 1.00  | \$19.00    | 19.00 ✓    |
| 32  | METER ASSY<br>P/N: 42063<br>- (REPORTED BY MECHANIC)                                  | REPLACE        | 1.00  | \$264.00   | 264.00 ✓   |
| 33  | METER IU (12V) NEW MODEL<br>P/N: 34351<br>- (REPORTED BY MECHANIC)                    | REPLACE        | 1.00  | \$280.00   | 280.00 ✓   |
| 34  | MID O-RING<br>P/N: 18587<br>- (REPORTED BY MECHANIC)                                  | REPLACE        | 1.00  | \$3.00     | 3.00 ✓     |
| 35  | MIRROR LH<br>P/N: 58099<br>- (REPORTED BY MECHANIC)                                   | REPLACE        | 1.00  | \$35.00    | 35.00 ✓    |
| 36  | MUDGUARD FRONT (RED)<br>P/N: 42220<br>- (REPORTED BY MECHANIC)                        | REPLACE        | 1.00  | \$49.00    | 49.00 ✓    |
| 37  | PIPE EXHAUST ASSY<br>P/N: 26600<br>- (REPORTED BY MECHANIC)                           | REPLACE        | 1.00  | \$630.00   | 630.00 ✓   |
| 38  | PLATE DISC BRAKE FRONT<br>P/N: 46052<br>- (REPORTED BY MECHANIC)                      | REPLACE        | 1.00  | \$193.00   | 193.00 ✓   |
| 39  | PLATE FRONT COWLING<br>P/N: 46220<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00  | \$26.00    | 26.00 ✓    |

\*41509 \*

bizSAFE<sub>3</sub>

| S/N | Description                                                                              | Action  | Qty  | Unit Price | Amount  |
|-----|------------------------------------------------------------------------------------------|---------|------|------------|---------|
| 40  | RUBBER FOOTREST FRONT<br>P/N: 26136<br>- (REPORTED BY MECHANIC)                          | REPLACE | 1.00 | \$14.00    | 14.00 X |
| 41  | STAY HEADLAMP<br>P/N: 45750<br>- (REPORTED BY MECHANIC)                                  | REPLACE | 1.00 | \$68.00    | 68.00   |
| 42  | STEERING CONE SET<br>P/N: 41793<br>- (REPORTED BY MECHANIC)                              | REPLACE | 1.00 | \$65.00    | 65.00   |
| 43  | STICKER (MCDONALDS) SIDE COVER / WINDSHEILD<br>P/N: 56222<br>- (REPORTED BY MECHANIC)    | REPLACE | 2.00 | \$16.00    | 32.00   |
| 44  | STICKER (MCDONALDS) WINDSHIELD V2<br>P/N: 56223<br>- (REPORTED BY MECHANIC)              | REPLACE | 1.00 | \$16.00    | 16.00   |
| 45  | STICKER NUMBER PLATE FRONT (BLACK)<br>STRAIGHT<br>P/N: 32921<br>- (REPORTED BY MECHANIC) | REPLACE | 1.00 | \$19.00    | 19.00   |
| 46  | TANK FUEL (RED)<br>P/N: 46240<br>- (REPORTED BY MECHANIC)                                | REPLACE | 1.00 | \$441.00   | 441.00  |
| 47  | TRANSPORT CHARGES<br>P/N: 07169<br>- BIKE TOWED BACK TO BHH                              |         | 1.00 | \$56.00    | 56.00   |
| 48  | VALVE RIM<br>P/N: 27762<br>- (REPORTED BY MECHANIC)                                      | REPLACE | 1.00 | \$13.00    | 13.00 X |

SUB TOTAL

\$7,080.00

GST @ 7 %

\$495.60

GRAND TOTAL (SGD)

\$7,575.60

50% deposit required before ordering of parts.

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge &amp; Accepted By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\*41509 \*

bizSAFE<sub>3</sub>