

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 22/08/2022

Estimated repair cost for vehicle no: SJR7068X TOYOTA VIOS E MANUAL

CHASSIS: MR053HY9305086698 (2008)

24/08/2022

TP China.
Xiao Long.

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>del</i>	\$548.90	\$548.90 ✓
2	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$74.60	\$149.20 <i>75.</i>
3	2	REAR BUMPER REFLECTOR <i>del</i>	\$87.60	\$175.20 ✓
4	1	REAR BOOTLID <i>Panel del</i>	\$645.20	\$645.20 ✓
5	1	REAR BOOTLID LOCK <i>del</i>	\$102.30	\$102.30 ✓
6	1	REAR BOOTLID INNER TRIME <i>del</i>	\$294.70	\$294.70 <i>+</i>
7	1	REAR BOOTLID OUTER MOULDING <i>new</i>	\$188.30	\$188.30 <i>+</i>
8	1	REAR BOOTLID EMBLEM LOGO <i>new</i>	\$55.60	\$55.60 ✓
9	1	REAR BOOTLID EMBLEM VIOS <i>new</i>	\$84.60	\$84.60 ✓
10	1	REAR BOOTLID EMBLEM E <i>new</i>	\$34.60	\$34.60 ✓
11	2	REAR BOOTLID HINGE <i>new</i>	\$65.10	\$130.20 <i>+</i>
12	1	REAR WEATHER STRIPE <i>del</i>	\$175.80	\$175.80 ✓
13	2	REAR TAILLAMP <i>del</i>	\$457.60	\$915.20 <i>630.</i>
14	2	REAR TAILLAMP INNER PANEL <i>Repair</i>	\$194.70	\$389.40 <i>+</i>
15	1	REAR END PANEL <i>del</i>	\$455.60	\$455.60 ✓
16	1	REAR END PANEL TOP GARNISH <i>del</i>	\$189.10	\$189.10 ✓
17	1	REAR SPARE TYRE COMPARTMENT PANEL <i>Repair</i>	\$863.70	\$863.70 <i>+</i>
18	1	REAR SPARE TYRE TOP BOARD <i>del</i>	\$185.10	\$185.10 ✓
19	1	REAR TOOLS SPONGE <i>del</i>	\$186.40	\$186.40 ✓

3543.40

2657.55

TOTAL :	<u>\$5,769.10</u>
LESS 25 %	<u>\$1,442.28</u>
SUB-TOTAL :	<u>\$4,326.83</u>

SJR7068X TOYOTA VIOS

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>Neu</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL TOP GARNISH CLIPS <i>Neu</i>	\$60.00	\$60.00 <i>10</i>
3	1	REAR REVERSE SENSOR <i>Brand</i>	\$250.00	\$250.00 <i>20</i>
4	1	REAR REVERSE CAMERA <i>Neu</i>	\$380.00	\$380.00 <i>+</i>
5	1	REAR END PANEL SEALANT <i>Neu</i>	\$60.00	\$60.00 <i>✓</i>
6	1	REAR NUMBER PLATE WITH CASING <i>Neu</i>	\$60.00	\$60.00 <i>+</i>
			TOTAL:	\$890.00
			TOTAL PARTS:	\$5,216.83

300

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,400.00 <i>850</i>
2	LABOUR FOR SPRAYPAINTING	\$1,200.00 <i>850</i>
3	WIRING CHECK	\$80.00 <i>30</i>
4	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00 <i>80</i>
6	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING	\$200.00 <i>60</i>
7	To remove reverse sensor and rear camera	<i>200.00</i>
8	To remove upholstery.	<i>150.00</i>
		Subtotal :- \$3,180.00
		Total:- \$8,396.83

2030

Adran G
 n/s 24/08/22.
 Obayan
 Total: 4987.85
 n/s: AK
 (AK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: