



6514 5247

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT22002538	Page	1
	3 ANSON ROAD #16-00	Date	: 1. Sep 2022		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: EK161B	Engine No	: L15B5672185		
Chassis No	: JHMRU1830JX202184	Date Time	: 1. Sep 2022 11:31:41 AM		
Model	: HRV LX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: KATHRYN CHAI MEI FERN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
62100-T7A-J00ZZ	PANEL COMPROOF	1	681.20	25	510.90	35.76	546.66
83200-T7A-T02ZA	LINING ASSY, ROOF	1	587.20	25	440.40	30.83	471.23
04636-T7A-310ZZ	PANEL SET, R.RR. OUTSIDE	1	657.60	25	493.20	34.52	527.72
04646-T7A-310ZZ	PANEL SET, L.RR. OUTSIDE	1	657.60	25	493.20	34.52	527.72
63320-T7A-900ZZ	GUTTER COMP R, RR	1	93.40	25	70.05	4.90	74.95
63720-T7A-900ZZ	GUTTER COMP L, RR	1	93.40	25	70.05	4.90	74.95
62130-T7A-310ZZ	RAIL COMP, RR, ROOF	1	117.50	25	88.12	6.17	94.29
68100-T7A-J20ZZ	TAIL GATE COMP	1	915.90	25	686.92	48.08	735.00
68210-T5A-J03ZZ	HINGE COMPTAILGATE	1	32.90	25	24.67	1.73	26.40
74820-T7A-003	STAY ASSY, R. TAILGATE OPEN	1	100.70	25	75.52	5.29	80.81
74870-T7A-003	STAY ASSY, L. TAILGATE OPEN	1	100.70	25	75.52	5.29	80.81
74900-T7A-E01ZJ	GARNISH ASSY, TAILGATE SPOILER	1	425.40	25	319.05	22.33	341.38
74440-T7A-003	WEATHERSTRIPTAILGATE	1	105.60	25	79.20	5.54	84.74
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY	1	174.70	25	131.02	9.17	140.19
74810-T7A-J01	SWITCH ASSY, TAILGATE OPENER	1	103.00	25	77.25	5.41	82.66
74813-T5A-003	STRIKER ASSY, TAILGATE	1	24.70	25	18.52	1.30	19.82
74827-SWA-A10	STOPPERTAILGATE	1	4.10	25	3.07	0.21	3.28
74899-T7A-003	DAMPERTAILGATE DYNAMIC	1	70.10	25	52.57	3.68	56.25
91513-T6A-003	CLIPTAILGATE SPOILER	1	2.60	25	1.95	0.14	2.09
75722-T7W-A01	EMBLEMRR.	1	15.40	25	11.55	0.81	12.36
75725-T8N-T00	EMBLEM, RR. I-VTEC	1	16.70	25	12.52	0.88	13.40
74890-T7A-J13ZB	GARNISH ASSY, RR. LICENSE	1	236.50	25	177.37	12.42	189.79
34100-T5A-003	LIGHT ASSY, LICENSE	1	34.00	25	25.50	1.79	27.29
34103-T5A-003	GASKET	1	5.20	25	3.90	0.27	4.17
33502-T7A-J31	LAMP UNIT, R.	1	429.90	25	322.42	22.57	344.99
33552-T7A-J31	LAMP UNIT, L.	1	429.90	25	322.42	22.57	344.99
34150-T7A-J31	LIGHT ASSY, R. LID	1	288.90	25	216.67	15.17	231.84
34155-T7A-J31	LIGHT ASSY, L. LID	1	288.90	25	216.67	15.17	231.84
34270-T7A-H01	LIGHT ASSY, HIGH MOUNT STOP	1	197.90	25	148.42	10.39	158.81

Printed on 1/9/2022 2:30:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : EK161B
Chassis No : JHMRU1830JX202184
Model : HRV LX-SIN CVT YM 2018
Owner's Name : KATHRYN CHAI MEI FERN
Ins Policy No :
Date of Accident : 27/8/2022

Document No. : SQT22002538
Date : 1. Sep 2022
Customer No. : WZC008
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5672185
Date | Time : 1. Sep 2022 11:31:41 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
73211-T8N-T02	GLASS SET,RR.WINDSHIELD	1	739.80	25	554.85	38.84	593.69
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.27	4.17
91501-S70-003	FASTENER BW/SHIELD	1	5.30	25	3.97	0.28	4.25
91502-S70-003	FASTENER B	1	5.40	25	4.05	0.28	4.33
91536-SS0-J01	FASTENER AW/SHIELD	1	3.80	25	2.85	0.20	3.05
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	145.60	25	109.20	7.64	116.84
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER	1	63.50	25	47.62	3.33	50.95
84435-T7A-J01ZA	LINING ASSYR.TAILGATE SIDE	1	22.70	25	17.02	1.19	18.21
84485-T7A-J01ZA	LINING ASSYL.TAILGATE SIDE	1	22.70	25	17.02	1.19	18.21
84400-T7A-J01ZA	COVER COMPTONNEAU	1	141.90	25	106.42	7.45	113.87
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING	1	157.40	25	118.05	8.26	126.31
84660-T7A-J02ZA	BASE COMP.L.TRUNK SIDE LINING	1	145.40	25	109.05	7.63	116.68
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	203.10	25	152.32	10.66	162.98
84550-T7A-J10	BOX ASSY,CARGO FL	1	138.60	25	103.95	7.28	111.23
04715-T7A-900ZZ	FACE,RR.BUMPER	1	484.70	25	363.52	25.45	388.97
76720-T7A-003	ARM,RR.WIPER	1	45.60	25	34.20	2.39	36.59
76721-S2H-003	COVERARM	1	5.60	25	4.20	0.29	4.49
76730-T7A-003	BLADEWINDSHIELD WIPER	1	39.90	25	29.92	2.09	32.01
39530-T7A-U01	CAMERA ASSY,RR.VIEW	1	1136.70	25	852.52	59.68	912.20
91533-STK-003	CLIPCOUPLER	1	5.70	25	4.27	0.30	4.57
08F52-T7S-700AX	TAIL GATE END MOLDING	1	95.30	10	85.77	6.00	91.77
08P01-T7S-700X	RR.BPR PROTECTOR	1	147.00	10	132.30	9.26	141.56
NMDVR-NEFUPLABO-2C	DVR, NEFU PLABO 2 CHANNEL	1	429.90		429.90	30.09	459.99
73151-T7A-003	MOLDING,FR.WINDSHIELD LOWER	1	43.50	25	32.62	2.28	34.90
73125-T7A-003	MOLDINGFR.WINDSHIELD SIDE	1	15.80	25	11.85	0.83	12.68

Printed on 1/9/2022 2:30:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT22002538	Page	3
	3 ANSON ROAD #16-00	Date	: 1. Sep 2022		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: EK161B	Engine No	: L15B5672185		
Chassis No	: JHMRU1830JX202184	Date Time	: 1. Sep 2022 11:31:41 AM		
Model	: HRV LX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: KATHRYN CHAI MEI FERN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
73150-T7A-003	MOLDINGFR.WINDSHIELD	1	19.90	25	14.92	1.04	15.96
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
77466-SV4-000	SEALFR.INSTRUMENT	1	12.10	25	9.07	0.63	9.70
64300-T7A-425ZZ	PANEL COMP.R.RR.INSIDE	1	657.60	25	493.20	34.52	527.72
04631-T7A-310ZZ	PANEL,R.SIDE SILL	1	265.40	25	199.05	13.93	212.98
Sum Item					9258.78	648.07	9,906.85

BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00	✓	650.00	45.50	695.50
BOSUN	SUNDRIES	1	110.00	50	110.00	7.70	117.70
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	180	280.00	19.60	299.60
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	280.00	180	280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	480	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	480	560.00	39.20	599.20
BG01S	TO VACUUM & CLEAR SHATTERED GLASS	1	380.00	325	380.00	26.60	406.60
BPBODY	INSTALL INCAR CAMERA	1	325.00	325	325.00	22.75	347.75
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	✓	650.00	45.50	695.50
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	650.00	✓	650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	✓	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT RR WINDSCREEN	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FR WINDSCREEN	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FENDER	1	120.00	100	120.00	8.40	128.40
BO-TOW	TOWING SERVICES (MBBS)	1	280.00	250	280.00	19.60	299.60
BKROR	CUT & RENEW ROOF PANEL, FENDER, INNER PANEL	1	13000.00	9750	13000.00	910.00	13910.00

Printed on 1/9/2022 2:30:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT22002538	Page	4
Registration No	: EK161B	Date	: 1. Sep 2022	Customer No.	: WZC008
Chassis No	: JHMRU1830JX202184	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15B5672185
Model	: HRV LX-SIN CVT YM 2018	Date Time	: 1. Sep 2022 11:31:41 AM	Surveyor Name	:
Owner's Name	: KATHRYN CHAI MEI FERN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 27/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (8P)	1	5200.00	✓	5200.00	364.00	5564.00
BG01R	REPLACE FR. WINDSCREEN.(N)	1	650.00	✓	650.00	45.50	695.50
			Sum Labor		24705.00	1,729.35	26,434.35
	CHASSIS ALIGNMENT	1500	✓				

Survey By Guo Qiang - LKK 82880282Date & Time 01-09-2022

Excess _____

Status _____

Signature _____

Total Amount 34,263.78 2,398.42 36,662.20**Total (Inclusive of GST)** **36,662.20**

25 Days

Before paint photos

**Printed on 1/9/2022 2:30:44 PM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.