



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SEDGWICK SINGAPORE PTE. LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712			Ref: CS/SGK22008537/Gny3e2	
			Date: 28/09/2022	
			Code: SGK	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	EK 161B
	Policy No.		Coverage (\$)	0.00
	Claim No.	6012669/ARI	Excess (\$)	0.00
	Assign From	ABRAHAM	Assign Date	01/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5 LX	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JHMRU1830JX202184	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date		Inspection Date	01/09/2022
	Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		25 Working Days	