



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22007177/Tvy3m4-1 Date: 08/09/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 9054G	Veh. Inspected	SKC 988D	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026075	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	30/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA CX-5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6KF2W7AK0318031	Colour	BLUE	
Odometer	35456 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/65 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2022	Inspection Date	27/07/2022	
Survey held at	CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	