



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					CS3/LPC22007177/Tvy3-1	
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555				Ref: CS3/LPC22007177/Tvy3 Date: 27/07/2022 30/08/2022 Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
Insured Veh.		GBA 9054G		Veh. Inspected		SKC 988D
Policy No.				Coverage (\$)		0.00
Claim No.				Excess (\$)		0.00
Assign From		GERALD POH		Assign Date		27/07/2022 30/08/2022
2. Vehicle Particulars & Condition						
Make & Model				c.c		0
Engine No.		HIDDEN		Year of Reg.		
Chassis No.				Colour		
Odometer		-		Steering		
Brakes				Modification		
General						
3. Conditions of Tyres						
		Size		Make		Balance
	R/H Front Tyre					mm
	L/H Front Tyre					mm
	R/H Rear Tyre					mm
	L/H Rear Tyre					mm
4. Description of Damages						
5. General Information						
Accident Date		26/07/2022		Inspection Date		27/07/2022
Survey held at		CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836				
5a. Remarks						
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						