

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 7880M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER - LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,349.63	-
1	REAR DOOR - LH (CONSISTENT)	DENTED / WARPED	1,278.31	1,278.31
1	REAR DOOR OUTER HANDLE - LH (CONSISTENT)	SERVICEABLE	51.88	-
	LESS 10% DISCOUNT		-267.98	-127.83
			2,411.84	1,150.48
	DEAD COORT DIM LLL (CONCICTENT) (CN)	CODATOLIED	245.00	60.00
1	REAR SPORT RIM - LH (CONSISTENT) (SN) LESS 10% DISCOUNT	SCRATCHED	345.60	60.00
	LESS 10% DISCOUNT		-34.56	-
			311.04	60.00
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (CONSISTENT) (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO TRANSFER LH REAR DAMAGED DOOR INTERIOR MECHANISM GLASS TO NEW NEW DOOR.		150.00	60.00
	TO PANEL BEAT & STRAIGHTEN LH DOOR PILLAR, LH REAR CHASSIS FRAME, TO CUT AND WELD REAR LH FENDER INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF REAR FENDER - LH.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		1,000.00	480.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.		120.00	30.00
	TO COMPUTERISE CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	
			2,540.00	1,070.00
	GRAND TOTAL		5,322.88	2,280.48

Report Ref No. CS/ASM22008543/Kvy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			2,280.48
-----------------------------	--	--	----------

Report Ref No. CS/ASM22008543/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser