



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 675722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Kenneth.

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : FBR5946U

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 29/08/2022

TP VEH REG NO : FBR5946U

ESTIMATE

NO : QUOT202208-000064(00)

DATE : 31/08/2022

POLICY NO : 999995580

VEH REG NO : SNE7880M

MAKE/MODEL : KIA CERATO 1.6(A) LX

CHASSIS NO : KNAF1416MN5139966

ENGINE NO : G4FGNH700526

REG. DATE : 2021

Not Notifying

Runway B4 pair

4 days

B 7280.48

Estimate Repair Cost to Vehicle No : SNE7880M

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear fender - LH	1	1,349.63	1,349.63 X
2 Rear door - LH	1	1,278.31	1,278.31 ✓
3 Rear door outer handle - LH	1	51.88	51.88 X
4 Rear sport rim - LH	1	345.60	345.60 60.00
			3,025.42
		Less 10%	302.54
			2,722.88
SPECIAL NET			
5 Rear windscreen sealant	1	60.00	60.00 X
			60.00
LABOUR			
6 To remove and refit rear windscreen glass	1	150.00	150.00 X
7 To transfer LH rear damaged door interior mechanism and glass to new new door	1	150.00	150.00 60.00
8 To panel beat & straighten LH door pillar, LH rear chassis frame, to cut and weld rear LH fender including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 500.00
9 To putty and spray paint on affected areas	1	1,000.00	1,000.00 480.00
10 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00 30.00
11 To computerise check wheel alignment	1	120.00	120.00 X
			2,540.00

TOTAL S\$ 5,322.88

ADD GST @ 7% 372.60

GRAND TOTAL S\$ 5,695.48

SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED NINETY FIVE AND CENTS FORTY-EIGHT ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE