

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cedge.com.sg

INSURER:

India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	13/08/2022
Vehicle Reg. No.:	SDK8800A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		
Make/Model:	TOYOTA CAMRY, 2.0 (A)	Vehicle Reg. Date:	30/12/2016
Vehicle Colour:	BLUE	Chassis No:	MR053DK5100108774
Engine No:	6ARP212540		
Odometer:	22390 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7 days		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*NOT Not have
1/1 Rm 8
Penny After Penny
Ex TBA*

COST OF CLAIMS	Amount
Parts	14,125.50
Miscellaneous Items	11.00
Labour	3,610.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	17,746.50
+ GST 7.00% (S\$)	1,242.26
Nett Amount (S\$)	18,988.76

This claim is handled by: **PATRICK TIA JEE KIANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

9/2/22, 9:21 AM

Merimen e-Claims

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 31 Aug 2022)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SDK8800A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH WING MIRROR ASSY	25.00	0.00	1,374.90 FL
2	1		*FRT RH DOOR	25.00	0.00	1,774.10 FL
3	1		*FRT RH DOOR HINGE TOP	25.00	0.00	103.10 FL
4	1		*FRT RH DOOR HINGE LOWER	25.00	0.00	117.60 FL
5	1		*FT RH DOOR CHECKER	25.00	0.00	195.20 FL
6	1		*FRT RH DOOR WINDOW REGULATOR	25.00	0.00	293.50 FL
7	1		*FRT RH DOOR WINDOW MOULDING (CHROME)	25.00	0.00	121.10 FL
8	1		*FRT RH DOOR FRAME MOULDING (BLACK)	25.00	0.00	83.50 FL
9	1		*FRT RH DOOR WHEATHERSTRIP	25.00	0.00	245.50 FL
10	1		*FRT RH DOOR LOCK MECHANISM	25.00	0.00	639.60 FL
11	1		*FRT RH DOOR GLASS	25.00	0.00	909.20 FL
12	1		*FRT DOOR HANDLE SEAL 1	25.00	0.00	38.20 FL
13	1		*FRT DOOR HANDLE SEAL 2	25.00	0.00	38.20 FL
14	1		*FRT RH DOOR HANDLE INNER BASE	25.00	0.00	224.70 FL
15	1		*FRT RH DOOR HANDLE SWITCH	25.00	0.00	44.80 FL
16	1		*FRT DOOR INNER TRIM	25.00	0.00	1,855.90 FL
17	1		*RH CENTER PILLAR OUTER	25.00	0.00	343.00 FL
18	1		*RH ROCKER PANEL GARNISH	25.00	0.00	633.30 FL
19	1		*REAR RH DOOR	25.00	0.00	1,597.40 FL
20	1		*RER RH DOOR HINGE TOP	25.00	0.00	103.10 FL
21	1		*REAR RH DOOR HINGE LOWER	25.00	0.00	103.10 FL
22	1		*REAR RH DOOR CHECKER	25.00	0.00	233.70 FL
23	1		*REAR RH DOOR WINDOW MOULDING (CHROME)	25.00	0.00	97.90 FL
24	1		*REAR RH DOOR FRAME MOULDING (BLACK)	25.00	0.00	83.50 FL
25	1		*REAR DOOR WHEATHERSTRIP	25.00	0.00	217.30 FL
26	1		*REAR DOOR LOCK	25.00	0.00	595.70 FL
27	1		*REAR DOOR GLASS	25.00	0.00	443.30 FL
28	1		*REAR DOOR WINDOW REGULATOR	25.00	0.00	289.30 FL
29	1		*REAR DOOR RUBBER	25.00	0.00	79.50 FL
30	1		*DRIVER SEAT BACKREST CUSHION COVER	25.00	0.00	-
31	1		*DRIVER SEAT BACKREST CUSHION SPONGE	25.00	0.00	-
32	1		*DRIVER SEAT AIRBAG	25.00	0.00	3,039.50 FL
33	1		*DRIVER SEATBELT	25.00	0.00	1,050.40 FL
34	1		*ROOF LINING	25.00	0.00	-
35	1		*RH ROOF TOOP AIRBAG	25.00	0.00	2318.00 FL
36	1		*AIRBAG CONTROL UNIT	25.00	0.00	1,864.90 FL
Sub Total (\$\$)						18,834.00
- List Item Discount on L Items (\$\$)						4,708.50
Total Parts (\$\$)						14,125.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9/2/22, 9:21 AM

Merimen e-Claims

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock & straighten on accident area, to remove & refit RIGHT damage parts	New	700d 1,000.00
2	To putty & respray on frt rh door, rear rh door, rh center pillar, rh rocker panel garnish, rh roof top pillar	New	90d 1,000.00
3	To repair rh roof top pillar	New	20d 400.00
4	To check wiring	New	2d 100.00
5	To remove & refit FRT RH Door trim, door glass, window regulator, door lock to assist work load.	New	80.00 ✓
6	To remove & refit REAR RH Door trim, door glass, window regulator, door lock to assist work load.	New	80.00 ✓
7	To refit airbag system	New	25d 400.00
8	To reset airbag control unit	New	200.00
9	To remove & refit roof lining, inner trim to assist work load	New	12d 200.00
10	To remove & refit inner seat & upholstery to assist work load	New	150.00
Gross Labour Cost (\$)			3,610.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >