

TP China.
Xiao Teng.

SLW 9037 Y.
Honda Shuttle Hybrid.

GPT1120206

Rees	Number Plate	} NP new	30(SN) X
Rees	Number Plate Holder		30(SN). X
Rees	Bumper	Del'd	986.90 ✓
Rees	Bumper Clips.	new	30(SN). ✓
Rees	Bumper Side Holder x 02	RH Del'd	32.20 $32.2 \times 2 = 64.40$
Rees	Bumper Tow Cover.	Missing	23.40. ✓
Rees	Bumper Side Grille RH.	Del'd	68.90. ✓
Rees	Bumper Side Grille Reflector RH.	NP new	45.20. X
Rees	Bumper Sponge RH.	used	47.50 ✓
Rees	Bumper Undercover RH	Del'd	155.10 ✓
Rees	Bumper Undercover Clips	new	20(SN) ✓
Rees	End Panel.	Del'd	681.20. ✓
Rees	End Panel Top Garnish.	Del'd	155.40 ✓
Rees	End Panel Top Garnish Clips.	new	20(SN) ✓
Rees	End Panel Sealant.	new	60(SN) ✓

SLW9037Y.

	Reverse Sensor	Dmgd	280(SW) ^{200(SW)}	
	Taillamp RH.	Crushed	520.50.	✓
	Taillamp Panel RH.	Repair	255.40.	X
	Tailgate	Distorted	1193.20	✓
	Tailgate Lock	Dmgd	298.40.	✓
	Tailgate Weatherstripe.	LA	166.50	✓
	Tailgate Reflector RH.	new	380.90	X
	Tailgate Inner Trim Board	Crushed	320.40	✓
	Tailgate Inner Trim Board Clips.	new	30(SW)	✓
	Rear RH Fender Inner Trim	Crushed	399.60	✓
	Rear RH Fender Inner Trim Clips.	new	30(SW)	✓
5163	Spare Tyre Top Cover.	new	585.20	X
413040	Honda Logo	new	45.90.	X
SN: 390	Shuttle Emblem.	new	55.40.	✓
	Hybrid Emblem.	new	58.40	✓
	Rear Exhaust Pipe	Repair	745.40	X
	Rear Exhaust Pipe Mounting.	new	32.40	X

SLW9037Y.

Panel Beating

Spray Painting

Wiring.

To remove reverse sensor

To remove rear camera.

To remove video recorder 2020

To remove upholstery.

To transfer tailgate fittings.

To remove tailgate g/s

To remove exhaust pipe. 2540

To spray tuff coat

(5,600)

~~1200~~ 1000

~~1100~~ 1000

~~50~~ 30

~~100~~ 50

~~100~~ 50

~~120~~ 50

~~150~~ 80

~~150~~ 80

~~180~~ 120

150. X.

~~150~~ 80

total: 7060.40

h/s: S.6K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: