

ADVANCE AUTO GARAGE

VEHICLE DETAILS

VEHICLE NO : SKT200D 2019 DEC
 VEHICLE MODEL : MERCEDES BENZ A250
 CHASSIS NO : WDD1771462J126118

TPA14.

Xiao Tony

ACCIDENT DETAILS
 DATE :
 TIME :

THIRD PARTY REQUESTOR / CONTACT : XAIVER / 90079247

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR <i>Dented</i>	1	\$ 2,245.00	\$ 2,245.00
2	FRONT DOOR LOCK <i>Dmgd</i>	1	\$ 389.00	\$ 389.00
3	FRONT DOOR WEATHERSTRIPE <i>New</i>	1	\$ 321.00	\$ 321.00
4	FRONT DOOR INNER TRIM BOARD <i>Crackd.</i>	1	\$ 898.00	\$ 898.00
5	FRONT DOOR OUTER HANDLE <i>new</i>	1	\$ 228.00	\$ 228.00
6	FRONT DOOR GLASS REGULATOR GEAR <i>Damaged</i>	1	\$ 345.00	\$ 345.00
7	FRONT DOOR GLASS REGULATOR MOTOR <i>New</i>	1	\$ 418.00	\$ 418.00
8	FRONT DOOR GLASS OUTER MOULDING <i>New</i>	1	\$ 218.00	\$ 218.00
9	FRONT DOOR HINGE <i>new</i>	2	\$ 140.00	\$ 280.00
10	ROCKER PANEL OUTER SKIRTING <i>Dented</i>	1	\$ 890.00	\$ 890.00
11	REAR DOOR <i>Dented</i>	1	\$ 2,319.00	\$ 2,319.00
12	REAR DOOR LOCK <i>new</i>	1	\$ 402.00	\$ 402.00
13	REAR DOOR WEATHERSTRIPE <i>New</i>	1	\$ 343.00	\$ 343.00
14	REAR DOOR INNER TRIM BOARD <i>Crackd</i>	1	\$ 881.00	\$ 881.00
15	REAR DOOR GLASS REGULATOR GEAR <i>Damaged</i>	1	\$ 359.00	\$ 359.00
16	REAR DOOR GLASS REGULATOR MOTOR <i>3MP</i>	1	\$ 450.00	\$ 450.00
17	REAR DOOR GLASS OUTER MOULDING <i>new</i>	1	\$ 204.00	\$ 204.00
18	REAR DOOR HINGE <i>3MP</i>	2	\$ 140.00	\$ 280.00
19	REAR DOOR CHECK <i>new</i>	1	\$ 95.00	\$ 95.00
20	REAR BUMPER <i>new</i>	1	\$ 1,458.00	\$ 1,458.00
21	REAR LOWER ARM <i>Best</i>	1	\$ 635.00	\$ 635.00
22	REAR LOWER ARM COVER <i>New</i>	1	\$ 95.00	\$ 95.00
23	REAR SHOCK ABSORBER <i>New</i>	1	\$ 604.00	\$ 604.00
24	REAR KNUCKLE ARM <i>Dmgd</i>	1	\$ 998.00	\$ 998.00
25	REAR WHEEL HUB C/W BEARING <i>Dmgd</i>	1	\$ 485.00	\$ 485.00
26	REAR CONTROL ARM <i>3 Best</i>	1	\$ 321.00	\$ 321.00
27	REAR STAY ARM	1	\$ 342.00	\$ 342.00

TOTAL PRICE: \$ 16,503.00
 LESS 10% \$ 1,650.30
 SUB TOTAL PRICE: \$ 14,852.70

1322.90
 11906.10

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00

30

2	ROCKER PANEL OUTER SKIRTING GARNISH <i>Rys</i>	1	\$	320.00	\$	320.00	<i>+</i>
3	ROCKER PANEL OUTER SKIRTING GARNISH CL PS <i>new</i>	1 SET	\$	50.00	\$	50.00	<i>+</i>
4	REAR DOOR INNER TRIM BOARD CLIPS <i>hw</i>	1 SET	\$	50.00	\$	50.00	<i>30</i>
5	REAR BUMPER CLIPS <i>hw</i>	1 SET	\$	50.00	\$	50.00	<i>880</i>
6	REAR WHEEL RIM <i>lt</i>	1	\$	1,500.00	\$	1,500.00	<i>+</i>
7	REAR TYRE <i>new</i>	1	\$	300.00	\$	300.00	<i>+</i>
				TOTAL :	\$	2,320.00	

8 Sticker Wrap Nec

1800 1200

2190

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE UPHOLSTERY	\$ 150.00	<i>X</i>	
7	TO DISMANTLE UNDERCARRIAGE	\$ 380.00	<i>220</i>	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	
9	TO TRANSFER FRONT & REAR DOOR FITTINGS	\$ 300.00	<i>160</i>	
10	TO PERFORM DIAGNOSTIC TEST	\$ 250.00	<i>150</i>	
		TOTAL:	\$ 4,380.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 17,172.70

TOTAL LABOUR COST: \$ 4,380.00

TOTAL REPAIR COST: \$ 21,552.70

2150

total: 1646.10

1/s: 13K

10 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

13K
10 days