

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200278
Date: 29 Aug 2022
Veh Reg No: SLH2986H
Make/Model: VOLKSWAGEN
TOURAN SPORT 1.4 TSI
AT 1T34C4
Chasis No: WVGZZZ1TZBW043918
Reg. Date: 26/01/2011
Your Ref No: SKH938Y

Claim Type: Third Party
Accident Date: 26/08/2022
TP Veh Reg No: SKH938Y

Estimate Repair Cost to Vehicle No :SLH2986H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID		
2	1 PC BOOT LID "VW" EMBLEM		
3	1 PC BOOT LID "TSI" EMBLEM		
4	1 PC "TOURAN" EMBLEM		
5	1 PC BOOT LID RUBBER		
6	1 PC REAR PANEL		
7	1 PC REAR PANEL TRIM		
8	1 PC REAR BUMPER		
9	2 PCS REAR BUMPER SIDE RETAINER		
10	1 PC REAR BUMPER REINFORCEMENT		
11	1 PC REAR BUMPER REINFORCEMENT SPONGE		
12	1 PC REAR LOWER BUMPER		
13	2 PCS REAR BUMPER REFLECTOR		
14	4 PCS REVERSE SENSORS		
15	1 PC EXHAUST PIPE		
16	2 PCS EXHAUST PIPE MOUNTING		
17	1 PC EXHAUST PIPE TOP SHIELD		
		0.00	0.00
	Special Net		
18	1 PC BOOT LID "WILDBOAR" STICKER	50.00	
19	1 SET REAR PANEL TRIM CLIPS	40.00	
20	1 PC REAR NUMBER PLATE	50.00	
21	1 SET REAR BUMPER CLIPS	60.00	
22	1 SET REAR LOWER BUMPER CLIPS	50.00	
23	1 PC REAR BUMPER TOP STAINLESS STEEL PLATE	200.00	
24	1 PC REAR WINDSCREEN SEAL	60.00	
25	1 PC REAR WINDSCREEN SEALANT	60.00	
		570.00	570.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200278
Date: 29 Aug 2022
Veh Reg No: SLH2986H
Make/Model: VOLKSWAGEN
TOURAN SPORT 1.4 TSI
AT 1T34C4
Chasis No: WVGZZZ1TZW043918
Reg. Date: 26/01/2011
Your Ref No: SKH938Y

Claim Type: Third Party
Accident Date: 26/08/2022
TP Veh Reg No: SKH938Y

Estimate Repair Cost to Vehicle No :SLH2986H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Labour			
26	1 TO CHECK WIRING	50.00	
27	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
28	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
29	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
30	1 TO REMOVE AND REFIT INNER TRIM	80.00	
31	1 TO SPRAY PANEL SEALANT	100.00	
32	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	180.00	
33	1 (REAR) TO SPRAY PAINTING	1,000.00	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,690.00	2,690.00
Others			
35	1 PC REAR TOOL TRAY		
		0.00	0.00
Total			S\$ 3,260.00
Add GST @ 7%			228.20
Total Amount Payable			<u>S\$ 3,488.20</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED EIGHTY EIGHT AND CENTS TWENTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE