

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Xiao Boy

Estimate : TP22-098

Date : 29/08/2022
Vehicle Num. : SKC881C
Make/Model : Volkswagen Golf-2019
Chassis/Eng# : WWWZZZAUZLW009296/CHH312054
Accident Date : 29/08/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Rear Bumper Assy <i>Distorted</i>		4,365.15 <i>1750</i>
2.	10 pcs	Rear Bumper Clips <i>new</i>	3.20	32.00 ✓
3.	2 pcs	Rear Bumper Side Holder L/R <i>Dmgd.</i>	58.40	116.80 ✓
4.	2 pcs	Rear Bumper Bracket L/R <i>Dmgd. Dmgd.</i>	55.15	110.30 ✓
5.	6 pcs	Rear Bumper PDC Parking Sensor	250.85	1,505.10 ✓
6.	1 pc	Rear Bumper Tow Hook Cover <i>Distorted</i>		32.65 ✓
7.	1 pc	Rear Bumper Lower Exhaust Guard Garnish <i>Deband</i>		326.75 ✓
8.	1 pc	Rear Bumper Centre Bracket <i>anched.</i>		148.13 ✓
9.	1 pc	Rear Bumper Reinforcement <i>Distorted</i>		585.95 ✓
10.	2 pcs	Rear No. Plate Lamp <i>Dmgd.</i>	66.58	133.16 ✓
11.	2 pcs	Rear Reflector Lamp L/R <i>anched.</i>	87.30	174.60 ✓
12.	1 pc	Rear End Panel <i>Distorted</i>		986.45 ✓
13.	2 pcs	Rear Lamp L/R <i>anched.</i>	498.10	996.20 ✓
14.	2 pcs	Rear Lamp Panel L/R <i>Dented.</i>	372.15	744.30 ✓ <i>1350</i>
15.	2 pcs	Rear Fender L/R <i>LH Distorted, RH Repair Distorted.</i>	1,832.85	3,665.70 <i>1532.85</i>
16.	2 pcs	Rear Fender Inner Upholstery Trim L/R <i>Distorted.</i>	396.65	793.30 ✓
17.	10 pcs	Rear Fender Inner Upholstery Trim Clips <i>new</i>	3.20	32.00 ✓
18.	1 pc	Rear End Panel Inner Top Garnish <i>Distorted</i>		216.05 ✓
19.	1 pc	Rear Spare Tyre Panel <i>Repair</i>		1,398.25 X ✓
20.	1 pc	Rear Sponge Tools Tray <i>Dmgd.</i>		90.52 ✓
21.	1 pc	Rear Tyre Panel Tray <i>Deband</i>		480.25 ✓
22.	1 pc	Rear Boot Lid Weatherstrip <i>at</i>		387.40 ✓
23.	1 pc	Rear Exhaust Silencer Box Assy <i>new</i>		1,458.85 X ✓
24.	1 pc	Rear PDC Sensor Wire Harness <i>at</i>		327.30 ✓
25.	1 pc	Rear Tailgate <i>Distorted.</i>		4,983.60 <i>1450</i>
26.	1 pc	Rear Tailgate Mechanism Lock <i>Jammed.</i>		381.62 ✓
27.	1 pc	Rear Tailgate Lock Hook <i>Dmgd.</i>		56.01 ✓
28.	2 pcs	Rear Tailgate Hinge L/R <i>Best</i>	153.65	307.30 ✓
29.	2 pcs	Rear Tailgate Damper Absorber L/R <i>Damaged</i>	171.50	343.00 ✓

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP22-098

Date : 29/08/2022

Vehicle Num. : SKC881C

Make/Model : Volkswagen Golf-2019

Chassis/Eng# : WWWZZZAUZLW009296/CHH312054

Accident Date : 29/08/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
30.	2 pcs	Rear Boot Lamp L/R <i>Cut</i>	518.10	1,036.20 ✓
31.	1 pc	Rear Tailgate 'Volkswagen' Logo <i>nee</i>		150.75 ✓
32.	1 pc	Rear Tailgate 'GTI' Emblem <i>nee</i>		121.65 ✓
33.	1 pc	Rear Wiper Motor Assy <i>Damaged</i>		399.45 ✓
34.	1 pc	Rear Wiper Arm <i>Cut</i>		78.65 ✓
35.	1 pc	Rear Wiper Blade		58.30 ✓
36.	1 pc	Rear Wiper Cover		28.45 ✓
37.	1 pc	Rear Windscreen <i>Shattered</i>		896.40 ✓
38.	3 pcs	Rear Windscreen Inner Side Garnish <i>Debond</i>	98.40	295.20 ✓
39.	1 pc	Rear Boot Lid Inner Trim Board <i>Distorted</i>		371.20 ✓
40.	1 pc	Rear Windscreen Heater Wire <i>nee</i>		28.90 ✓
41.	1 pc	Rear Boot Lid Toneau Cover <i>Debond</i>		531.70 ✓
42.	2 pcs	Rear Fender Inner Trim Garnish L/R <i>nee</i>	253.15	506.30 ✓
43.	2 pcs	Rear Door L/R <i>Repair</i>	1,988.45	3,976.90 ✓
44.	2 pcs	Rear Door Mechanism Lock L/R <i>nee</i>	456.75	913.50 ✓
45.	1 pc	Rear Reverse Camera <i>Distorted</i>		431.20 ✓
46.	2 pcs	Rear Boot Lid Inner Lamp Garnish L/R <i>nee</i>	73.10	146.20 ✓
47.	1 pc	Rear Boot Spoiler (Top) <i>Debond</i>		1,523.05 ✓
48.	2 pcs	Rear Boot Spoiler Side Guard Garnish L/R <i>nee</i>	373.95	747.90 ✓
49.	2 pcs	Rear Tailgate Stopper L/R <i>nee</i>	31.85	63.70 ✓
50.	2 pcs	Blindspot Monitor Sensor / Radar L/R <i>LH cut</i>	1,271.65	2,543.30 ✓ <i>1271.65</i>
51.	2 pcs	Blindspot Monitor Radar Wire Harness <i>nee</i>	272.30	544.60 ✓
52.	1 pc	Frt Bonnet <i>Repair</i>		1,581.35 ✓
53.	1 pc	Frt Bonnet Mechanism Lock <i>nee</i>		261.45 ✓
54.	2 pcs	Frt Bonnet Hinge L/R <i>nee</i>	86.65	173.30 ✓
55.	2 pcs	Bonnet Damper L/R <i>nee</i>	135.45	270.90 ✓
56.	1 pc	Headlamp Assy LH <i>nee</i>		2,135.25 ✓
57.	1 pc	Headlamp Bracket LH <i>nee</i>		58.45 ✓
58.	1 pc	Frt Grille Assy <i>nee</i>		651.38 ✓
59.	1 pc	Frt Bumper Assy <i>Debond</i>		1,238.50 ✓ <i>1080</i>
60.	1 pc	Frt Bumper Side Holder LH <i>nee</i>		36.55 ✓

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP22-098

Date : 29/08/2022
Vehicle Num. : SKC881C
Make/Model : Volkswagen Golf-2019
Chassis/Eng# : WWWZZZAUZLW009296/CHH312054
Accident Date : 29/08/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
61.	1 pc	Frt Bumper Bracket LH		49.65
62.	1 pc	Frt Bumper Inner Sponge		54.05
63.	1 pc	Frt Bumper Reinforcement		588.50
64.	2 pcs	Frt Bumper PDC Sensor LH	258.85	517.70
65.	1 pc	Air Bag Sensor		532.05
66.	1 pc	Air Bag ECU		1,472.00
67.	1 pc	Driver Seatbelt RH		1,356.95
68.	1 pc	Passenger Seatbelt LH		1,356.95
69.	1 pc	Rear Wheel House LH		2,433.75
70.	1 pc	Rear Dyna Audio Subwoofer Box		2,453.54
71.	1 pc	Tyre Panel Upholstery Trim		760.17
72.	1 pc	Rear Camera Powerbank		1,424.64
73.	2 pcs	Rear Blindspot Monitor ECU	1,384.72	2,769.44
74.	2 pcs	Rear Inner Lamp Panel Shell	510.75	1,021.50
75.	2 pcs	Rear Lamp Panel Lower Extension Panel	372.10	744.20
76.	1 pc	Rear Wheelhouse Lower Extension Panel LH		384.56
77.	2 pcs	Rear Fender Inner Lower Air Duct	160.70	321.40
78.	1 pc	Rear Tyre Panel Side Extension Panel		211.58
79.	5 pcs	Rear PDC Parking Sensor Bracket Holder	87.10	435.50
80.	1 pc	Rear Third Brake Lamp		150.00
81.	1 pc	Rear Wheelhouse Shell Panel LH		698.10
		Control Unit for Electronic Regulated Pumping		1807.50
		List Total S\$:		60,715.55
		10.00% Discount S\$:		6,071.56
				54,643.99
		SPECIAL NETT ITEMS :		
1.	1 pc	Guitar		680.00
2.	1 pc	Battery		350.00
3.	1 pc	Windscreen Sealant		40.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP22-098

Date : 29/08/2022
 Vehicle Num. : SKC881C
 Make/Model : Volkswagen Golf-2019
 Chassis/Eng# : WVVZZZAUZLW009296/CHH312054
 Accident Date : 29/08/2022
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	2 sets	Frt & Rear No. Plate w/frame	45.00	90.00
5.	1 pc	Rear Boot Cargo Netting		195.00
6.	1 pc	Rear Road Camera		480.00
Special Nett Total S\$:				1,835.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				250.00
To remove, replace rear windscreen.				350.00
To remove, replace & transfer rear boot lid components.				300.00
To remove, reinstal upholstery, inner trim garnishes.				480.00
To remove, replace exhaust silencer, realign pipe line.				360.00
To remove, replace seatbelts to change & reprogram ECU				550.00
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				5,800.00
To putty & respray painting on rear boot lid, rear bumper, end panel, tyre panel, rear fender L/R, rear door L/R, rear lamp panel L/R, frt bonnet and bumper.				4,200.00
C2S coating.				600.00
Towing from TP compound to workshop (King Trolley)				250.00
Labour Total S\$:				13,140.00

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 69,618.99

total: 37021.25

1/81 29.6k

18 Days