

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 29.08.2022

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNF3600B**
MODEL : **TOYOTA LEXUS ES 250**
DATE OF ACCIDENT : 14.08.2022
TIME OF ACCIDENT : 12:30HRS

JTHBJ/GG402/02824

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 1,218.00	\$ 1,218.00
2	REAR BUMPER SIDE RETAINER (FRONT) <i>could LH</i>	2	\$ 135.20	\$ 270.40
3	REAR BUMPER SIDE RETAINER (REAR) <i>could</i>	2	\$ 170.80	\$ 341.60
4	REAR BUMPER SPONGE <i>could</i>	1	\$ 159.50	\$ 159.50
5	REAR FENDER INNER COWLING <i>new</i>	2	\$ 284.90	\$ 569.80
6	TAIL LAMP <i>lit</i>	1	\$ 672.90	\$ 672.90
7	TAIL LAMP LOWER BRACKET <i>new</i>	1	\$ 85.70	\$ 85.70
8	REAR FENDER LH <i>Regr</i>	1	\$ 2,316.00	\$ 2,316.00
9	REAR FENDER AIR VENT LH <i>new</i>	1	\$ 86.70	\$ 86.70
10	REAR FENDER AIR VENT COVER GARNISH LH <i>Rehd</i>	1	\$ 89.00	\$ 89.00
11	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 187.00	\$ 187.00
12	REAR BLINDSPOT SENSOR LH <i>could</i>	1	\$ 1,683.90	\$ 1,683.90
13	REAR BLINDSPOT SENSOR WIRE HARNESS <i>new</i>	1	\$ 461.70	\$ 461.70
14	REVERSE SENSOR <i>3 new</i>	2	\$ 397.80	\$ 795.60
15	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 28.60	\$ 114.40

TOTAL PRICE \$ 9,052.20
LESS 10% \$ 905.22
SUB TOTAL PRICE \$ 8,146.98

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER DIFFUSER (SPECAIL TYPE) <i>could</i>	1	\$ 1,500.00	\$ 1,500.00
3	REAR FENDER SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
4	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNF3600B**
MODEL : **TOYOTA LEXUS ES 250**
DATE OF ACCIDENT : **14.08.2022**
TIME OF ACCIDENT : **12:30HRS**

5	REAR FENDER INNER TRIM CLIP (SET) <i>pen</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	TAIL LAMP CLIP (SET) <i>pen</i>	1	\$ 30.00	\$ 30.00	<i>10</i>

TOTAL \$ 1,860.00 *840*

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>500</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>600</i>
3	TUFF COAT	\$ 100.00	<i>40</i>
4	WIRING BULB CHECKING	\$ 120.00	<i>30</i>
5	REMOVE & REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	RESET BLIND STOP SYSTEM	\$ 800.00	<i>400</i>
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$ 3,680.00 *1620*

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,006.98
TOTAL LABOUR COST : \$ 3,680.00
TOTAL REPAIR COST : \$ 13,686.98

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian S
4/5 30/08/22
05kps

total: 5993.67
4/5: 4.81c