

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 02 Sep 2022

Preliminary Advice

Vehicle No	: SLT7447B	Accident Date	: 26/08/2022
Make	: VOLKSWAGEN POLO	Policy No.	: SP2002390510-01
Assignment Date	: 02/09/2022	Excess	: S\$600.00
Date of Inspection	: 2/9/2022	Est. Duration of Repair	: 5
Inspection At	: TAN LIM MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,914.90
Revised Amount	:S\$	4,826.70
Check Items (Estimated)	:S\$	885.50
Total	:S\$	5,712.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	25,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,045.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .