



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD027082022
Policy No:	SP2002390510-01	Date of Loss:	26/08/2022
Vehicle Reg. No.:	SLT7447B	Driveable?	NO
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Muhammad Syafiq Bin Azman		
Driver:	Muhammad Syafiq Bin Azman		
Make/Model:	VOLKSWAGEN POLO, 1.4 (A)	Vehicle Reg. Date:	26/07/2010
Vehicle Colour:	Grey	Gen Condition:	Excellent
Engine No:	CGG337922	Chassis No:	WVWZZZ6RZAU060030
Odometer:	148946 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

not authorized here means 2/9/22 excess \$600 5 days. 4/5/22 the job after 12pm.

COST OF CLAIMS

	Amount
Parts	5,234.90
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	800.00
Towing	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Calculated Gross Total (\$\$)	6,914.90	
- Excess (\$\$)	600.00	
	(\$\$)	6,314.90
+ GST 7.00% (\$\$)	442.04	
Nett Amount (\$\$)	6,756.94	

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2022)
Parts: 144 VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*front bumper <i>Dis</i>	0.00	0.00	*650.00 F <i>—</i>
2	8		*front bumper clips <i>nee</i>	0.00	0.00	*12.00 F <i>—</i>
3	2		*front bumper side retainer	0.00	0.00	*170.00 F <i>7</i>
4	1		*front bumper center grille <i>To.1</i>	0.00	0.00	*110.00 F <i>—</i>
5	2		*front bumper side grille <i>Cur/Mys</i>	0.00	0.00	*90.00 F <i>—</i>
6	2		*headlamp <i>3rd</i>	0.00	0.00	*440.00 F <i>—</i>
7	1		*bonnet <i>Buc</i>	0.00	0.00	*550.00 F <i>—</i>
8	1		*front bumper lower lip <i>Cur n/c</i>	0.00	0.00	*65.00 F <i>X</i>
9	1		*front grille assy <i>Cur</i>	0.00	0.00	*265.00 F <i>—</i>
10	1		*front grille emblem <i>Cur</i>	0.00	0.00	*70.00 F <i>—</i>
11	1		*front grille R emblem <i>NZ Ass</i>	0.00	0.00	*25.00 F <i>X</i>
12	2		*bonnet hinge <i>N</i>	0.00	0.00	*140.00 F <i>X</i>
13	1		*bonnet open lever <i>11</i>	0.00	0.00	*45.00 F <i>X</i>
14	1		*bonnet lock	0.00	0.00	*120.00 F <i>?</i>
15	2		*front fender <i>N/S Buc o/s n</i>	0.00	0.00	*600.00 F <i>1pc</i>
16	2		*front fender inner cowling <i>n</i>	0.00	0.00	*220.00 F <i>X</i>
17	8		*front fender inner cowling clips <i>11</i>	0.00	0.00	*12.00 F <i>X</i>
18	2		*front fender emblem <i>NZ Ass</i>	0.00	0.00	*50.00 F <i>X</i>
19	1		*front support panel <i>Cur</i>	0.00	0.00	*500.00 F <i>—</i>
20	1		*aircon condenser	0.00	0.00	*275.00 F <i>?</i>
21	2		*aircon air guide <i>To.1</i>	0.00	0.00	*30.00 F <i>—</i>
22	1		*radiator assy	0.00	0.00	*240.00 F <i>?</i>
23	2		*headlamp panel <i>Buc</i>	0.00	0.00	*80.00 F <i>—</i>

F=Franchise part.

Sub Total (S\$) **4,759.00**
 + Margin on L,N Items 10.00% (S\$) **475.90**

Total Parts (S\$) 5,234.90

Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New	700 800.00
Labour Items			
2	To check electrical lighting concerned.	New	20 60.00
3	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New	100 120.00
4	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	600 700.00
Gross Labour Cost (S\$)			1,680.00

Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1 Defu Lane 6 Singapore 539365
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

This claim is handled by: LAM WEI SHONG

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*