

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT 7447B  
Tanhuan

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

600k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

30

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

3000

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 28955

Date / Time

Action / Instruction

Completed 28-07-2030  
ABS light on

Veh No:

SLT 7447B

Yr Regn:

26/07/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen Polo

c.c

1390

Colour

multi colour

A/C:

Insured / Std / NI / NA

Sp. Reading

148947

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ6RZAU060030

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/45-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/08/22

D.O.I.

2/9/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 26/10 2022

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

MER-00

Lump Sum / L.B.T: (\$

4050

22/10/22 4/5 @ 4050 informed MR Tan. (Red @ 2945.30, 42%)



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                               |                              |                       |                   |
|-------------------------------|------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)              | Ref. No:              | OD027082022       |
| Policy No:                    | SP2002390510-01              | Date of Loss:         | 26/08/2022        |
| Vehicle Reg. No.:             | SLT7447B                     | Driveable?            | NO                |
| Driver Age/Info:              |                              | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                           | Third Party Involved? | YES               |
| Insured/Claimant:             | Muhammad Syafiq Bin Azman    |                       |                   |
| Driver:                       | Muhammad Syafiq Bin Azman    |                       |                   |
| Make/Model:                   | VOLKSWAGEN POLO, 1.4 (A)     | Vehicle Reg. Date:    | 26/07/2010        |
| Vehicle Colour:               | Grey                         | Gen Condition:        | Excellent         |
| Engine No:                    | CGG337922                    | Chassis No:           | WVWZZZ6RZAU060030 |
| Odometer:                     | 148946 KM                    |                       |                   |
| Paint Type:                   |                              |                       |                   |
| Total Loss?                   | NO                           |                       |                   |
| Est. Duration of Repair (day) | 10                           |                       |                   |
| Present Location:             | TAN LIM MOTOR PTE LTD (DEFU) |                       |                   |

*Handwritten notes:*  
not Authorized here means 2/5/22 excess \$600 5 days. 4080 1/55 after the repair.

**COST OF CLAIMS**

|                     | Amount   |
|---------------------|----------|
| Parts               | 5,234.90 |
| Miscellaneous Items | 0.00     |
| Labour              | 880.00   |
| Paintwork Labour    | 800.00   |
| Towing              | 0.00     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|                             |          |
|-----------------------------|----------|
| Calculated Gross Total (\$) | 6,914.90 |
| - Excess (\$)               | 600.00   |
| (S\$)                       | 6,314.90 |
| + GST 7.00% (\$)            | 442.04   |
| Nett Amount (\$)            | 6,756.94 |

This claim is handled by: LAM WEI SHONG

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 01 Sep 2022)  
**Parts:** 144      VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                                  | %Disc | %Depr | Amount               |
|-----|-----|----------|----------------------------------------------|-------|-------|----------------------|
| 1   | 1   |          | *front bumper <i>Dis</i>                     | 0.00  | 0.00  | *650.00 F <i>—</i>   |
| 2   | 8   |          | *front bumper clips <i>dis</i>               | 0.00  | 0.00  | *12.00 F <i>—</i>    |
| 3   | 2   |          | *front bumper side retainer <i>Surf/cnr</i>  | 0.00  | 0.00  | *170.00 F <i>—</i>   |
| 4   | 1   |          | *front bumper center grille <i>To.1</i>      | 0.00  | 0.00  | *110.00 F <i>—</i>   |
| 5   | 2   |          | *front bumper side grille <i>Cnr/MJ</i>      | 0.00  | 0.00  | *90.00 F <i>—</i>    |
| 6   | 2   |          | *headlamp <i>3rd</i>                         | 0.00  | 0.00  | *440.00 F <i>—</i>   |
| 7   | 1   |          | *bonnet <i>Suc</i>                           | 0.00  | 0.00  | *550.00 F <i>—</i>   |
| 8   | 1   |          | *front bumper lower lip <i>Cnr d/c</i>       | 0.00  | 0.00  | *65.00 F <i>X</i>    |
| 9   | 1   |          | *front grille assy <i>Cnr</i>                | 0.00  | 0.00  | *265.00 F <i>—</i>   |
| 10  | 1   |          | *front grille emblem <i>Cnr</i>              | 0.00  | 0.00  | *70.00 F <i>—</i>    |
| 11  | 1   |          | *front grille R emblem <i>NZ ASS</i>         | 0.00  | 0.00  | *25.00 F <i>X</i>    |
| 12  | 2   |          | *bonnet hinge <i>N</i>                       | 0.00  | 0.00  | *140.00 F <i>X</i>   |
| 13  | 1   |          | *bonnet open lever <i>11</i>                 | 0.00  | 0.00  | *45.00 F <i>X</i>    |
| 14  | 1   |          | *bonnet lock <i>twi</i>                      | 0.00  | 0.00  | *120.00 F <i>?</i>   |
| 15  | 2   |          | *front fender <i>N/S Suc o/s n</i>           | 0.00  | 0.00  | *600.00 F <i>1pc</i> |
| 16  | 2   |          | *front fender inner cowlings <i>11</i>       | 0.00  | 0.00  | *220.00 F <i>X</i>   |
| 17  | 8   |          | *front fender inner cowlings clips <i>11</i> | 0.00  | 0.00  | *12.00 F <i>X</i>    |
| 18  | 2   |          | *front fender emblem <i>NZ ASS</i>           | 0.00  | 0.00  | *50.00 F <i>X</i>    |
| 19  | 1   |          | *front support panel <i>Cnr</i>              | 0.00  | 0.00  | *500.00 F <i>—</i>   |
| 20  | 1   |          | *aircon condenser <i>Surf/pur</i>            | 0.00  | 0.00  | *275.00 F <i>?</i>   |
| 21  | 2   |          | *aircon air guide <i>To.1</i>                | 0.00  | 0.00  | *30.00 F <i>—</i>    |
| 22  | 1   |          | *radiator assy <i>Surf/pur</i>               | 0.00  | 0.00  | *240.00 F <i>?</i>   |
| 23  | 2   |          | *headlamp panel <i>Suc</i>                   | 0.00  | 0.00  | *80.00 F <i>—</i>    |

F=Franchise part.

Sub Total (S\$) 4,759.00  
 + Margin on L,N Items 10.00% (S\$) 475.90

Total Parts (S\$) 5,234.90

Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

7-3902  
 2-3975  
 102  
 4372.50  
 1420  
 5792.2  
 3998.  
 1792.50  
 32  
 4054.



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                             | Particulars                                                                                                             | Lab.Type | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------|----------|-----------------|
| <b>Paintwork Labour</b>        |                                                                                                                         |          |                 |
| 1                              | Putty and spray painting of the affected portion.                                                                       | New      | 700 800.00      |
| <b>Labour Items</b>            |                                                                                                                         |          |                 |
| 2                              | To check electrical lighting concerned.                                                                                 | New      | 20 60.00        |
| 3                              | To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.                                       | New      | 100 120.00      |
| 4                              | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | New      | 600 700.00      |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                         |          | <b>1,680.00</b> |

Tan Lim Motor Pte Ltd/SLT7447B/01/09/2022 15:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

1420

< END OF ESTIMATES >

1 Defu Lane 6 Singapore 539365  
Tel : 6858 5151 (24 hours) Fax : 6858 0877  
email@tlmotor.com.sg www.tlmotor.com.sg  
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 10 Sep 2022)  
**Parts:** 144      VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Tan Lim Motor Pte Ltd/SLT7447B/10/09/2022 14:20  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No.                                 | Qty | Part No. | Particulars       | %Disc | %Depr | Amount               |
|-------------------------------------|-----|----------|-------------------|-------|-------|----------------------|
| 1                                   | 1   |          | *main fuse socket | 0.00  | 0.00  | <i>Daye</i> *73.00 F |
| Sub Total (\$\$)                    |     |          |                   |       |       | 73.00                |
| + Margin on L,N Items 10.00% (\$\$) |     |          |                   |       |       | 7.30                 |
| Total Parts (\$\$)                  |     |          |                   |       |       | 80.30                |

Tan Lim Motor Pte Ltd/SLT7447B/10/09/2022 14:20. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS