

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 12.09.2022

TO : AXA MOTOR CLAIMS DEPTS  
VEHICLE NO : SMZ9869K  
MODEL : HONDA FIT  
DATE OF ACCIDENT : 31.08.2022  
TIME OF ACCIDENT : 20:45HRS

GR11028869  
Xiao Tony.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                   | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-----------------------------------------------|-----|-----------------|------------------|
| 1   | REAR BUMPER <i>Rehd</i>                       | 1   | \$ 708.20       | \$ 708.20        |
| 2   | REAR BUMPER REFLECTOR <i>new</i>              | 2   | \$ 40.30        | \$ 80.60         |
| 3   | REAR BUMPER REVERSE SENSOR <i>Rehd</i>        | 2   | \$ 228.40       | \$ 456.80        |
| 4   | REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>  | 4   | \$ 38.50        | \$ 154.00        |
| 5   | REAR BUMPER INNER ABSORBER BRACKET <i>new</i> | 2   | \$ 22.30        | \$ 44.60         |
| 6   | REAR BUMPER SIDE RETAINER <i>Rehd</i>         | 2   | \$ 18.70        | \$ 37.40         |
| 7   | TAIL GATE <i>Rehd</i>                         | 1   | \$ 1,035.80     | \$ 1,035.80      |
| 8   | TAIL GATE LAMP <i>new</i>                     | 2   | \$ 367.20       | \$ 734.40        |
| 9   | TAIL GATE EMBLEM 'FIT' <i>new</i>             | 1   | \$ 30.80        | \$ 30.80         |
| 10  | TAIL GATE INNER HOLDER <i>new</i>             | 1   | \$ 16.90        | \$ 16.90         |
| 11  | TAIL GATE OUTER GARNISH <i>new</i>            | 1   | \$ 381.20       | \$ 381.20        |
| 12  | TAIL GATE STOPPER <i>new</i>                  | 2   | \$ 17.20        | \$ 34.40         |
| 13  | TAIL GATE INNER LOCK <i>Rehd</i>              | 1   | \$ 153.80       | \$ 153.80        |
| 14  | TAIL GATE LOCK CATCH <i>new</i>               | 1   | \$ 24.30        | \$ 24.30         |
| 15  | TAIL GATE WEATHER STRIP <i>lit</i>            | 1   | \$ 76.50        | \$ 76.50         |
| 16  | TAIL GATE DETECTOR <i>new</i> <i>cancel</i>   | 1   | \$ 74.20        | \$ 74.20         |
| 17  | TAIL GATE BUZZER <i>cancel</i>                | 1   | \$ 79.80        | \$ 79.80         |
| 18  | TAIL GATE WINDSCREEN MOULDING <i>new</i>      | 2   | \$ 149.20       | \$ 298.40        |
| 19  | TAIL LAMP <i>cancel</i>                       | 2   | \$ 471.90       | \$ 943.80        |
| 20  | REAR FENDER INNER COWLING <i>new</i>          | 2   | \$ 89.40        | \$ 178.80        |
| 21  | REAR FENDER INNER TRIM <i>new</i>             | 2   | \$ 437.20       | \$ 874.40        |
| 22  | REAR END PANEL <i>Rehd</i>                    | 1   | \$ 529.40       | \$ 529.40        |
| 23  | REAR END PANEL TOP GARNISH <i>Rehd</i>        | 1   | \$ 61.50        | \$ 61.50         |
| 24  | REAR FLOOR PANEL TOP BOARD <i>Rehd</i>        | 1   | \$ 290.40       | \$ 290.40        |

598

x.

✓

< 100

x

✓

✓

x.

✓

x.

x.

x.

✓

x

✓

x

✓

✓

✓

x

x

✓

✓

✓

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMZ9869K  
 MODEL : HONDA FIT  
 DATE OF ACCIDENT : 31.08.2022  
 TIME OF ACCIDENT : 20:45HRS

|    |                                          |   |           |           |
|----|------------------------------------------|---|-----------|-----------|
| 25 | REAR TOOLS COMPARTMENT SPONGE <i>Pen</i> | 1 | \$ 294.60 | \$ 294.60 |
|----|------------------------------------------|---|-----------|-----------|

TOTAL PRICE \$ 7,595.00  
 LESS 20% \$ 1,519.00  
**SUB TOTAL PRICE \$ 6,076.00**

488780  
 3910.24

| S/N | DESCRIPTION                                     | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|-------------------------------------------------|-----|-------------|--------------|
| 1   | REAR BUMPER CLIP (SET) <i>new</i>               | 1   | \$ 80.00    | \$ 80.00     |
| 2   | TAIL GATE SEALANT <i>new</i>                    | 1   | \$ 80.00    | \$ 80.00     |
| 3   | TAIL GATE INNER TRIM CLIP (SET) <i>new</i>      | 1   | \$ 60.00    | \$ 60.00     |
| 4   | TAIL GATE WINDSCREEN SEALANT <i>green</i>       | 1   | \$ 80.00    | \$ 80.00     |
| 5   | TAIL GATE WINDSCREEN INNER SEAL <i>green</i>    | 1   | \$ 60.00    | \$ 60.00     |
| 6   | REAR FENDER INNER COWLING CLIP (SET) <i>new</i> | 1   | \$ 60.00    | \$ 60.00     |
| 7   | REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>   | 1   | \$ 60.00    | \$ 60.00     |
| 8   | REAR END PANEL INSULATION SEAL <i>new</i>       | 1   | \$ 120.00   | \$ 120.00    |
| 9   | REAR END PANEL TOP GARNISH CLIP <i>new</i>      | 1   | \$ 60.00    | \$ 350.00    |

30.  
 +  
 30  
 30  
 30  
 +  
 +  
 60.  
 10

150

**TOTAL \$ 950.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                                | PRICE       | ADJUSTED COST |
|-----|--------------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                     | \$ 1,500.00 | 80            |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                   | \$ 1,400.00 | 80            |
| 3   | TUFF COAT                                                                      | \$ 120.00   | 60            |
| 4   | WIRING CHECK                                                                   | \$ 100.00   | 30            |
| 5   | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR | \$ 150.00   | 60-           |
| 6   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                           | \$ 80.00    | 50            |
| 7   | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                           | \$ 80.00    | 50            |
| 8   | REMOVE AND VIDEO FOOTAGE AND DISTANCE SETTING                                  | \$ 80.00    | 50            |
| 9   | REMOVE AND REFIX TAILGATE WINDSCREEN                                           | \$ 120.00   | ✓             |

TO : AXA MOTOR CLAIMS DEPTS  
VEHICLE NO : SMZ9869K  
MODEL : HONDA FIT  
DATE OF ACCIDENT : 31.08.2022  
TIME OF ACCIDENT : 20:45HRS

|    |                                                                                                |           |     |
|----|------------------------------------------------------------------------------------------------|-----------|-----|
| 10 | TRANSFER TAILGATE MECHANISM                                                                    | \$ 80.00  | ✓   |
| 11 | SPECIAL COATING                                                                                | \$ 880.00 | 400 |
| 12 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 120.00 | x   |

2500

TOTAL \$ 4,710.00

Adnan L

2/s 13/09/22.  
06hys

#### ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,026.00  
TOTAL LABOUR COST : \$ 4,710.00  
TOTAL REPAIR COST : \$ 11,736.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6600.24  
2/s : 5250