

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 12.09.2022

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMZ9869K**
MODEL : HONDA FIT
DATE OF ACCIDENT : 31.08.2022
TIME OF ACCIDENT : 20:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 708.20	\$ 708.20
2	REAR BUMPER REFLECTOR	2	\$ 40.30	\$ 80.60
3	REAR BUMPER REVERSE SENSOR	2	\$ 228.40	\$ 456.80
4	REAR BUMPER REVERSE SENSOR HOLDER	4	\$ 38.50	\$ 154.00
5	REAR BUMPER INNER ABSORBER BRACKET	2	\$ 22.30	\$ 44.60
6	REAR BUMPER SIDE RETAINER	2	\$ 18.70	\$ 37.40
7	TAIL GATE	1	\$ 1,035.80	\$ 1,035.80
8	TAIL GATE LAMP	2	\$ 367.20	\$ 734.40
9	TAIL GATE EMBLEM 'FIT'	1	\$ 30.80	\$ 30.80
10	TAIL GATE INNER HOLDER	1	\$ 16.90	\$ 16.90
11	TAIL GATE OUTER GARNISH	1	\$ 381.20	\$ 381.20
12	TAIL GATE STOPPER	2	\$ 17.20	\$ 34.40
13	TAIL GATE INNER LOCK	1	\$ 153.80	\$ 153.80
14	TAIL GATE LOCK CATCH	1	\$ 24.30	\$ 24.30
15	TAIL GATE WEATHER STRIP	1	\$ 76.50	\$ 76.50
16	TAIL GATE DETECTOR	1	\$ 74.20	\$ 74.20
17	TAIL GATE BUZZER	1	\$ 79.80	\$ 79.80
18	TAIL GATE WINDSCREEN MOULDING	2	\$ 149.20	\$ 298.40
19	TAIL LAMP	2	\$ 471.90	\$ 943.80
20	REAR FENDER INNER COWLING	2	\$ 89.40	\$ 178.80
21	REAR FENDER INNER TRIM	2	\$ 437.20	\$ 874.40
22	REAR END PANEL	1	\$ 529.40	\$ 529.40
23	REAR END PANEL TOP GARNISH	1	\$ 61.50	\$ 61.50
24	REAR FLOOR PANEL TOP BOARD	1	\$ 290.40	\$ 290.40
25	REAR TOOLS COMPARTMENT SPONGE	1	\$ 294.60	\$ 294.60

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMZ9869K**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 31.08.2022
 TIME OF ACCIDENT : 20:45HRS

TOTAL PRICE	\$	7,595.00
LESS 20%	\$	1,519.00
SUB TOTAL PRICE	\$	6,076.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
2	TAIL GATE SEALANT	1	\$ 80.00	\$ 80.00
3	TAIL GATE INNER TRIM CLIP (SET)	1	\$ 60.00	\$ 60.00
4	TAIL GATE WINDSCEEN SEALANT	1	\$ 80.00	\$ 80.00
5	TAIL GATE WINDSCEEN INNER SEAL	1	\$ 60.00	\$ 60.00
6	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00
7	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 60.00	\$ 60.00
8	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ 120.00
9	REAR END PANEL TOP GARNISH CLIP	1	\$ 60.00	\$ 350.00

TOTAL \$ 950.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,500.00	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	
3	TUFF COAT	\$ 120.00	
4	WIRING CHECK	\$ 100.00	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 150.00	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	
8	REMOVE AND VIDEO FOOATGE AND DISTANCE SETTING	\$ 80.00	
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMZ9869K**
MODEL : HONDA FIT
DATE OF ACCIDENT : 31.08.2022
TIME OF ACCIDENT : 20:45HRS

11	SPECIAL COATING	\$ 880.00	
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 120.00	

TOTAL \$ 4,710.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,026.00
TOTAL LABOUR COST : \$ 4,710.00
TOTAL REPAIR COST : \$ 11,736.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787