

ASS. REC. BY:

REF:

A/G 22008580/K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 26,646.42

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 300T

Yr Regn:

02 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

718704

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1AB215AUC 282353

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NIT / S/Rim / STD A/Rim or

Tyre Size:

F: 175/80R16

R: Pailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

27/10/22

D.O.I.

30/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body & R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Await for BV

Recommend TILoss. Bal \$ 5952.00

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Fines

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authored
C/Rep S

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

AAD2208-

Vehicle No.:
Chassis No.:
UEN No:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

30 AUG 2022

SHD300T

VF1ABL15AUC282353

200303878K

RENAULT

LATITUDE

27/08/2022

SLA6014Z/AIG

04/02/2016

PART	LIST
1 BUMPER COVER FRT	\$ <i>mit</i> 747.20 ✓
1 BUMPER UNDERTRAY FRT	\$ <i>mit</i> 292.50 ✓
1 BUMPER SPOILER FRT	\$ <i>mit</i> 344.70 ✓
1 BUMPER BEAM FRT	\$ <i>R</i> 663.70 ✓
1 BUMPER ABSORBER FRT	\$ <i>mit</i> 394.68 ✓
1 BUMPER BRACKET KIT FRT LH	\$ <i>mit</i> 101.40 ✓
1 BUMPER RETAINER FRT LH	\$ <i>CM</i> 101.40 ✓
1 BUMPER BRACKET KIT FRT RH	\$ <i>mit</i> 101.40 ✓
1 BUMPER RETAINER FRT RH	\$ <i>CM</i> 101.40 ✓
1 BUMPER SUPPORT FRT	\$ <i>mit</i> 10.70 ✓
1 BUMPER BRACKET FRT LH (Headlamp Lower)	\$ <i>CM</i> 116.47 ✓
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$ <i>CM</i> 116.47 ✓
1 HEADLAMP PANEL FRT LH	\$ <i>Bu</i> 128.30 ✓
1 HEADLAMP PANEL FRT RH	\$ <i>Bu</i> 128.30 ✓
1 BUMPER GRILLE LOWER FRT	\$ <i>mit</i> 147.00 ✓
1 BUMPER FOG LAMP GRILLE LH	\$ <i>mit</i> 207.21 ✓
1 BUMPER FOG LAMP GRILLE RH	\$ <i>mit</i> 207.21 ✓
1 A/C CONDENSER	\$ <i>R</i> 1,537.80 ✓
1 RADIATOR	\$ <i>R</i> 871.20 ✓
1 STEERING PUMP ELECTRIC	\$ 2,026.70 ?
1 TOW COVER FRT	\$ <i>mit</i> 60.90 ✓
1 FENDER PANEL FRT LH	\$ <i>R</i> 437.10 ✓
1 FENDER PANEL FRT RH	\$ <i>R</i> 437.10 ✓
1 WHEELARCH FRT RH	\$ <i>T</i> 191.40 ✓
1 WHEELARCH FRT LH	\$ <i>mit</i> 191.40 ✓
1 BUMPER UNDERTRAY FRT	\$ 292.50 ?

Trans-cab Auto Services Pte Ltd**AAD2208-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

1 RADIATOR GRILLE	\$	<i>mt</i>	969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>mt</i>	225.36	✓
1 RADIATOR GRILLE FRAME	\$	<i>cm</i>	686.00	✓
1 FRAME FULL SUPPORT PANEL	\$	<i>cm</i>	592.70	✓
1 BONNET	\$	<i>Bj</i>	1,312.70	✓
1 BONNET INSULATOR	\$	<i>Deform</i>	294.30	✓
1 BONNET HINGE LH	\$	<i>rc</i>	237.40	X
1 BONNET HINGE RH	\$	<i>rc</i>	237.40	X
1 BONNET LOCK	\$	<i>Dir</i>	152.80	✓
1 HORN	\$	<i>Pl</i>	449.90	X
1 WIPER RESERVOIR	\$	<i>Sm</i>	179.60	X
1 HEADLAMP LH	\$	<i>mt, cat</i>	743.60	✓
1 HEADLAMP RH	\$	<i>" "</i>	743.60	✓
1 WINDSCREEN FRT	\$	<i>cm</i>	817.20	✓
1 PASSENGER AIRBAG	\$	<i>Burn</i>	2,093.60	✓
1 STEERING AIRBAG	\$	<i>" "</i>	1,592.90	✓
1 AIRBAG COMPUTER	\$	<i>rec</i>	1,213.90	✓
1 AIRBAG SENSOR	\$	<i>rec</i>	502.90	✓
1 SEATBELT LH	\$	<i>Tr</i>	1,488.70	✓
1 SEATBELT RH	\$	<i>Tr</i>	1,553.10	✓
1 FENDER PANEL FRT LH	\$	<i>Panels</i>	437.10	X
1 WHEELARCH FRT LH	\$	<i>" "</i>	191.40	X
1 FENDER PANEL FRT RH	\$	<i>" "</i>	437.10	X
1 WHEELARCH FRT RH	\$	<i>" "</i>	191.40	X
1 FENDER PANEL REAR RH	\$	<i>rc</i>	1,933.20	^
1 WHEELARCH REAR RH	\$	<i>Sm</i>	275.40	X
1 DOOR PANEL FRT RH	\$	<i>Bj</i>	2,844.66	✓
1 DOOR WEATHERSTRIP FRT RH	\$	<i>Pl</i>	410.27	} X
1 DOOR HANDLE OUTER FRT RH	\$	<i>Sm</i>	477.76	
1 DOOR HANDLE MODULE FRT RH	\$	<i>Sm</i>	133.60	
1 DOOR REGULATOR FRT RH	\$	<i>Sm</i>	505.19	
1 DOOR REGULATOR MOTOR FRT RH	\$	<i>Sm</i>	796.46	
1 DOOR HINGE UPPER FRT RH	\$	<i>rc</i>	261.28	
1 DOOR HINGE LOWER FRT RH	\$	<i>rc</i>	300.55	
1 DOOR PANEL REAR RH	\$	<i>rc</i>	2,844.66	
1 DOOR WEATHERSTRIP REAR RH	\$	<i>Sm</i>	311.60	}
1 DOOR HANDLE MODULE REAR RH	\$	<i>Sm</i>	133.40	
1 DOOR HANDLE OUTER REAR RH	\$	<i>Sm</i>	42.10	

Trans-cab Auto Services Pte Ltd

AAD2208-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

1 DOOR REGULATOR REAR RH	\$	<i>Pm</i>	450.60	X
1 DOOR REGULATOR MOTOR REAR RH	\$	<i>Pm</i>	758.10	X
1 DOOR HINGE UPPER REAR RH	\$	<i>Re</i>	241.60	X
1 DOOR HINGE LOWER REAR RH	\$	<i>n</i>	169.90	X
	\$		16,781.40	
10%	\$		1,678.14	
	\$		15,103.26	

Special Nett

1 FRT DOOR ADVERTISEMENT	\$	<i>na</i>	200.00	<i>1201 na</i>
1 RR DOOR ADVERTISEMENT	\$	<i>na</i>	200.00	<i>1205 na</i>
1 DOOR TRIM CLIP	\$	<i>na</i>	70.00	X
1 DOOR SEAL CLIP	\$	<i>na</i>	65.00	X
1 DOOR MOULDING CLIP	\$	<i>na</i>	70.00	X
1 DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>605 na</i>
1 DOOR STICKER 65553333	\$	<i>na</i>	100.00	<i>605 na</i>
1 DOOR STICKER CLASSIC	\$	<i>na</i>	100.00	<i>155 na</i>
1 FRONT BUMPER CLIP	\$	<i>na</i>	66.00	—
1 LICENSE PLATE WITH HOLDER REAR	\$	<i>Pm</i>	120.00	X
2 LICENSE PLATE WITH HOLDER FRT	\$	<i>na</i>	121.00	<i>455 na</i>
2 WINDSCREEN SEALANT	\$	<i>na</i>	150.00	<i>405 na</i>
1 WINDSCREEN MOULDING	\$	<i>na</i>	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	130.00	<i>305 na</i>
TOTAL	\$		1,692.00	
TOTAL PARTS	\$		16,795.26	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	<i>1201</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>1760</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>1000</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>1501</i>

Trans-cab Auto Services Pte Ltd

AAD2208-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$		170.00	12d
To check steering geometry and computer wheel alignment	\$		220.00	6d
To Check Electrical Lighting Concerned.	\$		170.00	2d

TOTAL \$ 7,880.00**Over All Total \$ 39,778.52****(LUMP SUM)****Repair Days****20 DAYS****12 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: