

ASS. REC. BY:

REF:

A/G 22008580/K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

B 26,646.00

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 300T

Yr Regn:

02 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

718704

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1AB215AUC 282353

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/80 215/60R16

R: Sailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

J

mm

L/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

27/8/22

D.O.I.

30/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body & PA

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Await for BV

Recommend T/Loss. Bal \$ 5952.00

Market Value - \$ 26,646.00
 - Total COE Rate - \$ 20,694.00
 = \$ 5,952.00

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T*Not Authored
L/Ry S***AAD2208-**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

30 AUG 2022**SHD300T**

VF1ABL15AUC282353

200303878K

RENAULT

LATITUDE

27/08/2022

SLA6014Z/AIG

04/02/2016

PART		LIST	
1 BUMPER COVER FRT	\$	<i>mit</i> 747.20	✓
1 BUMPER UNDERTRAY FRT	\$	<i>mit</i> 292.50	✓
1 BUMPER SPOILER FRT	\$	<i>mit</i> 344.70	✓
1 BUMPER BEAM FRT	\$	<i>Ry</i> 663.70	✓
1 BUMPER ABSORBER FRT	\$	<i>mit</i> 394.68	✓
1 BUMPER BRACKET KIT FRT LH	\$	<i>mit</i> 101.40	✓
1 BUMPER RETAINER FRT LH	\$	<i>CM</i> 101.40	✓
1 BUMPER BRACKET KIT FRT RH	\$	<i>mit</i> 101.40	✓
1 BUMPER RETAINER FRT RH	\$	<i>CM</i> 101.40	✓
1 BUMPER SUPPORT FRT	\$	<i>mit</i> 10.70	✓
1 BUMPER BRACKET FRT LH (Headlamp Lower)	\$	<i>CM</i> 116.47	✓
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$	<i>CM</i> 116.47	✓
1 HEADLAMP PANEL FRT LH	\$	<i>Bu</i> 128.30	✓
1 HEADLAMP PANEL FRT RH	\$	<i>Bu</i> 128.30	✓
1 BUMPER GRILLE LOWER FRT	\$	<i>mit</i> 147.00	✓
1 BUMPER FOG LAMP GRILLE LH	\$	<i>mit</i> 207.21	✓
1 BUMPER FOG LAMP GRILLE RH	\$	<i>mit</i> 207.21	✓
1 A/C CONDENSER	\$	<i>Ry</i> 1,537.80	✓
1 RADIATOR	\$	<i>Ry</i> 871.20	✓
1 STEERING PUMP ELECTRIC	\$	nn 2,026.70	✗
1 TOW COVER FRT	\$	<i>mit</i> 60.90	✓
1 FENDER PANEL FRT LH	\$	<i>Ry</i> 437.10	✓
1 FENDER PANEL FRT RH	\$	<i>Ry</i> 437.10	✓
1 WHEELARCH FRT RH	\$	<i>Tn</i> 191.40	✓
1 WHEELARCH FRT LH	\$	<i>mit</i> 191.40	✓
1 BUMPER UNDERTRAY FRT	\$	nn 292.50	✗

Trans-cab Auto Services Pte Ltd**AAD2208-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

1 RADIATOR GRILLE	\$	Mil	969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	Mil	225.36	✓
1 RADIATOR GRILLE FRAME	\$	CM	686.00	✓
1 FRAME FULL SUPPORT PANEL	\$	CM	592.70	✓
1 BONNET	\$	B	1,312.70	✓
1 BONNET INSULATOR	\$	Reform	294.30	✓
1 BONNET HINGE LH	\$	R	237.40	X
1 BONNET HINGE RH	\$	R	237.40	X
1 BONNET LOCK	\$	Dis	152.80	✓
1 HORN	\$	Pl	449.90	X
1 WIPER RESERVOIR	\$	Sm	179.60	X
1 HEADLAMP LH	\$	Mil CM	743.60	✓
1 HEADLAMP RH	\$	" "	743.60	✓
1 WINDSCREEN FRT	\$	CM	817.20	✓
1 PASSENGER AIRBAG	\$	Burn	2,093.60	✓
1 STEERING AIRBAG	\$	"	1,592.90	✓
1 AIRBAG COMPUTER	\$	rec	1,213.90	✓
1 AIRBAG SENSOR	\$	rec	502.90	✓
1 SEATBELT LH	\$	Tn	1,488.70	✓
1 SEATBELT RH	\$	Tn	1,553.10	✓
1 FENDER PANEL FRT LH	\$	Perman	437.10	X
1 WHEELARCH FRT LH	\$	"	191.40	X
1 FENDER PANEL FRT RH	\$	"	437.10	X
1 WHEELARCH FRT RH	\$	"	191.40	X
1 FENDER PANEL REAR RH	\$	R	1,933.20	✓
1 WHEELARCH REAR RH	\$	Sm	275.40	X
1 DOOR PANEL FRT RH	\$	R	2,844.66	✓
1 DOOR WEATHERSTRIP FRT RH	\$	Pl	410.27	} X
1 DOOR HANDLE OUTER FRT RH	\$	Sm	477.76	
1 DOOR HANDLE MODULE FRT RH	\$	Sm	133.60	
1 DOOR REGULATOR FRT RH	\$	Sm	505.19	
1 DOOR REGULATOR MOTOR FRT RH	\$	Sm	796.46	
1 DOOR HINGE UPPER FRT RH	\$	R	261.28	
1 DOOR HINGE LOWER FRT RH	\$	R	300.55	
1 DOOR PANEL REAR RH	\$	R	2,844.66	
1 DOOR WEATHERSTRIP REAR RH	\$	Sm	311.60	}
1 DOOR HANDLE MODULE REAR RH	\$	Sm	133.40	
1 DOOR HANDLE OUTER REAR RH	\$	Sm	42.10	

Trans-cab Auto Services Pte Ltd**AAD2208-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

1 DOOR REGULATOR REAR RH	\$	<i>Pm</i>	450.60	X
1 DOOR REGULATOR MOTOR REAR RH	\$	<i>Sm</i>	758.10	X
1 DOOR HINGE UPPER REAR RH	\$	<i>R</i>	241.60	X
1 DOOR HINGE LOWER REAR RH	\$	<i>n</i>	169.90	X
	\$		16,781.40	
10%	\$		1,678.14	
	\$		15,103.26	

Specical Nett

1 FRT DOOR ADVERTISEMENT	\$	<i>M</i>	200.00	<i>120M</i>
1 RR DOOR ADVERTISEMENT	\$	<i>M</i>	200.00	<i>120M</i>
1 DOOR TRIM CLIP	\$	<i>nn</i>	70.00	X
1 DOOR SEAL CLIP	\$	<i>nn</i>	65.00	X
1 DOOR MOULDING CLIP	\$	<i>nn</i>	70.00	X
1 DOOR STICKER TRANSCAB	\$	<i>M</i>	100.00	<i>60M</i>
1 DOOR STICKER 65553333	\$	<i>M</i>	100.00	<i>60M</i>
1 DOOR STICKER CLASSIC	\$	<i>M</i>	100.00	<i>15M</i>
1 FRONT BUMPER CLIP	\$	<i>M</i>	66.00	
1 LICENSE PLATE WITH HOLDER REAR	\$	<i>Sm</i>	120.00	X
2 LICENSE PLATE WITH HOLDER FRT	\$	<i>Mr</i>	121.00	<i>45M</i>
2 WINDSCREEN SEALANT	\$	<i>M</i>	150.00	<i>40M</i>
1 WINDSCREEN MOULDING	\$	<i>nn</i>	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>M</i>	130.00	<i>30M</i>
TOTAL	\$		1,692.00	
TOTAL PARTS	\$		16,795.26	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	<i>120</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>1760</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>1000</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>150</i>

Trans-cab Auto Services Pte Ltd**AAD2208-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD300T

To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$		170.00	<i>12d</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>6d</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>2d</i>

TOTAL \$ 7,880.00**Over All Total \$ 39,778.52****(LUMP SUM)****Repair Days****20 DAYS***12 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD300T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Aug 2022
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002894
Chassis No.:	VF1ABL15AUC282353
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Feb 2016
First Registration Date:	04 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Feb 2024
PARF Rebate Amount:	\$12,998.00

Intended COE Rebate Details

COE Expiry Date:	03 Feb 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$43,040.00
COE Rebate Amount:	\$7,696.00
Total Rebate Amount:	\$20,694.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Aug 2022

OK