

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20010407/UPA3Q2-1**Date:** 02/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800076198
Claimant Vehicle No :	FBL633L	Insured Vehicle No :	SMC3248M
Date of Loss:	31/08/2020	Nature of Claim:	TP
		Claim No:	6209241770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL633L	Engine No:	H405402466
Make & Model:	SUZUKI UH200AL6 BURGMAN, 200cc ABS	Chassis No:	MLCC91121G0402466
Reg. Date:	24/05/2016 (Man. Year: 2016)	Odometer:	8163 km
Colour:	White		
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/90 R13	Rear Tyre Size:	130/70 R12
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,061.00	1,785.60	2,275.40	56.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	280.00	35.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,376.00	2,065.60	2,310.40	52.80
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	4,376.00	1,650.00	2,726.00	62.29
+ GST 7.00/7.00% (S\$)	306.32	115.50	190.82	62.29
Nett Amount (S\$)	4,682.32	1,765.50	2,916.82	62.29
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,827.50		

INSPECTION

Date of Assignment:	29/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER	Scratched	20.00 F	*20.00 FL
2	1		*BODY MUFFLER	Repair	1,724.00 F	*- FL
3	1		*BOX REAR (KAPPA) K42	Scratched	270.00 F	*270.00 FL
4	1		*CONNECTOR MUFFLER	Not Necessary	24.00 F	*- FL
5	1		*COVER SHIELD ,LEG FRONT (WHITE)	Cut	327.00 F	*327.00 FL
6	1		*COVER ,COMP MUFFLER FR	Cut	24.00 F	*24.00 FL
7	1		*COVER MUFFLER	Cut	76.00 F	*76.00 FL
8	1		*COVER MUFFLER RR	Cut	44.00 F	*44.00 FL
9	1		*FOOTBOARD RH (BLACK)	Cut	35.00 F	*35.00 FL
10	1		*HANDLE PILLION RIDER RH (WHITE)	Repair	136.00 F	*- FL
11	1		*LEVER ,FRONT BRAKE	Scratched	42.00 F	*42.00 FL
12	1		*MIRROR ASSY ,RR VIEW LH (CUT)	Not Consistent With The Impact	51.00 F	*- FL
13	1		*MIRROR ASSY ,RR VIEW RH	Cut	56.00 F	*56.00 FL
14	1		*MUDGUARD FRONT (WHITE)	Repair	142.00 F	*- FL
15	1		*SHIELD ,LEG LOWER (GRAY)	Cut	122.00 F	*122.00 FL
16	1		*SHIELD ,LEG SIDE RH (GRAY)	Cut	128.00 F	*128.00 FL
17	1		*COVER TAIL CENTRE WHITE (ADDITIONAL)	Cracked	91.00 F	*91.00 FL
18	1		*EMBLEM SUZUKI (ADDITIONAL)	Necessary	14.00 F	*14.00 FL
19	1		*RUBBER SEAT BOX (ADDITIONAL)	Necessary	35.00 F	*35.00 FL
20	1		*SEAT ASSY (BLACK/ GRAY) (ADDITIONAL)	Cracked	700.00 F	*700.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,061.00	1,984.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	198.40
Total Parts (S\$)	4,061.00	1,785.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	315.00	280.00
Gross Labour Cost (\$\$)			315.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >