

✓ SAS-KIV → see attached.

# COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

LKK -

DATE: 29.08.2022

MODEL: Hyundai Ioniq

INSURANCE: NTUC CP/P

VEHICLE NO.: SHC8644D

MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper X Repair	1		\$ 459.40
	Rear Bumper Centre Moulding X	1		\$ 451.25
	Rear Bumper Lower Moulding X	1		\$ 155.00
	Rear Bumper Cover Clips X	10	\$ 2.20	\$ 22.00
	<b>SUB TOTAL</b>			<b>\$ 1,087.65</b>
	<b>LESS 20%</b>			<b>\$ 217.53</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 870.12</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 820.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,690.12</b>

350  
250  
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.

P/P

Good Day

25/8/22

12pm

640

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after repair/finishing
- To display damaged parts for inspection
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault Found" basis
- No illegal modifications allowed
- Supplementary item(s) must be approved and is subject to final approval of the insurance company

Acknowledged by Repairer:  
Signature:  
Date: