

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7308/B

Date: 26.08.2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>MC</i>			\$459.40 ✓
10	REAR BUMPER CLIPS <i>MC</i>			\$22.00 ✓
1	REAR BUMPER CENTRE MOULDING ASSY <i>Cut</i>			\$451.25 ✓
1	REAR BUMPER REINFORCEMENT X NN			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH <i>X NN</i>			\$138.10
1	REAR BUMPER SIDE BRACKET LH <i>Cut</i>			\$55.80 ✓
1	REAR BUMPER LOWER CTR MOULDING <i>BR</i>			\$155.00 ✓
1	REAR BUMPER CENTRE UNDER COVER <i>X NN</i>			\$225.00 ✓
1	REAR BUMPER SIDE UNDER COVER LH <i>TD</i>			\$108.00 ✓
1	REAR BUMPER REFLECTOR LAMP LH <i>Cut</i>			\$41.45 ✓
SUB TOTAL				\$2,050.80
LESS 20%				\$410.16
DISCOUNTED TOTAL				\$1,640.64
REAR BUMPER RUBBER MAT <i>MC</i>				\$50.00 ✓
REAR NUMBER PLATE WITH TRIM COVER <i>X NN</i>				\$55.00
REAR BUMPER REVERSE SENSOR <i>X</i>				\$180.00
				\$285.00
Labour Charge				
PANEL BEATING				\$400.00 <i>350</i>
SPRAY PAINTING CHARGE				\$300.00 <i>250</i>
REMOVE/REFIX REVERSE SENSOR				\$80.00 <i>60</i>
TOTAL LABOUR				\$780.00
ESTIMATE TOTAL				\$2,705.64
				1350

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
4/5
emo Q: p
29/8/22
bpm

LKK Auto Consultants to notify
the Repairer of the damage.

- To resurvey before repair is completed
- To display damaged parts for presurvey
- Parts prices are subject to presurvey
- Third party survey is on a "no dispute" basis
- No illegal modification or repair
- Supplementary items are subject to final approval

is subject to final approval by the insurance company.

Acknowledged by Repairer
Signature: _____