



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

ATTN: FIONA SHEN

Ref: CS/INC22008587/Gqy3m4

Date: 14/10/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBE 2898M	Veh. Inspected	SMR 4676A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1184832-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	02/09/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GP72006106	Colour	WHITE
Odometer	53102 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/08/2022	Inspect Date / Time	02/09/2022 (11:30 AM)
Survey held at	WORLD AUTO PTE LTD NO.5, KIM CHUAN LANE SINGAPORE 537070		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------