



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22008588/Upa3q2 Date: 02/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 8957L	Veh. Inspected	SMW 6064B
	Policy No.	P2180048	Coverage (\$)	0.00
	Claim No.	S2M04A7A	Excess (\$)	0.00
	Assign From		Assign Date	02/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MHFZ28H3X00063240	Colour	BROWN
	Odometer	124329 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	WINRUN	7 mm
	L/H Front Tyre	195/50 R16	WINRUN	7 mm
	R/H Rear Tyre	195/50 R16	WINRUN	7 mm
	L/H Rear Tyre	195/50 R16	WINRUN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/09/2022	Inspection Date	02/09/2022
	Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	