

HSR Auto

2. + Arthur
2/9/22
4/5 @ 6200
6 days

NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43

#07-97 Singapore 520436

Tel: (65) 9674 1991

✉ nineteenautowerks@gmail.com

ESTIMATE



NINETEEN
AUTOWERKS

DATE:

2-Sep-22

DOA:

1-Sep-22

VEHICLE NO:

SMW 6064 B

MAKE & MODEL:

Toyota Sienna

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
LIST ITEMS			
Rear boot lid	1	\$1,131.50	\$1,131.50 ✓
Rear boot lid logo "TOYOTA"	1	\$67.40	\$67.40 ✓
Rear boot lid outer handle	1	\$485.70	\$485.70 X
Rear boot lid top lock	1	\$373.70	\$373.70 ✓
Rear boot rubber	1	\$353.00	\$353.00 ✓
Rear boot lid reflector	2	\$328.00	\$656.00 X
Tailgate wiper motor	1	\$455.80	\$455.80 X
Tailgate lock catch	1	\$46.00	\$46.00 X
Tailgate inner trim	1	\$586.00	\$586.00 X
Rear end panel	1	\$661.70	\$661.70 ✓
Rear end panel lock garnish	1	\$212.80	\$212.80 ✓
Taillamps	2	\$469.50	\$939.00 X
Rear bumper top	1	\$498.70	\$498.70 ✓
Rear bumper <i>centre lamp</i>	1	\$367.90	\$367.90 ✓
Rear bumper top bracket	2	\$87.80	\$175.60 X
Rear bumper side retainers	2	\$92.60	\$185.20 ✓
Rear bumper side protector	2	\$169.90	\$339.80 PC
Rear bumper center protector	1	\$267.90	\$267.90 ✓
Rear bumper reflector	2	\$125.20	\$250.40 PC
Rear windscreen moulding	1	\$133.70	\$133.70 ✓
Tailgate detector	1	\$321.00	\$321.00 X
Tailgate detector wire harness	1	\$589.00	\$589.00 X
Rear bumper tow cover	1	\$43.90	\$43.90 ✓
Rear fender inner trim	2	\$689.00	\$1,378.00 X
Rear fender inner cowling	2	\$203.00	\$406.00 X
Rear floor panel	1	\$784.00	\$784.00 ✓
Rear floor panel top board	2	\$358.00	\$716.00 X
Rear tool box garnish	1	\$585.00	\$585.00 ✓
Rear exhaust silencer	1	\$899.20	\$899.20 X
Rear exhaust mounting	1	\$90.00	\$90.00 ✓
Rear <i>antenne sensor</i>	1	\$166.00	\$166.00 ✓
Total			\$14,165.90
Less 25%			\$3,541.48
			\$10,624.43

SPECIAL NETT ITEMS

Sundries	1	\$60.00	\$60.00 X
Rear bumper clips (set)	1	\$80.00	\$80.00 50

Taillamps clips (set)	2	\$32.00	11	\$64.00	X
Tailgate windscreen sealant	1	\$80.00	11	\$80.00	40
Tailgate windscreen inner seal	1	\$80.00	11	\$80.00	30
Tailgate outer garnish clips (set)	1	\$40.00	11	\$40.00	X
Tailgate inner trim clips (set)	1	\$50.00	11	\$50.00	X
Rear fender inner trim clips (set)	2	\$60.00	11	\$120.00	X
Rear fender inner cowling clips (set)	2	\$60.00	11	\$120.00	X
Rear end panel top garnish clips (set)	1	\$40.00	11	\$40.00	X
Rear end panel insulation seal <i>Sealant</i>	1	\$120.00	11	\$120.00	50
Rear floor panel insulation seal	1 set	\$150.00	11	\$150.00	✓
Reverse camera	1	\$600.00	11	\$600.00	X
Reverse sensor	1 set	\$280.00	11	\$280.00	220
				\$1,884.00	
		Parts Total		\$12,508.43	

LABOUR CHARGES

Panel beating		\$1,800.00	1100
Spray painting		\$1,500.00	1100
Tuff coat		\$300.00	80
Check wiring after disconnect & connect		\$120.00	30
Remove & refit cushion seat / upholstery and roof lining		\$250.00	80
Remove & refit tailgate mechanism		\$150.00	60
Remove & refit tailgate windscreen		\$150.00	120
Remove & refit rear exhaust		\$150.00	X
Remove & install reverse camera and test		\$200.00	50
Remove & install reverse sensor and test		\$200.00	50
	Labour Total	\$4,820.00	
		\$17,328.43	

Total Parts and Labour Cost of Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-6127.5
254
4585.62
140
2620
7785.62