

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22008607/NCY3M4**Date:** 06/01/2023**REFERENCE**

Insured/Claimant: CHONG TECK SIN Policy No: DMPCSNA00165072201

Date of Loss: 31/08/2022 Nature of Claim: OD Claim No: SNM22D206224/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE4273J**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4032247
 Reg. Date: 21/07/2016 (Man. Year: 2015) Chassis No: RU11112239
 Colour: White Odometer: 0 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: S\$61,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	2,280.00	-2,280.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	201.60	201.60	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	201.60	2,481.60	-2,280.00	-1,130.95
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	-298.40	1,981.60	-2,280.00	764.08
+ GST 7.00/7.00% (S\$)	0.00	138.71	-138.71	
Nett Amount (S\$)	-298.40	2,120.31	-2,418.71	810.56

INSPECTION

Date of Assignment: 02/09/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
 Date Inspected: 06/09/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
 6 Marsiling Lane
 Singapore 739145
 Estimated Period of Repair: 7.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,920.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE4273J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		0.00 F	*2,280.00 F
F=Franchise part.						
				Total Parts (\$\$)	0.00	2,280.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	201.60	201.60
Gross Labour Cost (\$\$)			201.60	201.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >