



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref:	CS3/CTI22008610/Sqy3
3 ANSON ROAD #16-00			Date:	02/09/2022
SPRINGLEAF TOWERSINGAPORE 079909			Code:	CTI
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMQ 854J	Veh. Inspected	SJT 9846T	
Policy No.	DMPCSNW00200862102	Coverage (\$)	0.00	
Claim No.	SNM22D206233/C02	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	02/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/08/2022	Inspection Date	02/09/2022	
Survey held at	TECHNEAT PTE LTD 8 KAKI BUKIT AVENUE 4, #03-38/39 PREMIER @ KAKI BUKIT			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				