

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ANG HUI MIN
 85 YISHUN AVE 11 #11-32
 SINGAPORE 768865

Contact : 98269663

*TP Chua
 Xiao Chen*

TAX INVOICE

Repair Code : CLM15649
 Date in : 31/08/2022
 Vehicle Num. : SJG315L
 Model : TOYOTA RUSH 1.5X A
 Chassis/Eng# : J200E0019658/3SZ033871

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Debond</i>	1	695.50	✓ 695.50
REAR BUMPER NUMBER PLATE LAMP L/R <i>cracked</i>	2	527.80	136. ✓ 1,055.60
REAR BUMPER REFLECTOR L/R <i>the new</i>	2	52.80	x. 105.60
REAR BUMPER SIDE RETAINER L/R <i>the new</i>	2	89.60	+ 179.20
REAR END PANEL <i>Dented</i>	1	317.80	✓ 317.80
REAR END PANEL INNER TOP GARNISH <i>Debond</i>	1	274.30	✓ 274.30
REAR TAILGATE <i>Debond</i>	1	2107.10	1404. ✓ 2,107.10
REAR TAILGATE 'RUSH' EMBLEM <i>new</i>	1	79.20	✓ 79.20
REAR TAILGATE HINGE (LOWER) <i>the new</i>	1	168.10	x 168.10
REAR TAILGATE HINGE (TOP)	1	168.10	x 168.10
REAR TAILGATE INNER RUBBER GUIDE STOPPER <i>the new</i>	2	30.40	x. 60.80
REAR TAILGATE INNER TRIM BOARD <i>cracked</i>	1	319.60	✓ 319.60
REAR TAILGATE MECHANISM LOCK <i>the new</i>	1	188.20	x. 188.20
REAR TAILGATE SPARE TYRE BRACKET <i>the new</i>	1	290.40	x. 290.40
REAR TAILGATE SPARE TYRE COVER (INNER) <i>cracked</i>	1	335.30	✓ 335.30
REAR TAILGATE SPARE TYRE COVER (OUTER) <i>Debond</i>	1	1704.80	✓ 1,704.80
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	270.70	✓ 270.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki-Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ANG HUI MIN
 85 YISHUN AVE 11 #11-32
 SINGAPORE 768865

Contact : 98269663

TAX INVOICE

Repair Code : CLM15649

Date in : 31/08/2022

Vehicle Num. : SJG315L

Model : TOYOTA RUSH 1.5X A

Chassis/Eng# : J200E0019658/3SZ033871

	Subtotal before discount	5537.20	8,320.30
Percentage discount 25%		4152.90	2,080.08
	Sub-total 1		6,240.23
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
REAR BUMPER NUMBER PLATE HOLDER <i>new</i>	1	50.00	+ 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Den d</i>	1	280.00	20 280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	10 40.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR TAILGATE WINDSCREEN SEAL <i>2 new</i>	1	80.00	30 80.00
REAR TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	80.00	30 80.00
	Subtotal before discount		655.00
Percentage discount 0%			0.00
	Sub-total 2		655.00
	Parts-total		6,895.23

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

~~60~~ 80.00
~~120~~ 150.00
~~30~~ 100.00
~~80~~ 1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ANG HUI MIN
85 YISHUN AVE 11 #11-32
SINGAPORE 768865

Contact : 98269663

TAX INVOICE

Repair Code : CLM15649

Date in : 31/08/2022

Vehicle Num. : SJG315L

Model : TOYOTA RUSH 1.5X A

Chassis/Eng# : J200E0019658/3SZ033871

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

1830	7w 800.00
	40.100.00
	✓ 80.00
Labour Total	2,310.00
Parts & Labour Total	9,205.23

*** This is a computer-generated document which requires no signature.***

page 3

total: 6312.80
y/s: 5k
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5k