



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMX9317Y

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 27/08/2022

TP VEH REG NO : SMX9317Y

ESTIMATE

NO : QUOT202208-000060(00)

DATE : 30/08/2022

POLICY NO : 999995580

VEH REG NO : SLQ7955S

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R279913

ENGINE NO : 27491030944597

REG. DATE : 2017

Not Authorised

Permy B4 pain

6 days

810,654.01

Estimate Repair Cost to Vehicle No : SLQ7955S

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			<i>2522.70</i>
1 Bootlid	1	2,696.00	2,696.00 ✓
2 Bootlid weatherstrip	1	238.00	238.00 ✓
3 Bootlid outer side garnish -- RH / LH (Top)	2	65.00	130.00 ✓
4 Bootlid lock	1	325.00	325.00 X
5 Bootlid centre logo	1	56.00	56.00 ✓
6 Bootlid '9G-TRONIC' emblem	1	95.00	95.00 ✓
7 Bootlid hinges -- RH / LH	2	288.00	576.00 X
8 Bootlid 'C180' emblem	1	130.00	130.00 ✓
9 Bootlid inner garnish	1	285.00	285.00 X
10 Bootlid inner garnish clips	10	12.00	120.00 X
11 Bootlid centre chrome	1	172.00	172.00 ✓
12 Rear number plate lamp - RH / LH	2	34.00	68.00 X
13 Rear end panel	1	1,769.00	1,769.00 ✓
14 Rear end panel top garnish	1	182.00	182.00 ✓
15 Rear end panel top garnish clips	10	12.60	126.00 ✓
16 Taillamp assy - RH / LH	2	865.00	1,730.00 ✓
17 Taillamp lower bracket LH	1	45.00	45.00 ✓
18 Rear bumper	1	2,020.00	2,020.00 ✓
19 Rear bumper reinforcement	1	830.00	830.00 ✓
20 Rear bumper side retainer -- RH / LH	2	75.00	150.00 ✓
21 Rear bumper reverse sensor	4	215.00	860.00 X
22 Rear bumper reverse sensor seal	6	12.00	72.00 ✓
23 Rear bumper clips	15	9.00	135.00 ✓
24 Rear bumper centre inner frame	1	125.00	125.00 ✓
25 Rear bumper lower spoiler	1	275.00	275.00 X
26 Rear bumper lower centre bracket	1	145.60	145.60 X
27 Rear bumper lower spoiler clips	8	10.00	80.00 X
28 Rear bumper lower bracket RH/LH	2	46.00	92.00 X
29 Rear bumper lower chrome	1	316.00	316.00 X
30 Bootlid spare tyre compartment top board	1	440.00	440.00 X
			14,283.60
		Less 10%	1,428.36
			12,855.24



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMX9317Y

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 27/08/2022

TP VEH REG NO : SMX9317Y

ESTIMATE

NO : QUOT202208-000060(00)

DATE : 30/08/2022

POLICY NO : 999995580

VEH REG NO : SLQ7955S

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R279913

ENGINE NO : 27491030944597

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ7955S

Description	Quantity	Unit Price	Amount
		S\$	S\$
SPECIAL NET			
31 Rear number plate NEC ✓	1	✓ 40.00	40.00 40.00 X
LABOUR			
32 To remove & refit rear bumper sensor	1	100.00	100.00 601
33 To check & rectify wiring system	1	80.00	80.00 201
34 To transfer damage bootlid interior mechaism to new bootlid	1	120.00	120.00 601
35 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, , including replacement of parts and align where necessary, to refit and adjust the the same	1	1,500.00	1,500.00 7001
36 To putty & spray paint on affected area	1	1,500.00	1,500.00 8001
37 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00 301
			3,460.00
		TOTAL	S\$ 16,355.24
		ADD GST @ 7%	1,144.87
		GRAND TOTAL	S\$ 17,500.11

SINGAPORE DOLLAR SEVENTEEN THOUSAND FIVE HUNDRED AND CENTS ELEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMX9317Y

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 27/08/2022

TP VEH REG NO : SMX9317Y

ESTIMATE

NO : QUOT202208-000060(00)

DATE : 30/08/2022

POLICY NO : 999995580

VEH REG NO : SLQ7955S

MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050402R279913

ENGINE NO : 27491030944597

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ7955S

Description	Quantity	Unit Price	Amount
33 Rear bumper lower centre bracket	1	\$45.00	145.00
34 Rear bumper lower bracket RH/LH	2	46.00	92.00
TAILAMP LOWER BRACKET LH - SUPP			14,690.60
REAR BUMPER CENTRE INNER FRAME -SUPP		\$125.00	1,469.06
SPECIAL NET			13,221.54
35 Rear number plate		40.00	40.00
LABOUR			40.00
36 To remove & refit rear bumper sensor		100.00	100.00
37 To check & rectify wiring system		80.00	80.00
38 To transfer damage, bootlid interior mechanism to new bootlid		120.00	120.00
39 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to rent and adjust the tire same		1,500.00	1,500.00
40 To apply & spray paint on affected area		1,500.00	1,500.00
41 To apply rust proofing on replaced and repaired panels		160.00	160.00
			3,460.00
		TOTAL	\$16,721.54
		ADD GST @ 7%	1,170.51
		GRAND TOTAL	\$17,892.05

SINGAPORE DOLLAR SEVENTEEN THOUSAND EIGHT HUNDRED NINETY-TWO AND CENTS FIVE ONLY

8 = 12,582.84
-10% 1,158.28
10,424.56
S/N 40.00
10,464.56
L = 1670.00
12,134.56
11,403.14

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE