

REPAIR ESTIMATE*

VEHICLE NO SHC133P

DATE 29.08.2022

MAKE REG.17.08.2018

MODEL : HYUNDAI IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH X WIP			\$35.00
1	FRONT BUMPER / CPA			\$481.10 ✓
1	FRONT BUMPER REINFORCEMENT ?			\$1,136.70
1	FRONT RADIATOR GRILLE / CPA			\$1,409.10 ✓
1	FRONT BUMPER CENTRE MOULDING X			\$368.50
1	FRONT HEAD LAMP RH X			\$2,110.30
1	FOG LAMP RH X			\$642.50
1	FRONT BUMPER GARNISH RH X			\$186.90
1	REAR BUMPER / CPA			\$459.40 ✓
1	REAR BUMPER CENTRE MOULDING / CPA			\$451.25 ✓
1	REAR BUMPER REINFORCEMENT ?			\$394.80
1	REAR BUMPER BRACKET RH ?			\$55.80
1	REAR BUMPER REFLECTOR RH ?			\$41.45
1	REAR BUMPER FOG LAMP X			\$201.50
1	REAR BUMPER NUMBER LAMP X			\$85.30
1	FRONT BUMPER GARNISH RH X			\$186.90
SUB TOTAL			2800.85	\$8,246.50
20.00%				\$1,649.30
DISCOUNTED TOTAL			2240.68	\$6,597.20
2	REAR FENDER ADVERTISEMENT /		\$100.00	\$200.00
1	REAR BUMPER MAT /			\$50.00
1	REAR REVERSE SENSOR / CPA			\$180.00
1	FRONT NUMBER PLATE W/HOLDER / CPA			\$55.00
				\$485.00 ✓
Labour Charge				
Panel Beating				\$1,225.00 700
Spray Paint				\$800.00 500
Remove/refix reverse sensor				\$50.00 40
Tuff Coating				\$90.00 X
Check lighting				\$60.00 X
TOTAL LABOUR				\$2,225.00 1240
ESTIMATE TOTAL				\$9,307.20
				4295.52
				-20%: 3450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be carried out
- Supplies and materials used are resurveyed and approved by the Insurance Company

Acknowledged:

Signature:

Date:

3 Pans -
 4/5
 Gms Q/cp
 20/8/22
 1/Am