

REPAIR ESTIMATEDATE: 29.08.2022

LKK-

MODEL: Hyundai IoniqINSURANCE: NTUC ^(4/5)VEHICLE NO.: SHD4296XMVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Wing Mirror RH <i>/ 015</i>	1		\$ 1,390.70
	SUB TOTAL			\$ 1,390.70
	LESS 20%			\$ 278.14
	DISCOUNTED TOTAL			\$ 1,112.56
	Labour Charge			
	Panel Beating - Windscreen Pillar RH		250	\$ 400.00
	Spray Painting Charge		350	\$ 400.00
	Check Wirings			\$ 40.00
	TOTAL LABOUR			\$ 880.00
	ESTIMATE TOTAL			\$ 1,992.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

-20%: 1450

2 Days

30/8/22

Gme Og

11 Am.

4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary charges must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: