

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7364D

DATE: 31.08.22

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 30.08.22

NTUC (P/P)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY / TW			\$459.40
1	REAR BUMPER CENTRE MOULDING / AT			\$451.25
1	REAR BUMPER BEAM X NN			\$394.80
10	REAR BUMPER CLIPS X ac			\$22.00
1	REAR FOG LAMP X NN			\$201.50
1	ANTENNA - SMARTKEY X NN			\$40.50
SUB TOTAL				\$1,569.45
LESS 20%				\$313.89
DISCOUNTED TOTAL				\$1,255.56
REAR NUMBER PLATE / CNA				\$50.00
BUMPER MAT / MC				\$50.00
				\$100.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINT				\$300.00
REMOVE / REFIX REVERSE SENSOR				\$50.00
TOTAL LABOUR				\$750.00
ESTIMATE TOTAL				\$2,105.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications (one) is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date:

2 Days
P/P
One Day
31/8/22
2pm

350
250
40