

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4938C

Make : HYUNDAI

Model : IONIQ(G3)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to a 7% Without Prejudice basis
- Third party survey is on a Without Prejudice basis
- No illegal modification
- Subsequent item(s) must be surveyed and is subject to final approval from Insurance Company

Date: 31.08.2022

Insurance: NTUC

MVA: MS LOKE YY

Qty	Parts Description / Labour	Acknowledged by Repairer	Type	Unit Price	Amount
1	REAR BUMPER CO	Signature:			\$459.40
10	REAR BUMPER CLIP	Date:			\$22.00
1	REAR BUMPER CENTRAL MOUNTING ASSY				\$451.25
1	REAR BUMPER REINFORCEMENT				\$394.80
2	REAR BUMPER REINFORCEMENT SOCKET LH RH			\$138.10	\$276.20
1	REAR BUMPER FOG LAMP				\$201.50
1	REAR BUMPER LICENCE LAMP				\$85.30
1	ANTENNA ASSY SMARTKEY				\$40.50
2	REAR BUMPER SIDE BRACKET LH RH			\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING				\$155.00
1	BOOTLID				\$2,549.70
1	EMBLEM HYBRID				\$24.30
1	EMBLEM - IONIQ				\$31.30
1	BOOT LID TRIMBOARD CT				\$159.70
1	REAR PANEL				\$532.00
1	REAR PANEL GARNISH				\$346.80
SUB TOTAL					\$5,841.35
LESS 20%					\$1,168.27
DISCOUNTED TOTAL					\$4,673.08
	RENEW ADVERTISEMENT STICKER				\$300.00 Nett
	REAR BUMPER RUBBER MAT				\$50.00 Nett
	REAR NUMBER PLATE WITH TRIM COVER				\$55.00 Nett
	BOOTLID COMFORT TEL NO STICKER				\$40.00 Nett
	BOOTLID COMFORT LOGO STICKER				\$30.00 Nett
	BOOTLID COMFORT APP STICKER				\$30.00 Nett
	REAR BUMPER REVERSE SENSOR				\$180.00 Nett
					\$685.00
Labour Charge					
	PANEL BEATING				\$1,100.00
	SPRAY PAINTING CHARGE				\$800.00
	CHK ALL LIGHTING				\$60.00
	TUFF KOTE				\$60.00
	REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR					\$2,100.00
ESTIMATE TOTAL					\$7,458.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days.
4/5 Gino Ong
21/8/22 3pm

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4953H

23.08.2022

MAKE REG.10.07.2019

MODEL IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>X Repair</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>cat</i>			\$451.25 ✓
1	REAR BUMPER REINFORCEMENT <i>?</i>			\$394.80
2	REAR BUMPER STAY LH/RH <i>X X X</i>		\$138.10	\$276.20
10	REAR BUMPER CLIPS <i>X X X</i>		\$2.20	\$22.00
1	REAR BUMPER LOWER CENTRE MOULDING <i>X X</i>			\$155.00
1	BOOTLID <i>Boac</i>			\$2,549.70 ✓
1	BOOTLID LAMP LH/RH <i>?</i>		\$822.00	\$1,644.00
1	SPOILER BRAKE LAMP <i>X na</i>			\$385.60
1	SPOILER <i>X Repair</i>			\$665.40
1	BOOTLID GLASS LOWER <i>sm</i>			\$805.80 ✓
1	BOOTLID H EMBLEM <i>sm</i>			\$38.00 ✓
1	BOOTLID EMBLEM IONID <i>sm</i>			\$31.80 ✓
1	BOOTLID EMBLEM HYBRID <i>sm</i>			\$24.30 ✓
1	REAR BUMPER TOW COVER <i>X</i>			\$98.80
1	REAR SMART KEY SENSOR <i>X</i>			\$40.50
1	REAR BUMPER FOG LAMP <i>X</i>			\$201.50
2	REAR NUMBER PLATE LAMP <i>X</i>		\$42.65	\$85.30
2	REAR BUMPER BRACKET LH/RH <i>X</i>		\$55.80	\$111.60
				\$8,440.95
				20.00%
				DISCOUNTED TOTAL
				\$1,688.19
				\$6,752.76
1	BOOTLID COMFORT APP STICKER <i>sm</i>			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER <i>sm</i>		\$30.00	\$60.00
1	REAR NUMBER PLATE W/HOLDER <i>ORA</i>			\$55.00
1	REAR REVERSE SENSOR <i>X na</i>			\$180.00
			155	\$301.50
	Labour Charge			
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$600.00
	Remove/Refix bootlid glass upper/lower			\$200.00
	Check wiring and lighting			\$60.00
	Tuff Kote			\$90.00
	Remove/Refix reverse sensor			\$60.00
	TOTAL LABOUR			\$2,060.00
	ESTIMATE TOTAL			\$9,114.26
			1300	
			-20%: 3650	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will