

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL
Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/08/2022
Vehicle Reg. No.:	SHA4083J	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ, 1.6 (A)	Vehicle Reg. Date:	14/11/2019
Vehicle Colour:	BLUE		
Engine No:	G4LEKU405235	Chassis No:	KMHC851CVLU188863
Odometer:	383263 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,564.28
Miscellaneous Items	11.00
Labour	970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,545.28
+ GST 7.00% (\$\$)	178.17
Nett Amount (\$\$)	2,723.45

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2022)**Parts:** 143 HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA4083J/30/08/2022 09:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>X Repair</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER BRACKET - LH <i>X</i>	20.00	0.00	*55.80 FL
3	1		*REAR BUMPER CENTRE MOULDING <i>X</i>	20.00	0.00	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT BEAM <i>X</i>	20.00	0.00	*394.80 FL
5	1		*REAR BUMPER REINFORCEMENT STAY LH <i>X</i>	20.00	0.00	*138.10 FL
6	1		*REAR BUMPER TOW COVER <i>X</i>	20.00	0.00	*98.80 FL
7	10		*REAR BUMPER CLIPS <i>X</i>	20.00	0.00	*22.00 FL
8	1		*REAR NUMBER PLATE W/HOLDER <i>X</i>	0	0.00	*55.00 FS
9	1		*REAR REVERSE SENSOR <i>X</i>	0	0.00	*180.00 FS
10	1		*REAR BUMPER REFLECTOR LH <i>X</i>	20.00	0.00	*41.45 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**1,896.60****- List Item Discount on L Items (\$\$)****332.32****Total Parts (\$\$)****1,564.28****ComfortDelGro Engineering Pte Ltd/SHA4083J/30/08/2022 09:44. Not valid without Reference section.**

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 550.00
2	SPRAY PAINTING	New	250 300.00
3	TUFF COATING	New	60.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00
Gross Labour Cost (\$)			970.00

ComfortDelGro Engineering Pte Ltd/SHA4083J/30/08/2022 09:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.

~~4/8~~

8/8

6m 08

31/8/22

3 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: