

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 23.08.22INSURANCE: CHINA TAIPINGMODEL: Hyundai i40MVA: LIM T SVEHICLE NO: SHC8458A

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Door RH	1		\$ 2,416.80
	Rear Fender RH	1		\$ 2,171.40
	Rocker Panel Garnish RH	1		\$ 732.80
	SUB TOTAL			\$ 5,321.00
	LESS 20%			\$ 1,064.20
	DISCOUNTED TOTAL			\$ 4,256.80
	Rear Door APPS Sticker RH	1		\$ 80.00
	<u>Labour Charge</u>			
	Panel Beating			\$ 900.00
	Spray Painting Charge			\$ 900.00
	Tuff Kote			\$ 80.00
	Transfer Of Door			\$ 120.00
	TOTAL LABOUR			\$ 2,000.00
	ESTIMATE TOTAL			\$ 6,336.80

b4
Rr
de

NETT an

525
2560
30
60

600

cut

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97415747
in 23/8/22 0430
2/3 days after repair
Tanji Chikandun
2-3 days

Date/Time: 23.08.2022 13:50

Page : 1

Item: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4640268

JC NO: 305527417

STOMER

REGN NO.:

SHC8458A

MILEAGE

/MS COMFORT TRANSPORTATION PTE LTD

MAKE:

HYUNDAI

FUEL

STOMER NO. 7010045

E.....1/2.....F

DRESS 383 SIN MING DRIVE

MODEL

I-40

DATE/TIME IN 23.08.2022 10:25

Singapore SINGAPORE 575717

.. (R) 65508755

(O)

YR OF MANU.

03.12.2015

TARGET DATE

(P)

CHASSIS CODE

KMHLB41UMGU080656

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 23.08.2022

ATURE: 3P 23.08.2022

LKK -

HS
China

PC
3499 U.

/NO


00010

LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHC8458A-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

e No.: SHC8458A

LIMITS

Vehicle No.:

SHC8458A

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard