

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

(4S)

DATE: 23.08.22MODEL: Hyundai i40INSURANCE: CHINA TAIPINGVEHICLE NO: SHC8458AMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Door RH	1		\$ 2,416.80
	Rear Fender RH	1		\$ 2,171.40
	Rocker Panel Garnish RH	1		\$ 732.80
	SUB TOTAL		3144.60	\$ 5,321.00
	LESS 20%			\$ 1,064.20
	DISCOUNTED TOTAL		2519.68	\$ 4,256.80
	Rear Door APPS Sticker RH	1	80	\$ 80.00
	Labour Charge			
	Panel Beating			\$ 900.00
	Spray Painting Charge		600	\$ 900.00
	Tuff Kote			\$ 80.00
	Transfer Of Door		1215	\$ 120.00
	TOTAL LABOUR		3814.68	\$ 2,000.00
	ESTIMATE TOTAL		11543050	\$ 6,336.80
			03 days	

b4-
Rr
de-

NETT an

525
4560
30
60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphi 97495747
in' 23/8/22 0430
2/3 days after repair
Tanphi 97495747
2/3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: