COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

23.08.22

MODEL:

Hyundai i40

vehicle is surveyed by a motor Surveyor appointed by the insurance company.

VEHICLE NO: SHC8458A

INSURANCE: CHINA TAIPING

MVA: LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
S. Marcheller	Rear Door RH	1	734-W-17-17-18-18-18-18-18-18-18-18-18-18-18-18-18-	\$ 2,416.80
	Rear Fender RH	1		\$ 2,171.40
	Rocker Panel Garnish RH	1		\$ 732.80
	SUB TOTAL		3149.60	\$ 5,321.00
	LESS 20%			\$ 1,064.20
	DISCOUNTED TOTAL		25/9.68	\$ 4,256.80
	Rear Door APPS Sticker RH	1	80	\$ 80.00
	Labour Charge			at.
	Panel Beating			\$ 900.00
	Spray Painting Charge		600	\$ 900.00
	Tuff Kote			\$ 80.00
	Transfer Of Door		1215	\$ 120.00
	TOTAL LABOUR		3814.68	\$ 2,000.0
	ESTIMATE TOTAL		11593050 03days.X	\$ 6,336.8

Taypi 9749741 in 23/4120430