



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2207753
3 ANSON ROAD #16-00	INV Date	16/12/2022
SPRINGLEAF TOWER	Reference	CC3/CTI22008637/Tpa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SHB 6646S
Insured Veh.	SMX 6613L
Claim No.	SNM22D205971/C02
Policy No.	DMHCSNW00014012200
Accident Date	24/08/2022
Inspection Date	24/08/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI22008637/Tpa3q2 Date: 16/12/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMX 6613L	Veh. Inspected	SHB 6646S
Policy No.	DMHCSNW00014012200	Coverage (\$)	0.00
Claim No.	SNM22D205971/C02	Excess (\$)	0.00
Assign From		Assign Date	24/08/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU115015	Colour	BLUE
Odometer	527745 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/08/2022	Inspection Date	24/08/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6646S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	459.40	459.40
2	REAR BUMPER SIDE BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
2	REAR BUMPER REINFORCEMENT STAY LH/RH @\$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER REINFORCEMNT	NOT NECESSARY	394.80	-
1	REAR FOG LAMP	NOT NECESSARY	201.50	-
2	REAR BUMPER REFLECTOR LH/RH @\$41.45	NOT NECESSARY	82.90	-
1	TOWING COVER	NOT NECESSARY	98.80	-
2	REAR NUMBER PLATE LAMP LH/RH @\$85.30	NOT NECESSARY	170.60	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-453.81	-186.53
			1,815.24	746.12
<b>SPECIAL NETT ITEMS</b>				
2	REAR FENDER ADVERTISEMENT LH/RH @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR NUMBER PLATE W/HOLDER (SN)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	180.00	180.00
			435.00	435.00
<b>LABOUR</b>				
	PANEL BEATING.		550.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
			970.00	630.00
<b>GRAND TOTAL</b>			<b>3,220.24</b>	<b>1,811.12</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,450.00</b>

Report Ref No. CC3/CTI22008637/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHB 6646S

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SHB 6646S

## RE-INSPECTION

