

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO SHB6646S

24.08.2022

MAKE REG.30.10.2018

CHIANG/CHINA

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
2	REAR BUMPER REINFORCEMENT STAY LH/RH		\$138.10
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR FOG LAMP		\$201.50
2	REAR BUMPER REFLECTOR LH/RH		\$41.45
1	TOWING COVER		\$98.80
2	REAR NUMBER PLATE LAMP LH/RH		\$85.30
10	REAR BUMPER CLIPS		\$2.20
	<b>SUB TOTAL</b>		<b>\$2,269.05</b>
	<b>20.00% DISCOUNTED TOTAL</b>		<b>\$453.81</b>
			<b>\$1,815.24</b>
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			<b>\$435.00</b>
	<b>Labour Charge</b>		
	Panel Beating	350	\$550.00
	Spray Painting Charge	630	250 \$300.00
	Tuff Kote	w.m.x	\$60.00
	Remove/refix Reverse sensor	30	\$60.00
	<b>TOTAL LABOUR</b>		<b>\$970.00</b>
			<b>\$1,450</b>
	<b>ESTIMATE TOTAL</b>		<b>\$3,220.24</b>
			<b># 2 days</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495749  
 up 24/8/22 @ 4pm  
 2 days  
 c/s survey after repair  
 fastlane@lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: