



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1158S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FASCIA-FRT BPR (DISC 10%)	DEFORMED	721.66	649.49
1	GRILLE ASM-RAD (DISC 10%)	CRACKED	978.02	880.22
1	NUMBER PLATE (SN)	BENT	35.00	35.00
1	NUMBER PLATE FRAME (SN)	CUT	25.00	25.00
1	HOOD ASM	NOT NECESSARY	2,407.29	-
1	MODULE-FRT END	NOT NECESSARY	295.26	-
1	GRILLE-FRT BPR FASCIA LOWER	NOT NECESSARY	149.03	-
1	FINISHER-FRT BPR - LH	NOT NECESSARY	98.80	-
1	FINISHER-FRT BPR - RH	NOT NECESSARY	98.80	-
1	SUPPORT-FRT BPR FASCIA UPR	NOT NECESSARY	172.33	-
1	PANEL ASM-LEG CTHR	NOT NECESSARY	131.04	-
1	BAR ASM- FRT BPR IMP	NOT NECESSARY	624.00	-
1	COVER-F/CMPT ORNA	NOT NECESSARY	217.67	-
1	BRACKET-F/CMPT TR PLT	NOT NECESSARY	55.33	-
1	BRACKET-F/CMPT TR PLT	NOT NECESSARY	44.51	-
1	HEADLAMP ASM-LH	NOT NECESSARY	1,098.86	-
1	HEADLAMP ASM-RH	NOT NECESSARY	1,098.86	-
1	FINISHER-FRT BPR - RH (DISC 10%)	CRACKED	98.80	88.92
			8,350.26	1,678.63
<u>LABOUR</u>				
	PANEL BEATING & BODY WORK.		1,200.00	250.00
	SPRAY PAINT.		856.00	220.00
	TOWING CHARGE.		112.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
	ISOLATED OF (EV) (NET).		150.00	150.00

Report Ref No. NS/INC22008642/Rvce2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
			3,048.00	770.00
GRAND TOTAL			11,398.26	2,448.63
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,448.63

Report Ref No. NS/INC22008642/Rvce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.