

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

JM6KF2W7AM0674143

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place #03-03
Singapore Land Tower
Singapore 048623
Attn: motor claims Dept

TP Sompo
Veron.

6/9/2022

Estimate Cost of Repair Vehilce no: SNA7899G

Front bonnet <i>Repair</i>	1076.30	X.
Front top Panel <i>Rehanded</i>	299.30	✓
Front Headlamp <i>cracked</i>	2641.00	✓
Front fender L/h <i>Rehanded</i>	380.70	✓
Front fender Protector <i>Rehanded</i>	158.30	✓
Front fender inner shield <i>Rehanded</i>	98.20	✓
Front bumper <i>Distorted</i>	1023.10	✓
Front bumper side retainer <i>Damd.</i>	15.50	✓
Font bumper fog lamp Grille <i>cracked</i>	19.60	✓
Front Grille assy <i>Not new</i>	1071.00	+
Front Grille chrome L/h <i>cracked</i>	196.90	✓
Front Grille LOGO <i>Not new</i>	95.10	X.
Front bumper clip <i>new</i>	80.00	30.
Front fog lamp Base Bracket <i>cracked</i>	18.90	✓
Front fender stay bracket <i>Bent</i>	51.30	✓
Front bumper side bracket <i>Damd.</i>	28.00	✓
8pcs inner shield clip \$3.50x8 <i>new</i>	28.00	✓
6pcs Grille Rivet \$9.20x6 <i>new</i>	55.20	20.
8pcs Grille Clip \$5.00x8 <i>new</i>	40.00	20.
Front bumper lower cover <i>Not new</i>	155.50	X.
Front grille chrome center clip <i>new</i>	13.70	✓

5042.50

4034

1370

Labor for knocking, cutting, welding, replaced of Parts
To spray paint on the damage Portion
To checking wire

1000.00	500
1500.00	800
80.00	30
180.00	X
180.00	40

10,485.60

Total: 5404
(PIP)

Adrian Lj
7/9 08/05/22
05 Days.

To focus and align headlamp
Apply rust-proofing

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: